










Report No.: AAEMT/RF/230704-01-03





































































Report No.: AAEMT/RF/230704-01-03































Antenna 4:



Channel: 48




Report No.: AAEMT/RF/230704-01-03





Report No.: AAEMT/RF/230704-01-03


Channel: 48





Report No.: AAEMT/RF/230704-01-03





Channel: 48







Channel: 48






Channel: 165






Channel: 165






Report No.: AAEMT/RF/230704-01-03




Report No.: AAEMT/RF/230704-01-03


Channel: 165










Channel: 165

































Report No.: AAEMT/RF/230704-01-03


Channel: 48










Report No.: AAEMT/RF/230704-01-03

Channel: 165















Report No.: AAEMT/RF/230704-01-03


Channel: 165

























Report No.: AAEMT/RF/230704-01-03

Channel: 165




Report No.: AAEMT/RF/230704-01-03



Report No.: AAEMT/RF/230704-01-03

99% OBW 802.11n40

Channel: 151




Channel: 159




Report No.: AAEMT/RF/230704-01-03

99% OBW 802.11ac40

Channel: 38




Channel: 46




Report No.: AAEMT/RF/230704-01-03

99% OBW 802.11ac40



Channel: 151



Channel: 159




Report No.: AAEMT/RF/230704-01-03



Report No.: AAEMT/RF/230704-01-03

99%OBW 802.11ax40



Channel: 151





Channel: 159





Report No.: AAEMT/RF/230704-01-03










Antenna 5:






























Channel: 157



