




Test Report N° 210209-01.TR01



BE-NR-HIGH, SISO-B, 802.11ax80-HE0, Ch171




BE-NR-HIGH, SISO-B, 802.11ax160-HE0, Ch163




Date: 26.AUG.2022 12:56:07

BE-NR-HIGH, MIMO-A, 802.11n20-HT8, Ch177




Date: 26.AUG.2022 12:59:40

BE-NR-HIGH, MIMO-A, 802.11n40-HT8, Ch175




Date: 26.AUG.2022 13:00:12

BE-NR-HIGH, MIMO-A, 802.11ac80-VHT0, Ch171




Date: 26.AUG.2022 13:00:44

BE-NR-HIGH, MIMO-A, 802.11ac160-VHT0, Ch163




Date: 26.AUG.2022 13:01:15

BE-NR-HIGH, MIMO-A, 802.11ax20-HE0, Ch177




Date: 26.AUG.2022 13:01:47


BE-NR-HIGH, MIMO-A, 802.11ax40-HE0, Ch175



BE-NR-HIGH, MIMO-A, 802.11ax80-HE0, Ch171




BE-NR-HIGH, MIMO-A, 802.11ax160-HE0, Ch163




Date: 26.AUG.2022 17:06:27

BE-NR-HIGH, MIMO-B, 802.11n20-HT8, Ch177




Date: 26.AUG.2022 17:11:51

BE-NR-HIGH, MIMO-B, 802.11n40-HT8, Ch175




Date: 26.AUG.2022 17:12:23

BE-NR-HIGH, MIMO-B, 802.11ac80-VHT0, Ch171




Date: 26.AUG.2022 17:12:55

BE-NR-HIGH, MIMO-B, 802.11ac160-VHT0, Ch163




Date: 26.AUG.2022 17:13:27

BE-NR-HIGH, MIMO-B, 802.11ax20-HE0, Ch177




Date: 26.AUG.2022 17:13:59

BE-NR-HIGH, MIMO-B, 802.11ax40-HE0, Ch175



BE-NR-HIGH, MIMO-B, 802.11ax80-HE0, Ch171



BE-NR-HIGH, MIMO-B, 802.11ax160-HE0, Ch163