

KoreLock, Inc. 7100 E. Bellevue Ave. Suite 203 Greenwood Village, CO 80111 USA 303.681.5785

Date: Oct 17, 2024

## Justification for Re-use of Radio Test Results

We, KoreLock Inc, believe that the conducted signal test data on original reports provided by the Laird Technologies FCC ID: SQGBL654 Report# FR813002 on 29th Jun 2018 & ESPRESSIF SYSTEMS (SHANGHAI) CO., LTD FCC ID: 2AC7Z-ESPS2MINI1 Report# R2009A0623-R1 on 22 Nov 2020 can be re-used for the following reasons:

- 1. Applicant has built in the radio module according to the specific radio module integration guides.
- 2. No changes have been made on radio module.
- 3. Re-test the conducted power for spot check verification, the radiated spurious emission, and reevaluated the RF Exposure.

Also, we have disabled the 802.15.4 proprietary protocol in the BLE module.

By Robert Goff

Title: VP, Product