

MURPHY'S BOWL LLC
10400 NE 4th Street, Suite 3600
Bellevue, Washington 98004

March 20, 2024

Nemko North America, Inc.
303 River Road, Ottawa, ON K1V 1H2 Canada
Attn: Director of Certification

FCC ID: 2BE69-MBAP01
Models: IDAP v1.0, IDAP nUWB v1.0

Family Certification request letter

We hereby request Family Certification for the above mentioned HVINs/Models based on them being electrically, and physically identical apart from model 'IDAP nUWB 1.0'.

For model 'IDAP nUWB v1.0', the Ultra-Wide Band (UWB) radio (FCC ID VPYLB2BP) is not being populated on the PCBA - the models are electrically identical otherwise. With this exception, circuitry, components, layout, enclosure and assembly are otherwise identical between the models.

The included antennas and their gains in model 'IDAP nUWB v1.0' are identical as well, except for the UWB antenna not being actively driven due to the associated radio not being stuffed on the PCBA.

Sincerely,

Signed by:  _____
Signed: 3/22/2024
Signature

Brandt Vaughan _____
Print name

President - Corporate _____
Title

+1 (425) 242-6391 _____
Phone

Murphy's Bowl LLC _____
Company Name

Record of Signing

For
Name
Title



Signed on 2024-03-22 00:44:46 GMT

Secured by Concord™
DocumentID: 02w3zKMxLaCceKKiVgi1SG
SigningID: 02w3zKMxLaCKw1rdN7RxjU
Signing date: 3/22/2024
IP Address: 50.226.68.126
Email: brandt@ballmergroup.com



Signed with www.concordnow.com