



WiTricity Halo™ Receiver

Model Number: VWL1300

The WiTricity Halo™ PV Receiver shall be professionally installed in accordance with good engineering practices and WiTricity's engineering guidelines. Consult WiTricity's engineering support and integration guidelines to ensure that the integration meets Electromagnetic Compatibility and RF Exposure requirements when used with the WiTricity Halo™ PV Power Hub.

This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.



FCC Compliance Statement

This equipment generates, uses, and can radiate radio frequency energy and, if not installed and used in accordance with the provided instructions, may cause unintended harmful interference to radio communications. Due to a wide variety of installation scenarios, there is no guarantee that interference will not occur for a particular installation. It can be reasonably determined if this equipment causes interference by unplugging it and plugging it back in to see if interference continues for radio or television reception when plugged in. If this equipment does cause interference to radio or television reception, the user is encouraged to attempt to correct the interference using one or more of the following options:

- Increase the distance between the equipment and the receiving antenna on the radio and/or television.
- Relocate or change the orientation of the receiving antenna on the radio and/or television.
- Ensure that the equipment is attached to a different circuit than the one being used for the radio and/or television.
- Consult a radio expert, dealer, or technician for help resolving interference concerns.

Any changes made to this product not authorized by WiTricity might void the Electromagnetic Compatibility (EMC) or increase RF Exposure levels that have been validated. Unauthorized changes could negatively affect your authority to operate this product.