


Test Graphs



Band4_1.4MHz_QPSK_19957_1RB#0




Band4_1.4MHz_16QAM_19957_1RB#0



Band4_1.4MHz_QPSK_19957_1RB#5



Band4_1.4MHz_16QAM_19957_1RB#5



Band4_1.4MHz_QPSK_19957_6RB#0



Band4_1.4MHz_16QAM_19957_6RB#0





Band4_1.4MHz_QPSK_20393_1RB#0



Band4_1.4MHz_16QAM_20393_1RB#0



Band4_1.4MHz_QPSK_20393_1RB#5



Band4_1.4MHz_16QAM_20393_1RB#5



Band4_1.4MHz_QPSK_20393_6RB#0



Band4_1.4MHz_16QAM_20393_6RB#0

Shenzhen Anbotek Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.
 Tel: (86) 0755-26066440 Fax: (86) 0755-26014772 Email: service@anbotek.com

Hotline
 400-003-0500
 www.anbotek.com.cn





Band4_3MHz_QPSK_19965_1RB#0



Band4_3MHz_16QAM_19965_1RB#0



Band4_3MHz_QPSK_19965_1RB#14



Band4_3MHz_16QAM_19965_1RB#14



Band4_3MHz_QPSK_19965_15RB#0



Band4_3MHz_16QAM_19965_15RB#0

Shenzhen Anbotek Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.
 Tel: (86) 0755-26066440 Fax: (86) 0755-26014772 Email: service@anbotek.com

Hotline 400-003-0500
 www.anbotek.com.cn





Band4_3MHz_QPSK_20385_1RB#0



Band4_3MHz_16QAM_20385_1RB#0



Band4_3MHz_QPSK_20385_1RB#14



Band4_3MHz_16QAM_20385_1RB#14



Band4_3MHz_QPSK_20385_15RB#0



Band4_3MHz_16QAM_20385_15RB#0





Band4_5MHz_QPSK_19975_1RB#0



Band4_5MHz_16QAM_19975_1RB#0



Band4_5MHz_QPSK_19975_1RB#24



Band4_5MHz_16QAM_19975_1RB#24



Band4_5MHz_QPSK_19975_25RB#0



Band4_5MHz_16QAM_19975_25RB#0

Shenzhen Anbotek Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.
Tel: (86) 0755-26066440 Fax: (86) 0755-26014772 Email: service@anbotek.com




Hotline

400-003-0500

www.anbotek.com.cn





Shenzhen Anbotek Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.
Tel: (86) 0755-26066440 Fax: (86) 0755-26014772 Email: service@anbotek.com

Hotline 400-003-0500
www.anbotek.com.cn





Band4_10MHz_QPSK_2000_1RB#0



Band4_10MHz_16QAM_2000_1RB#0



Band4_10MHz_QPSK_2000_1RB#49



Band4_10MHz_16QAM_2000_1RB#49



Band4_10MHz_QPSK_20350_1RB#0



Band4_10MHz_16QAM_20350_1RB#0

Shenzhen Anbotek Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.
Tel: (86) 0755-26066440 Fax: (86) 0755-26014772 Email: service@anbotek.com



Hotline

400-003-0500

www.anbotek.com.cn






Band4_10MHz_QPSK_20350_1RB#49



Band4_10MHz_16QAM_20350_1RB#49



Band4_10MHz_QPSK_20000_50RB#0



Band4_10MHz_QPSK_20350_50RB#0




Band4_15MHz_QPSK_20025_1RB#0




Band4_15MHz_16QAM_20025_1RB#0






Band4_15MHz_QPSK_2025_1RB#74



Band4_15MHz_16QAM_2025_1RB#74




Band4_15MHz_QPSK_20325_1RB#0



Band4_15MHz_16QAM_20325_1RB#0



Band4_15MHz_QPSK_20325_1RB#74



Band4_15MHz_16QAM_20325_1RB#74

Shenzhen Anbotek Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.
 Tel: (86) 0755-26066440 Fax: (86) 0755-26014772 Email: service@anbotek.com

Hotline 400-003-0500
 www.anbotek.com.cn






Band4_15MHz_QPSK_2025_75RB#0



Band4_15MHz_QPSK_20325_75RB#0




Band4_20MHz_QPSK_20050_1RB#0



Band4_20MHz_16QAM_20050_1RB#0



Band4_20MHz_QPSK_20050_1RB#99



Band4_20MHz_16QAM_20050_1RB#99

Shenzhen Anbotek Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.
 Tel: (86) 0755-26066440 Fax: (86) 0755-26014772 Email: service@anbotek.com

Hotline 400-003-0500
 www.anbotek.com.cn






Band4_20MHz_QPSK_20300_1RB#0



Band4_20MHz_16QAM_20300_1RB#0




Band4_20MHz_QPSK_20300_1RB#99



Band4_20MHz_16QAM_20300_1RB#99



Band4_20MHz_QPSK_20050_100RB#0



Band4_20MHz_QPSK_20300_100RB#0

Shenzhen Anbotek Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.
 Tel: (86) 0755-26066440 Fax: (86) 0755-26014772 Email: service@anbotek.com

Hotline 400-003-0500
 www.anbotek.com.cn



Appendix E: Conducted Spurious Emission

Test Result

Band	Bandwidth	Modulation	Channel	RB Configuration	Frequency Range	Result (dBm)	Verdict
Band4	1.4MHz	QPSK	19957	1RB#0	0.009~0.15	-61.14	PASS
Band4	1.4MHz	QPSK	19957	1RB#0	0.15~30	-61.96	PASS
Band4	1.4MHz	QPSK	19957	1RB#0	30~1000	-66.76	PASS
Band4	1.4MHz	QPSK	19957	1RB#0	1000~3000	-43.67	PASS
Band4	1.4MHz	QPSK	19957	1RB#0	3000~20000	-47.14	PASS
Band4	1.4MHz	16QAM	19957	1RB#0	0.009~0.15	-62.85	PASS
Band4	1.4MHz	16QAM	19957	1RB#0	0.15~30	-62.69	PASS
Band4	1.4MHz	16QAM	19957	1RB#0	30~1000	-67.22	PASS
Band4	1.4MHz	16QAM	19957	1RB#0	1000~3000	-44.41	PASS
Band4	1.4MHz	16QAM	19957	1RB#0	3000~20000	-48.62	PASS
Band4	1.4MHz	QPSK	20175	1RB#0	0.009~0.15	-62.76	PASS
Band4	1.4MHz	QPSK	20175	1RB#0	0.15~30	-61.38	PASS
Band4	1.4MHz	QPSK	20175	1RB#0	30~1000	-67.27	PASS
Band4	1.4MHz	QPSK	20175	1RB#0	1000~3000	-42.96	PASS
Band4	1.4MHz	QPSK	20175	1RB#0	3000~20000	-45.44	PASS
Band4	1.4MHz	16QAM	20175	1RB#0	0.009~0.15	-60.16	PASS
Band4	1.4MHz	16QAM	20175	1RB#0	0.15~30	-59.38	PASS
Band4	1.4MHz	16QAM	20175	1RB#0	30~1000	-67.19	PASS
Band4	1.4MHz	16QAM	20175	1RB#0	1000~3000	-43.31	PASS
Band4	1.4MHz	16QAM	20175	1RB#0	3000~20000	-46.47	PASS
Band4	1.4MHz	QPSK	20393	1RB#0	0.009~0.15	-62.32	PASS
Band4	1.4MHz	QPSK	20393	1RB#0	0.15~30	-61.43	PASS
Band4	1.4MHz	QPSK	20393	1RB#0	30~1000	-67.17	PASS
Band4	1.4MHz	QPSK	20393	1RB#0	1000~3000	-43.04	PASS
Band4	1.4MHz	QPSK	20393	1RB#0	3000~20000	-48.90	PASS
Band4	1.4MHz	16QAM	20393	1RB#0	0.009~0.15	-61.99	PASS
Band4	1.4MHz	16QAM	20393	1RB#0	0.15~30	-62.52	PASS
Band4	1.4MHz	16QAM	20393	1RB#0	30~1000	-66.83	PASS
Band4	1.4MHz	16QAM	20393	1RB#0	1000~3000	-43.69	PASS
Band4	1.4MHz	16QAM	20393	1RB#0	3000~20000	-48.79	PASS
Band4	3MHz	QPSK	19965	1RB#0	0.009~0.15	-64.84	PASS
Band4	3MHz	QPSK	19965	1RB#0	0.15~30	-61.99	PASS
Band4	3MHz	QPSK	19965	1RB#0	30~1000	-66.57	PASS
Band4	3MHz	QPSK	19965	1RB#0	1000~3000	-50.60	PASS
Band4	3MHz	QPSK	19965	1RB#0	3000~20000	-47.81	PASS
Band4	3MHz	16QAM	19965	1RB#0	0.009~0.15	-63.55	PASS
Band4	3MHz	16QAM	19965	1RB#0	0.15~30	-60.34	PASS

Shenzhen Anbotek Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.
Tel: (86) 0755-26066440 Fax: (86) 0755-26014772 Email: service@anbotek.com



Hotline
400-003-0500
www.anbotek.com.cn



Band4	3MHz	16QAM	19965	1RB#0	30~1000	-66.95	PASS
Band4	3MHz	16QAM	19965	1RB#0	1000~3000	-48.34	PASS
Band4	3MHz	16QAM	19965	1RB#0	3000~20000	-48.16	PASS
Band4	3MHz	QPSK	20175	1RB#0	0.009~0.15	-65.68	PASS
Band4	3MHz	QPSK	20175	1RB#0	0.15~30	-63.52	PASS
Band4	3MHz	QPSK	20175	1RB#0	30~1000	-67.21	PASS
Band4	3MHz	QPSK	20175	1RB#0	1000~3000	-48.16	PASS
Band4	3MHz	QPSK	20175	1RB#0	3000~20000	-46.25	PASS
Band4	3MHz	16QAM	20175	1RB#0	0.009~0.15	-60.67	PASS
Band4	3MHz	16QAM	20175	1RB#0	0.15~30	-60.38	PASS
Band4	3MHz	16QAM	20175	1RB#0	30~1000	-67.32	PASS
Band4	3MHz	16QAM	20175	1RB#0	1000~3000	-47.32	PASS
Band4	3MHz	16QAM	20175	1RB#0	3000~20000	-48.77	PASS
Band4	3MHz	QPSK	20385	1RB#0	0.009~0.15	-65.04	PASS
Band4	3MHz	QPSK	20385	1RB#0	0.15~30	-63.15	PASS
Band4	3MHz	QPSK	20385	1RB#0	30~1000	-67.33	PASS
Band4	3MHz	QPSK	20385	1RB#0	1000~3000	-47.91	PASS
Band4	3MHz	QPSK	20385	1RB#0	3000~20000	-48.77	PASS
Band4	3MHz	16QAM	20385	1RB#0	0.009~0.15	-65.44	PASS
Band4	3MHz	16QAM	20385	1RB#0	0.15~30	-63.09	PASS
Band4	3MHz	16QAM	20385	1RB#0	30~1000	-67.22	PASS
Band4	3MHz	16QAM	20385	1RB#0	1000~3000	-47.89	PASS
Band4	3MHz	16QAM	20385	1RB#0	3000~20000	-49.10	PASS
Band4	5MHz	QPSK	19975	1RB#0	0.009~0.15	-61.79	PASS
Band4	5MHz	QPSK	19975	1RB#0	0.15~30	-62.55	PASS
Band4	5MHz	QPSK	19975	1RB#0	30~1000	-67.13	PASS
Band4	5MHz	QPSK	19975	1RB#0	1000~3000	-53.22	PASS
Band4	5MHz	QPSK	19975	1RB#0	3000~20000	-47.58	PASS
Band4	5MHz	16QAM	19975	1RB#0	0.009~0.15	-64.25	PASS
Band4	5MHz	16QAM	19975	1RB#0	0.15~30	-59.95	PASS
Band4	5MHz	16QAM	19975	1RB#0	30~1000	-67.29	PASS
Band4	5MHz	16QAM	19975	1RB#0	1000~3000	-53.25	PASS
Band4	5MHz	16QAM	19975	1RB#0	3000~20000	-48.58	PASS
Band4	5MHz	QPSK	20175	1RB#0	0.009~0.15	-62.82	PASS
Band4	5MHz	QPSK	20175	1RB#0	0.15~30	-61.77	PASS
Band4	5MHz	QPSK	20175	1RB#0	30~1000	-67.07	PASS
Band4	5MHz	QPSK	20175	1RB#0	1000~3000	-53.41	PASS
Band4	5MHz	QPSK	20175	1RB#0	3000~20000	-47.28	PASS
Band4	5MHz	16QAM	20175	1RB#0	0.009~0.15	-64.68	PASS
Band4	5MHz	16QAM	20175	1RB#0	0.15~30	-60.62	PASS
Band4	5MHz	16QAM	20175	1RB#0	30~1000	-67.05	PASS
Band4	5MHz	16QAM	20175	1RB#0	1000~3000	-53.14	PASS

Shenzhen Anbotek Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.
Tel: (86) 0755-26066440 Fax: (86) 0755-26014772 Email: service@anbotek.com



Hotline
400-003-0500
www.anbotek.com.cn



Band4	5MHz	16QAM	20175	1RB#0	3000~20000	-47.53	PASS
Band4	5MHz	QPSK	20375	1RB#0	0.009~0.15	-59.88	PASS
Band4	5MHz	QPSK	20375	1RB#0	0.15~30	-61.06	PASS
Band4	5MHz	QPSK	20375	1RB#0	30~1000	-67.01	PASS
Band4	5MHz	QPSK	20375	1RB#0	1000~3000	-53.17	PASS
Band4	5MHz	QPSK	20375	1RB#0	3000~20000	-49.04	PASS
Band4	5MHz	16QAM	20375	1RB#0	0.009~0.15	-61.97	PASS
Band4	5MHz	16QAM	20375	1RB#0	0.15~30	-61.62	PASS
Band4	5MHz	16QAM	20375	1RB#0	30~1000	-66.89	PASS
Band4	5MHz	16QAM	20375	1RB#0	1000~3000	-52.84	PASS
Band4	5MHz	16QAM	20375	1RB#0	3000~20000	-48.79	PASS
Band4	10MHz	QPSK	20000	1RB#0	0.009~0.15	-66.65	PASS
Band4	10MHz	QPSK	20000	1RB#0	0.15~30	-63.33	PASS
Band4	10MHz	QPSK	20000	1RB#0	30~1000	-70.05	PASS
Band4	10MHz	QPSK	20000	1RB#0	1000~3000	-56.47	PASS
Band4	10MHz	QPSK	20000	1RB#0	3000~20000	-51.43	PASS
Band4	10MHz	16QAM	20000	1RB#0	0.009~0.15	-66.16	PASS
Band4	10MHz	16QAM	20000	1RB#0	0.15~30	-67.48	PASS
Band4	10MHz	16QAM	20000	1RB#0	30~1000	-70.10	PASS
Band4	10MHz	16QAM	20000	1RB#0	1000~3000	-56.35	PASS
Band4	10MHz	16QAM	20000	1RB#0	3000~20000	-51.99	PASS
Band4	10MHz	QPSK	20175	1RB#0	0.009~0.15	-63.25	PASS
Band4	10MHz	QPSK	20175	1RB#0	0.15~30	-66.43	PASS
Band4	10MHz	QPSK	20175	1RB#0	30~1000	-70.12	PASS
Band4	10MHz	QPSK	20175	1RB#0	1000~3000	-56.55	PASS
Band4	10MHz	QPSK	20175	1RB#0	3000~20000	-48.33	PASS
Band4	10MHz	16QAM	20175	1RB#0	0.009~0.15	-67.10	PASS
Band4	10MHz	16QAM	20175	1RB#0	0.15~30	-64.11	PASS
Band4	10MHz	16QAM	20175	1RB#0	30~1000	-70.16	PASS
Band4	10MHz	16QAM	20175	1RB#0	1000~3000	-56.33	PASS
Band4	10MHz	16QAM	20175	1RB#0	3000~20000	-48.48	PASS
Band4	10MHz	QPSK	20350	1RB#0	0.009~0.15	-64.93	PASS
Band4	10MHz	QPSK	20350	1RB#0	0.15~30	-64.21	PASS
Band4	10MHz	QPSK	20350	1RB#0	30~1000	-70.23	PASS
Band4	10MHz	QPSK	20350	1RB#0	1000~3000	-56.63	PASS
Band4	10MHz	QPSK	20350	1RB#0	3000~20000	-51.44	PASS
Band4	10MHz	16QAM	20350	1RB#0	0.009~0.15	-64.49	PASS
Band4	10MHz	16QAM	20350	1RB#0	0.15~30	-63.28	PASS
Band4	10MHz	16QAM	20350	1RB#0	30~1000	-70.52	PASS
Band4	10MHz	16QAM	20350	1RB#0	1000~3000	-56.27	PASS
Band4	10MHz	16QAM	20350	1RB#0	3000~20000	-51.87	PASS
Band4	15MHz	QPSK	20025	1RB#0	0.009~0.15	-66.17	PASS

Shenzhen Anbotek Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.
Tel: (86) 0755-26066440 Fax: (86) 0755-26014772 Email: service@anbotek.com

Hotline
400-003-0500
www.anbotek.com.cn



Band4	15MHz	QPSK	20025	1RB#0	0.15~30	-65.67	PASS
Band4	15MHz	QPSK	20025	1RB#0	30~1000	-70.32	PASS
Band4	15MHz	QPSK	20025	1RB#0	1000~3000	-56.82	PASS
Band4	15MHz	QPSK	20025	1RB#0	3000~20000	-51.96	PASS
Band4	15MHz	16QAM	20025	1RB#0	0.009~0.15	-66.02	PASS
Band4	15MHz	16QAM	20025	1RB#0	0.15~30	-65.52	PASS
Band4	15MHz	16QAM	20025	1RB#0	30~1000	-69.50	PASS
Band4	15MHz	16QAM	20025	1RB#0	1000~3000	-56.68	PASS
Band4	15MHz	16QAM	20025	1RB#0	3000~20000	-51.89	PASS
Band4	15MHz	QPSK	20175	1RB#0	0.009~0.15	-67.22	PASS
Band4	15MHz	QPSK	20175	1RB#0	0.15~30	-64.09	PASS
Band4	15MHz	QPSK	20175	1RB#0	30~1000	-70.05	PASS
Band4	15MHz	QPSK	20175	1RB#0	1000~3000	-56.32	PASS
Band4	15MHz	QPSK	20175	1RB#0	3000~20000	-48.13	PASS
Band4	15MHz	16QAM	20175	1RB#0	0.009~0.15	-64.83	PASS
Band4	15MHz	16QAM	20175	1RB#0	0.15~30	-63.99	PASS
Band4	15MHz	16QAM	20175	1RB#0	30~1000	-70.06	PASS
Band4	15MHz	16QAM	20175	1RB#0	1000~3000	-56.38	PASS
Band4	15MHz	16QAM	20175	1RB#0	3000~20000	-50.64	PASS
Band4	15MHz	QPSK	20325	1RB#0	0.009~0.15	-64.84	PASS
Band4	15MHz	QPSK	20325	1RB#0	0.15~30	-64.35	PASS
Band4	15MHz	QPSK	20325	1RB#0	30~1000	-70.04	PASS
Band4	15MHz	QPSK	20325	1RB#0	1000~3000	-56.51	PASS
Band4	15MHz	QPSK	20325	1RB#0	3000~20000	-51.56	PASS
Band4	15MHz	16QAM	20325	1RB#0	0.009~0.15	-68.80	PASS
Band4	15MHz	16QAM	20325	1RB#0	0.15~30	-65.70	PASS
Band4	15MHz	16QAM	20325	1RB#0	30~1000	-70.45	PASS
Band4	15MHz	16QAM	20325	1RB#0	1000~3000	-56.11	PASS
Band4	15MHz	16QAM	20325	1RB#0	3000~20000	-51.97	PASS
Band4	20MHz	QPSK	20050	1RB#0	0.009~0.15	-68.54	PASS
Band4	20MHz	QPSK	20050	1RB#0	0.15~30	-65.92	PASS
Band4	20MHz	QPSK	20050	1RB#0	30~1000	-70.45	PASS
Band4	20MHz	QPSK	20050	1RB#0	1000~3000	-56.39	PASS
Band4	20MHz	QPSK	20050	1RB#0	3000~20000	-51.74	PASS
Band4	20MHz	16QAM	20050	1RB#0	0.009~0.15	-68.26	PASS
Band4	20MHz	16QAM	20050	1RB#0	0.15~30	-61.51	PASS
Band4	20MHz	16QAM	20050	1RB#0	30~1000	-70.28	PASS
Band4	20MHz	16QAM	20050	1RB#0	1000~3000	-56.33	PASS
Band4	20MHz	16QAM	20050	1RB#0	3000~20000	-51.84	PASS
Band4	20MHz	QPSK	20175	1RB#0	0.009~0.15	-66.09	PASS
Band4	20MHz	QPSK	20175	1RB#0	0.15~30	-62.95	PASS
Band4	20MHz	QPSK	20175	1RB#0	30~1000	-69.98	PASS

Shenzhen Anbotek Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.
 Tel: (86) 0755-26066440 Fax: (86) 0755-26014772 Email: service@anbotek.com



Hotline
400-003-0500
www.anbotek.com.cn



Band4	20MHz	QPSK	20175	1RB#0	1000~3000	-56.25	PASS
Band4	20MHz	QPSK	20175	1RB#0	3000~20000	-49.02	PASS
Band4	20MHz	16QAM	20175	1RB#0	0.009~0.15	-64.05	PASS
Band4	20MHz	16QAM	20175	1RB#0	0.15~30	-66.50	PASS
Band4	20MHz	16QAM	20175	1RB#0	30~1000	-70.09	PASS
Band4	20MHz	16QAM	20175	1RB#0	1000~3000	-56.24	PASS
Band4	20MHz	16QAM	20175	1RB#0	3000~20000	-51.18	PASS
Band4	20MHz	QPSK	20300	1RB#0	0.009~0.15	-69.25	PASS
Band4	20MHz	QPSK	20300	1RB#0	0.15~30	-63.35	PASS
Band4	20MHz	QPSK	20300	1RB#0	30~1000	-70.14	PASS
Band4	20MHz	QPSK	20300	1RB#0	1000~3000	-56.42	PASS
Band4	20MHz	QPSK	20300	1RB#0	3000~20000	-51.42	PASS
Band4	20MHz	16QAM	20300	1RB#0	0.009~0.15	-66.94	PASS
Band4	20MHz	16QAM	20300	1RB#0	0.15~30	-65.44	PASS
Band4	20MHz	16QAM	20300	1RB#0	30~1000	-70.31	PASS
Band4	20MHz	16QAM	20300	1RB#0	1000~3000	-56.42	PASS
Band4	20MHz	16QAM	20300	1RB#0	3000~20000	-51.78	PASS

Shenzhen Anbotek Compliance Laboratory Limited


Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.
 Tel: (86) 0755-26066440 Fax: (86) 0755-26014772 Email: service@anbotek.com




Hotline
 400-003-0500
www.anbotek.com.cn



Test Graphs




Band4_1.4MHz_QPSK_19957_1RB#0_0.009~0.15_0.09~0.15



Band4_1.4MHz_QPSK_19957_1RB#0_0.15~30_0.15~30




Band4_1.4MHz_QPSK_19957_1RB#0_30~1000_30~1000



Band4_1.4MHz_QPSK_19957_1RB#0_1000~3000_1000~3000



Band4_1.4MHz_QPSK_19957_1RB#0_3000~20000_3000~20000




Band4_1.4MHz_16QAM_19957_1RB#0_0.009~0.15_0.09~0.15

Shenzhen Anbotek Compliance Laboratory Limited


Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.
 Tel: (86) 0755-26066440 Fax: (86) 0755-26014772 Email: service@anbotek.com

Hotline 400-003-0500
 www.anbotek.com.cn






Band4_1.4MHz_16QAM_19957_1RB#0_0.15~30_0.15
~30




Band4_1.4MHz_16QAM_19957_1RB#0_30~1000_30~1000




Band4_1.4MHz_16QAM_19957_1RB#0_1000~3000_1000~3000



Band4_1.4MHz_16QAM_19957_1RB#0_3000~20000_3000~20000




Band4_1.4MHz_QPSK_20175_1RB#0_0.009~0.15_0.009~0.15




Band4_1.4MHz_QPSK_20175_1RB#0_0.15~30_0.15~30





Band4_1.4MHz_QPSK_20175_1RB#0_30~1000_30~1000




Band4_1.4MHz_QPSK_20175_1RB#0_1000~3000_1000~3000



Band4_1.4MHz_QPSK_20175_1RB#0_3000~20000_3000~20000



Band4_1.4MHz_16QAM_20175_1RB#0_0.009~0.15_0.009~0.15



Band4_1.4MHz_16QAM_20175_1RB#0_0.15~30_0.15~30



Band4_1.4MHz_16QAM_20175_1RB#0_30~1000_30~1000






Band4_1.4MHz_16QAM_20175_1RB#0_1000~3000_1
000~3000




Band4_1.4MHz_16QAM_20175_1RB#0_3000~20000_3
000~20000




Band4_1.4MHz_QPSK_20393_1RB#0_0.009~0.15_0.0
09~0.15



Band4_1.4MHz_QPSK_20393_1RB#0_0.15~30_0.15~3
0



Band4_1.4MHz_QPSK_20393_1RB#0_30~1000_30~1
000



Band4_1.4MHz_QPSK_20393_1RB#0_1000~3000_100
0~3000

Shenzhen Anbotek Compliance Laboratory Limited


Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.
Tel: (86) 0755-26066440 Fax: (86) 0755-26014772 Email: service@anbotek.com

Hotline 400-003-0500
www.anbotek.com.cn







Band4_1.4MHz_QPSK_20393_1RB#0_3000~20000_3000~20000




Band4_1.4MHz_16QAM_20393_1RB#0_0.009~0.15_0.009~0.15



Band4_1.4MHz_16QAM_20393_1RB#0_0.15~30_0.15~30



Band4_1.4MHz_16QAM_20393_1RB#0_30~1000_30~1000



Band4_1.4MHz_16QAM_20393_1RB#0_1000~3000_1000~3000




Band4_1.4MHz_16QAM_20393_1RB#0_3000~20000_3000~20000







Band4_3MHz_QPSK_19965_1RB#0_0.009~0.15_0.00
9~0.15



Band4_3MHz_QPSK_19965_1RB#0_0.15~30_0.15~30




Band4_3MHz_QPSK_19965_1RB#0_30~1000_30~100
0



Band4_3MHz_QPSK_19965_1RB#0_1000~3000_1000~3000




Band4_3MHz_QPSK_19965_1RB#0_3000~20000_3000~20000




Band4_3MHz_16QAM_19965_1RB#0_0.009~0.15_0.00
9~0.15






Band4_3MHz_16QAM_19965_1RB#0_0.15~30_0.15~3

0




Band4_3MHz_16QAM_19965_1RB#0_30~1000_30~10

00




Band4_3MHz_16QAM_19965_1RB#0_1000~3000_100

0~3000




Band4_3MHz_16QAM_19965_1RB#0_3000~20000_30

00~20000




Band4_3MHz_QPSK_20175_1RB#0_0.009~0.15_0.00

9~0.15




Band4_3MHz_QPSK_20175_1RB#0_0.15~30_0.15~30






Band4_3MHz_QPSK_20175_1RB#0_30~1000_30~100
0




Band4_3MHz_QPSK_20175_1RB#0_1000~3000_1000~3000
3000




Band4_3MHz_QPSK_20175_1RB#0_3000~20000_3000~20000
0~20000



Band4_3MHz_16QAM_20175_1RB#0_0.009~0.15_0.009~0.15
9~0.15



Band4_3MHz_16QAM_20175_1RB#0_0.15~30_0.15~30
0



Band4_3MHz_16QAM_20175_1RB#0_30~1000_30~1000
00







Band4_3MHz_16QAM_20175_1RB#0_1000~3000_100
0~3000




Band4_3MHz_16QAM_20175_1RB#0_3000~20000_30
00~20000




Band4_3MHz_QPSK_20385_1RB#0_0.009~0.15_0.00
9~0.15



Band4_3MHz_QPSK_20385_1RB#0_0.15~30_0.15~30



Band4_3MHz_QPSK_20385_1RB#0_30~1000_30~100
0



Band4_3MHz_QPSK_20385_1RB#0_1000~3000_1000~3000







Band4_3MHz_QPSK_20385_1RB#0_3000~20000_300
0~20000




Band4_3MHz_16QAM_20385_1RB#0_0.009~0.15_0.00
9~0.15



Band4_3MHz_16QAM_20385_1RB#0_0.15~30_0.15~3
0



Band4_3MHz_16QAM_20385_1RB#0_30~1000_30~10
00



Band4_3MHz_16QAM_20385_1RB#0_1000~3000_100
0~3000




Band4_3MHz_16QAM_20385_1RB#0_3000~20000_30
00~20000

Shenzhen Anbotek Compliance Laboratory Limited


Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.
Tel: (86) 0755-26066440 Fax: (86) 0755-26014772 Email: service@anbotek.com

Hotline 400-003-0500
www.anbotek.com.cn







Band4_5MHz_QPSK_19975_1RB#0_0.009~0.15_0.00
 9~0.15



Band4_5MHz_QPSK_19975_1RB#0_0.15~30_0.15~30



Band4_5MHz_QPSK_19975_1RB#0_30~1000_30~100
 0



Band4_5MHz_QPSK_19975_1RB#0_1000~3000_1000~3000




Band4_5MHz_QPSK_19975_1RB#0_3000~20000_3000~20000
 0~20000



Band4_5MHz_16QAM_19975_1RB#0_0.009~0.15_0.00
 9~0.15






Band4_5MHz_16QAM_19975_1RB#0_0.15~30_0.15~3

0



Band4_5MHz_16QAM_19975_1RB#0_30~1000_30~10

00




Band4_5MHz_16QAM_19975_1RB#0_1000~3000_100

0~3000




Band4_5MHz_16QAM_19975_1RB#0_3000~20000_30

00~20000



Band4_5MHz_QPSK_20175_1RB#0_0.009~0.15_0.00

9~0.15



Band4_5MHz_QPSK_20175_1RB#0_0.15~30_0.15~30

