



20MHz_Low_16QAM_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
 Date: 27.JUL.2024 13:15:53

20MHz_Low_16QAM_100@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
 Date: 27.JUL.2024 13:14:50

20MHz_High_QPSK_1@99




ProjectNo.:2402V58055E-RF Tester:Karl Liang
 Date: 27.JUL.2024 13:19:56

20MHz_High_QPSK_100@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
 Date: 27.JUL.2024 13:17:43

20MHz_High_16QAM_1@99



ProjectNo.:2402V58055E-RF Tester:Karl Liang
 Date: 27.JUL.2024 13:58:41


20MHz_High_16QAM_100@0



ProjectNo.:2402V58055E-RF Tester:Karl Liang
 Date: 27.JUL.2024 13:43:29


B41 , Normal

5MHz_Low_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
 Date: 27.JUL.2024 14:03:39

5MHz_Low_QPSK_25@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
 Date: 27.JUL.2024 14:02:08

5MHz_Low_16QAM_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
 Date: 27.JUL.2024 14:06:42

5MHz_Low_16QAM_25@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
 Date: 27.JUL.2024 14:05:10

5MHz_High_QPSK_1@24




ProjectNo.:2402V58055E-RF Tester:Karl Liang
 Date: 27.JUL.2024 14:17:11

5MHz_High_QPSK_25@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
 Date: 27.JUL.2024 14:12:45

5MHz_High_16QAM_1@24




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 27.JUL.2024 14:25:59

5MHz_High_16QAM_25@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 27.JUL.2024 14:21:35

10MHz_Low_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 27.JUL.2024 14:30:06

10MHz_Low_QPSK_50@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 27.JUL.2024 14:28:35

10MHz_Low_16QAM_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 27.JUL.2024 14:33:09

10MHz_Low_16QAM_50@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 27.JUL.2024 14:31:38

10MHz_High_QPSK_1@49




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 27.JUL.2024 14:35:44

10MHz_High_QPSK_50@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 27.JUL.2024 14:34:40

10MHz_High_16QAM_1@49




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 27.JUL.2024 14:37:52

10MHz_High_16QAM_50@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 27.JUL.2024 14:36:48

15MHz_Low_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 27.JUL.2024 14:41:16

15MHz_Low_QPSK_75@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 27.JUL.2024 14:40:11

15MHz_Low_16QAM_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
 Date: 27.JUL.2024 14:43:26

15MHz_Low_16QAM_75@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
 Date: 27.JUL.2024 14:42:22

15MHz_High_QPSK_1@74




ProjectNo.:2402V58055E-RF Tester:Karl Liang
 Date: 27.JUL.2024 15:09:43

15MHz_High_QPSK_75@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
 Date: 27.JUL.2024 15:51:18

15MHz_High_16QAM_1@74




ProjectNo.:2402V58055E-RF Tester:Karl Liang
 Date: 27.JUL.2024 15:32:22

15MHz_High_16QAM_75@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
 Date: 27.JUL.2024 15:21:03

20MHz_Low_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
 Date: 27.JUL.2024 15:38:29

20MHz_Low_QPSK_100@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
 Date: 27.JUL.2024 15:37:25

20MHz_Low_16QAM_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
 Date: 27.JUL.2024 15:40:35

20MHz_Low_16QAM_100@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
 Date: 27.JUL.2024 15:39:32

20MHz_High_QPSK_1@99




ProjectNo.:2402V58055E-RF Tester:Karl Liang
 Date: 27.JUL.2024 15:46:34

20MHz_High_QPSK_100@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
 Date: 27.JUL.2024 15:45:26

20MHz_High_16QAM_1@99



ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 27.JUL.2024 15:48:50

20MHz_High_16QAM_100@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 27.JUL.2024 15:47:41

Spurious Emissions at Antenna Terminal


FCC For 90S

B26_1 , Normal


1_1.4MHz_Low_QPSK_1@0




1_1.4MHz_High_QPSK_1@0




1_3MHz_Low_QPSK_1@0




1_3MHz_High_QPSK_1@0




1_5MHz_Low_QPSK_1@0




1_5MHz_High_QPSK_1@0



1_10MHz_Low_QPSK_1@0




1_15MHz_Low_QPSK_1@0




B26_3 , Normal


3_1.4MHz_Middle_QPSK_1@0




3_3MHz_Middle_QPSK_1@0




3_5MHz_Middle_QPSK_1@0



3_10MHz_Middle_QPSK_1@0



3_15MHz_Middle_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 26.JUL.2024 09:45:01

FCC Part 22H


B5 , Normal

1.4MHz_Low_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 23.JUL.2024 09:42:30

1.4MHz_Middle_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 30.JUL.2024 19:37:16

1.4MHz_High_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 30.JUL.2024 19:37:30

3MHz_Low_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 23.JUL.2024 09:47:44

3MHz_Middle_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 23.JUL.2024 09:48:16

3MHz_High_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 23.JUL.2024 09:48:49

5MHz_Low_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 26.JUL.2024 08:18:46

5MHz_Middle_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 23.JUL.2024 09:04:08

5MHz_High_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 23.JUL.2024 09:04:38

10MHz_Low_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 26.JUL.2024 08:27:40

10MHz_Middle_QPSK_1@0



ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 26.JUL.2024 08:28:10


10MHz_High_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 26.JUL.2024 08:28:40

B26_2 , Normal


2_1.4MHz_Low_QPSK_1@0




2_1.4MHz_Middle_QPSK_1@0




2_1.4MHz_High_QPSK_1@0




2_3MHz_Low_QPSK_1@0




2_3MHz_Middle_QPSK_1@0



2_3MHz_High_QPSK_1@0




2_5MHz_Low_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 26.JUL.2024 09:24:26

2_5MHz_Middle_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 26.JUL.2024 09:24:57

2_5MHz_High_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 26.JUL.2024 09:25:28

2_10MHz_Low_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 26.JUL.2024 09:28:32

2_10MHz_Middle_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 26.JUL.2024 09:29:08

2_10MHz_High_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 26.JUL.2024 09:29:43

2_15MHz_Low_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 26.JUL.2024 09:31:39

2_15MHz_Middle_QPSK_1@0



ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 26.JUL.2024 09:41:29

2_15MHz_High_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 26.JUL.2024 09:42:03

FCC Part 24E


B2 , Normal

1.4MHz_Low_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 22.JUL.2024 22:30:44

1.4MHz_Middle_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 22.JUL.2024 22:31:28

1.4MHz_High_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 22.JUL.2024 22:32:20

3MHz_Low_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 22.JUL.2024 22:34:13

3MHz_Middle_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 22.JUL.2024 22:34:53

3MHz_High_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 22.JUL.2024 22:35:11

5MHz_Low_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 22,JUL,2024 22:37:22

5MHz_Middle_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 22,JUL,2024 22:37:58

5MHz_High_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 22,JUL,2024 22:38:33

10MHz_Low_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 22,JUL,2024 22:41:02

10MHz_Middle_QPSK_1@0



ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 22,JUL,2024 22:41:41

10MHz_High_QPSK_1@0



ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 22,JUL,2024 22:42:19