



Band 5\_3 MHz\_Middle\_QPSK\_RB15#0




ProjectNo.:2401Y68085E-RF Tester:Usain Ou  
Date: 11.DEC.2024 18:56:38

Band 5\_3 MHz\_Middle\_16QAM\_RB15#0




ProjectNo.:2401Y68085E-RF Tester:Usain Ou  
Date: 11.DEC.2024 18:56:52

Band 5\_5 MHz\_Middle\_QPSK\_RB25#0




ProjectNo.:2401Y68085E-RF Tester:Usain Ou  
Date: 11.DEC.2024 19:02:06

Band 5\_5 MHz\_Middle\_16QAM\_RB25#0




ProjectNo.:2401Y68085E-RF Tester:Usain Ou  
Date: 11.DEC.2024 19:02:24

Band 5\_10 MHz\_Middle\_QPSK\_RB50#0




ProjectNo.:2401Y68085E-RF Tester:Usain Ou  
Date: 11.DEC.2024 19:04:46

Band 5\_10 MHz\_Middle\_16QAM\_RB50#0




ProjectNo.:2401Y68085E-RF Tester:Usain Ou  
Date: 11.DEC.2024 19:05:06

Band 7\_5 MHz\_Middle\_QPSK\_RB25#0




ProjectNo.:2401Y68085E-RF Tester:Usain Ou  
Date: 11.DEC.2024 19:07:39

Band 7\_5 MHz\_Middle\_16QAM\_RB25#0




ProjectNo.:2401Y68085E-RF Tester:Usain Ou  
Date: 11.DEC.2024 19:07:57

Band 7\_10 MHz\_Middle\_QPSK\_RB50#0




ProjectNo.:2401Y68085E-RF Tester:Usain Ou  
Date: 11.DEC.2024 19:15:24

Band 7\_10 MHz\_Middle\_16QAM\_RB50#0




ProjectNo.:2401Y68085E-RF Tester:Usain Ou  
Date: 11.DEC.2024 19:15:54

Band 7\_15 MHz\_Middle\_QPSK\_RB75#0




ProjectNo.:2401Y68085E-RF Tester:Usain Ou  
Date: 11.DEC.2024 19:18:54

Band 7\_15 MHz\_Middle\_16QAM\_RB75#0




ProjectNo.:2401Y68085E-RF Tester:Usain Ou  
Date: 11.DEC.2024 19:19:23

Band 7\_20 MHz\_Middle\_QPSK\_RB100#0



ProjectNo.:2401Y68085E-RF Tester:Usain Ou  
Date: 11.DEC.2024 19:22:21

Band 7\_20 MHz\_Middle\_16QAM\_RB100#0



ProjectNo.:2401Y68085E-RF Tester:Usain Ou  
Date: 11.DEC.2024 19:22:55

## Conducted Spurious Emissions

























