

1; After the machine is powered on automatically, touch the symbol marked in the following figure



2; Touch the Settings symbol marked in the image below



3; In the marked area below, touch down to the bottom and click Certification to appear as below

