







ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 21:14:25




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 21:15:19




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 21:16:08



ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 21:17:32




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 21:18:22



ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 21:19:11


B13 , Normal
1RB was the worst case

5MHz_Low_QPSK_1@0(30MHz~8.87GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 21:20:15

5MHz_Low_QPSK_1@0(763MHz~775MHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 21:10:32

5MHz_Low_QPSK_1@0(793MHz~806MHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 21:20:46

5MHz_Low_QPSK_1@0(1559MHz~1610MHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 21:20:58

5MHz_High_QPSK_1@0(30MHz~7.845GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 13.NOV.2024 21:22:11

5MHz_High_QPSK_1@0(763MHz~775MHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 13.NOV.2024 21:23:57

5MHz_High_QPSK_1@0(793MHz~806MHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 13.NOV.2024 21:25:17

5MHz_High_QPSK_1@0(1559MHz~1610MHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 13.NOV.2024 21:23:14

10MHz_Middle_QPSK_1@0(30MHz~8.87GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 8.NOV.2024 21:25:03

10MHz_Middle_QPSK_1@0(763MHz~775MHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 8.NOV.2024 21:25:17

10MHz_Middle_QPSK_1@0(793MHz~806MHz)



ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 8.NOV.2024 21:25:30


10MHz_Middle_QPSK_1@0(1559MHz~1610MHz)



ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 8.NOV.2024 21:25:44


B17 , Normal
1RB was the worst case

5MHz_Low_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 21:27:34

5MHz_Middle_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 21:18:25

5MHz_High_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 21:29:16

10MHz_Low_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 21:10:33

10MHz_Middle_QPSK_1@0(30MHz~8.16GHz)



ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 21:31:23


10MHz_High_QPSK_1@0(30MHz~8.16GHz)



ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 21:21:14


B66 , Normal
1RB was the worst case

1.4MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 17:36:33

1.4MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 17:37:53

1.4MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 17:39:14

3MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 17:40:50

3MHz_Middle_QPSK_1@0(30MHz~18.8GHz)









ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 17:42:10


3MHz_High_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 17:43:33




15MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 17:54:00

15MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 17:55:23

15MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 17:56:48

20MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 17:58:30

20MHz_Middle_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 17:59:53

20MHz_High_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 18:01:17