


Test setup semi-anechoic chamber M276, 30 MHz - 1 GHz

 Examiner:
 Sebastian KREHS
 Report Number:
 F231078E4

 Date of issue:
 19.12.2023
 Order Number:
 23-111078
 page 1 of 5






Test setup semi-anechoic chamber M276, $1-2~\mathrm{GHz}$


 Examiner:
 Sebastian KREHS
 Report Number:
 F231078E4

 Date of issue:
 19.12.2023
 Order Number:
 23-111078
 page 2 of 5





Main cable harness (PWR, CAN)



Secondary cable harness (LIN, SHP)

 Examiner:
 Sebastian KREHS
 Report Number:
 F231078E4

 Date of issue:
 19.12.2023
 Order Number:
 23-111078
 page 3 of 5





SilverBoxV2

 Examiner:
 Sebastian KREHS
 Report Number:
 F231078E4

 Date of issue:
 19.12.2023
 Order Number:
 23-111078
 page 4 of 5





Ignition lock + key

 Examiner:
 Sebastian KREHS
 Report Number:
 F231078E4

 Date of issue:
 19.12.2023
 Order Number:
 23-111078
 page 5 of 5