



5MHz_Low_QPSK_1@0




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 24.JUL.2024 09:19:17

5MHz_Low_QPSK_25@0




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 24.JUL.2024 09:34:38

5MHz_Low_16QAM_1@0




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 24.JUL.2024 09:30:48

5MHz_Low_16QAM_25@0




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 24.JUL.2024 09:35:00

5MHz_High_QPSK_1@24




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 24.JUL.2024 09:22:46

5MHz_High_QPSK_25@0




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 24.JUL.2024 09:35:34

5MHz_High_16QAM_1@24




ProjectNo.:2402V84480E-RF Tester:Loge Long
 Date: 24.JUL.2024 09:23:08

5MHz_High_16QAM_25@0




ProjectNo.:2402V84480E-RF Tester:Loge Long
 Date: 24.JUL.2024 09:35:57

10MHz_Low_QPSK_1@0




ProjectNo.:2402V84480E-RF Tester:Loge Long
 Date: 24.JUL.2024 09:23:57

10MHz_Low_QPSK_50@0




ProjectNo.:2402V84480E-RF Tester:Loge Long
 Date: 10.JUL.2024 17:17:03

10MHz_Low_16QAM_1@0




ProjectNo.:2402V84480E-RF Tester:Loge Long
 Date: 24.JUL.2024 09:24:30

10MHz_Low_16QAM_50@0




ProjectNo.:2402V84480E-RF Tester:Loge Long
 Date: 10.JUL.2024 17:17:24

10MHz_High_QPSK_1@49




ProjectNo.:2402V84480E-RF Tester:Loge Long
 Date: 24.JUL.2024 09:25:14

10MHz_High_QPSK_50@0




ProjectNo.:2402V84480E-RF Tester:Loge Long
 Date: 10.JUL.2024 17:17:56

10MHz_High_16QAM_1@49




ProjectNo.:2402V84480E-RF Tester:Loge Long
 Date: 24.JUL.2024 09:25:46

10MHz_High_16QAM_50@0




ProjectNo.:2402V84480E-RF Tester:Loge Long
 Date: 10.JUL.2024 17:18:17

15MHz_Low_QPSK_1@0




ProjectNo.:2402V84480E-RF Tester:Loge Long
 Date: 10.JUL.2024 17:19:08

15MHz_Low_QPSK_75@0




ProjectNo.:2402V84480E-RF Tester:Loge Long
 Date: 10.JUL.2024 17:18:58

15MHz_Low_16QAM_1@0




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 10.JUL.2024 17:19:28

15MHz_Low_16QAM_75@0




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 10.JUL.2024 17:19:18

15MHz_High_QPSK_1@74




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 10.JUL.2024 17:19:58

15MHz_High_QPSK_75@0




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 10.JUL.2024 17:19:48

15MHz_High_16QAM_1@74




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 10.JUL.2024 17:20:18

15MHz_High_16QAM_75@0




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 10.JUL.2024 17:20:08

20MHz_Low_QPSK_1@0




ProjectNo.:2402V84480E-RF Tester:Loge Long
 Date: 10.JUL.2024 17:21:00

20MHz_Low_QPSK_100@0




ProjectNo.:2402V84480E-RF Tester:Loge Long
 Date: 10.JUL.2024 17:20:49

20MHz_Low_16QAM_1@0




ProjectNo.:2402V84480E-RF Tester:Loge Long
 Date: 10.JUL.2024 17:21:21

20MHz_Low_16QAM_100@0




ProjectNo.:2402V84480E-RF Tester:Loge Long
 Date: 10.JUL.2024 17:21:10

20MHz_High_QPSK_1@99




ProjectNo.:2402V84480E-RF Tester:Loge Long
 Date: 10.JUL.2024 17:21:52

20MHz_High_QPSK_100@0




ProjectNo.:2402V84480E-RF Tester:Loge Long
 Date: 10.JUL.2024 17:21:41

20MHz_High_16QAM_1@99



ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 10.JUL.2024 17:22:14

20MHz_High_16QAM_100@0




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 10.JUL.2024 17:22:02

Spurious Emissions at Antenna Terminal

FCC Part 22H


B5, Normal

1.4MHz_Low_QPSK_1@0 -25.42dBm




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 9.JUL.2024 15:08:41

1.4MHz_Low_QPSK_6@0 -25.57dBm




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 9.JUL.2024 15:08:58

1.4MHz_Middle_QPSK_1@0 -25.65dBm




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 9.JUL.2024 15:09:16

1.4MHz_Middle_QPSK_6@0 -25.40dBm




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 9.JUL.2024 15:09:34

1.4MHz_High_QPSK_1@0 -26.02dBm




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 9.JUL.2024 15:09:52

1.4MHz_High_QPSK_6@0 -24.96dBm




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 9.JUL.2024 15:10:10


3MHz_Low_QPSK_1@0 -25.36dBm




3MHz_Low_QPSK_15@0 -25.29dBm




3MHz_Middle_QPSK_1@0 -25.64dBm




3MHz_Middle_QPSK_15@0 -25.62dBm




3MHz_High_QPSK_1@0 -25.29dBm




3MHz_High_QPSK_15@0 -25.64dBm




5MHz_Low_QPSK_1@0 -26.00dBm




5MHz_Low_QPSK_25@0 -25.29dBm




5MHz_Middle_QPSK_1@0 -25.49dBm




5MHz_Middle_QPSK_25@0 -25.57dBm




5MHz_High_QPSK_1@0 -24.95dBm



5MHz_High_QPSK_25@0 -24.92dBm




10MHz_Low_QPSK_1@0 -25.53dBm




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 9.JUL.2024 15:14:23

10MHz_Low_QPSK_50@0 -25.92dBm




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 9.JUL.2024 15:14:42

10MHz_Middle_QPSK_1@0 -26.21dBm




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 9.JUL.2024 15:15:02

10MHz_Middle_QPSK_50@0 -25.79dBm




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 9.JUL.2024 15:15:22

10MHz_High_QPSK_1@0 -25.71dBm



ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 9.JUL.2024 15:15:41

10MHz_High_QPSK_50@0 -25.78dBm




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 9.JUL.2024 15:16:00

FCC Part 24E


B2 , Normal

1.4MHz_Low_QPSK_1@0 -24.63dBm




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 9.JUL.2024 14:55:40

1.4MHz_Low_QPSK_6@0 -24.41dBm




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 9.JUL.2024 14:56:00

1.4MHz_Middle_QPSK_1@0 -24.50dBm




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 9.JUL.2024 14:56:20

1.4MHz_Middle_QPSK_6@0 -24.28dBm




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 9.JUL.2024 14:56:41

1.4MHz_High_QPSK_1@0 -23.76dBm




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 9.JUL.2024 14:57:01

1.4MHz_High_QPSK_6@0 -23.56dBm




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 9.JUL.2024 14:57:22


3MHz_Low_QPSK_1@0 -25.01dBm




3MHz_Low_QPSK_15@0 -24.27dBm




3MHz_Middle_QPSK_1@0 -24.50dBm




3MHz_Middle_QPSK_15@0 -24.34dBm




3MHz_High_QPSK_1@0 -24.59dBm



3MHz_High_QPSK_15@0 -24.18dBm




5MHz_Low_QPSK_1@0 -24.60dBm




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 9.JUL.2024 14:59:52

5MHz_Low_QPSK_25@0 -23.98dBm




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 9.JUL.2024 15:00:12

5MHz_Middle_QPSK_1@0 -23.22dBm




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 9.JUL.2024 15:00:33

5MHz_Middle_QPSK_25@0 -24.31dBm




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 9.JUL.2024 15:00:55

5MHz_High_QPSK_1@0 -24.25dBm




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 9.JUL.2024 15:01:16

5MHz_High_QPSK_25@0 -23.07dBm




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 9.JUL.2024 15:01:37

10MHz_Low_QPSK_1@0 -24.46dBm




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 9.JUL.2024 15:02:02

10MHz_Low_QPSK_50@0 -24.42dBm




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 9.JUL.2024 15:02:23

10MHz_Middle_QPSK_1@0 -24.32dBm




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 9.JUL.2024 15:02:46

10MHz_Middle_QPSK_50@0 -24.32dBm




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 9.JUL.2024 15:03:08

10MHz_High_QPSK_1@0 -25.12dBm




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 9.JUL.2024 15:03:30

10MHz_High_QPSK_50@0 -24.15dBm




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 9.JUL.2024 15:03:52

15MHz_Low_QPSK_1@0 -24.61dBm




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 9.JUL.2024 15:04:17

15MHz_Low_QPSK_75@0 -24.49dBm




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 9.JUL.2024 15:04:40

15MHz_Middle_QPSK_1@0 -24.83dBm




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 9.JUL.2024 15:05:03

15MHz_Middle_QPSK_75@0 -24.47dBm




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 9.JUL.2024 15:05:25

15MHz_High_QPSK_1@0 -24.51dBm




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 9.JUL.2024 15:05:48

15MHz_High_QPSK_75@0 -24.45dBm




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 9.JUL.2024 15:06:10


20MHz_Low_QPSK_1@0 -24.78dBm




20MHz_Low_QPSK_100@0 -23.66dBm




20MHz_Middle_QPSK_1@0 -24.84dBm




20MHz_Middle_QPSK_100@0 -24.76dBm



20MHz_High_QPSK_1@0 -24.44dBm




20MHz_High_QPSK_100@0 -24.56dBm



FCC Part 27


B12 , Normal

1.4MHz_Low_QPSK_1@0 -25.51dBm




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 9.JUL.2024 15:16:22

1.4MHz_Low_QPSK_6@0 -26.26dBm




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 9.JUL.2024 15:16:39

1.4MHz_Middle_QPSK_1@0 -25.30dBm




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 9.JUL.2024 15:16:58

1.4MHz_Middle_QPSK_6@0 -25.18dBm




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 9.JUL.2024 15:17:16

1.4MHz_High_QPSK_1@0 -25.27dBm




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 9.JUL.2024 15:17:34

1.4MHz_High_QPSK_6@0 -25.68dBm




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 9.JUL.2024 15:17:53


3MHz_Low_QPSK_1@0 -26.01dBm




3MHz_Low_QPSK_15@0 -25.56dBm




3MHz_Middle_QPSK_1@0 -25.40dBm




3MHz_Middle_QPSK_15@0 -26.00dBm




3MHz_High_QPSK_1@0 -24.85dBm




3MHz_High_QPSK_15@0 -25.57dBm




5MHz_Low_QPSK_1@0 -25.52dBm




5MHz_Low_QPSK_25@0 -25.76dBm




5MHz_Middle_QPSK_1@0 -25.91dBm




5MHz_Middle_QPSK_25@0 -25.72dBm




5MHz_High_QPSK_1@0 -25.04dBm



5MHz_High_QPSK_25@0 -25.25dBm




10MHz_Low_QPSK_1@0 -25.56dBm




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 9.JUL.2024 15:21:56

10MHz_Low_QPSK_50@0 -25.86dBm




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 9.JUL.2024 15:22:24

10MHz_Middle_QPSK_1@0 -26.05dBm




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 9.JUL.2024 15:22:43

10MHz_Middle_QPSK_50@0 -25.72dBm




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 9.JUL.2024 15:23:01

10MHz_High_QPSK_1@0 -25.43dBm



ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 9.JUL.2024 15:23:20


10MHz_High_QPSK_50@0 -25.84dBm




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 9.JUL.2024 15:23:38

B66 , Normal


1.4MHz_Low_QPSK_1@0 -24.51dBm




1.4MHz_Low_QPSK_6@0 -24.36dBm




1.4MHz_Middle_QPSK_1@0 -24.53dBm




1.4MHz_Middle_QPSK_6@0 -23.33dBm




1.4MHz_High_QPSK_1@0 -24.10dBm



1.4MHz_High_QPSK_6@0 -24.44dBm




3MHz_Low_QPSK_1@0 -23.97dBm




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 9.JUL.2024 15:26:34

3MHz_Low_QPSK_15@0 -24.58dBm




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 9.JUL.2024 15:26:55

3MHz_Middle_QPSK_1@0 -24.30dBm




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 9.JUL.2024 15:27:16

3MHz_Middle_QPSK_15@0 -24.74dBm




ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 9.JUL.2024 15:27:37

3MHz_High_QPSK_1@0 -24.40dBm



ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 9.JUL.2024 15:27:58

3MHz_High_QPSK_15@0 -24.61dBm



ProjectNo.:2402V84480E-RF Tester:Loge Long
Date: 9.JUL.2024 15:28:20