


INTERTEK TESTING SERVICE

Report No.: 14070655HKG-001

Equipment Photographs

Model: CR82060BE1

(Internal)





INTERTEK TESTING SERVICE

Report No.: 14070655HKG-001

Equipment Photographs

Model: CR82060BE1

(Internal)





INTERTEK TESTING SERVICE

Report No.: 14070655HKG-001

Equipment Photographs

Model: CR82060BE1

(Internal)





INTERTEK TESTING SERVICE

Report No.: 14070655HKG-001

Equipment Photographs

Model: CR82060BE1

(Internal)




INTERTEK TESTING SERVICE

Report No.: 14070655HKG-001

Equipment Photographs

Model: CR82060BE1

(Internal)




INTERTEK TESTING SERVICE

Report No.: 14070655HKG-001

Equipment Photographs

Model: CR82060BE1

(Internal)





INTERTEK TESTING SERVICE

Report No.: 14070655HKG-001

Equipment Photographs

Model: CR82060BE1

(Internal)




INTERTEK TESTING SERVICE

Report No.: 14070655HKG-001

Equipment Photographs

Model: CR82060BE1

(Internal)





INTERTEK TESTING SERVICE

Report No.: 14070655HKG-001

Equipment Photographs

Model: CR82060BE1

(Internal)



INTERTEK TESTING SERVICE

Report No.: 14070655HKG-001

Equipment Photographs

Model: CR82060BE1

(Internal)




INTERTEK TESTING SERVICE

Report No.: 14070655HKG-001

Equipment Photographs

Model: CR82060BE1

(Internal)



INTERTEK TESTING SERVICE

Report No.: 14070655HKG-001

Equipment Photographs

Model: CR82060BE1

(Internal)

