
### **INTERTEK TESTING SERVICE**

Report No: HK12090539-1

# Configuration Photographs Worst-Case Line-Conducted Emissions (Front View)

Model: PA5075U-1SPA




FCC ID: A2HPA5075U-1SPA

### **INTERTEK TESTING SERVICE**

Report No: HK12090539-1

# Configuration Photographs Worst-Case Line-Conducted Emissions (Rear View)

Model: PA5075U-1SPA




FCC ID: A2HPA5075U-1SPA

### **INTERTEK TESTING SERVICE**

Report No: HK12090539-1

# Configuration Photographs Worst-Case Line-Conducted Emissions (Side View)

Model: PA5075U-1SPA



FCC ID: A2HPA5075U-1SPA