


# INTERTEK TESTING SERVICE

---

Report No.: 13060108HKG-001

## Equipment Photographs

Model: SBX5065KU / SBX5065KC  
(Internal)



# INTERTEK TESTING SERVICE


---

Report No.: 13060108HKG-001

## Equipment Photographs

Model: SBX5065KU / SBX5065KC

(Internal)



---

# INTERTEK TESTING SERVICE


---

Report No.: 13060108HKG-001

## Equipment Photographs

Model: SBX5065KU / SBX5065KC

(Internal)



# INTERTEK TESTING SERVICE



---

Report No.: 13060108HKG-001

## Equipment Photographs

Model: SBX5065KU / SBX5065KC

(Internal)



---

# INTERTEK TESTING SERVICE


---

Report No.: 13060108HKG-001

## Equipment Photographs

Model: SBX5065KU / SBX5065KC

(Internal)



---

# INTERTEK TESTING SERVICE


---

Report No.: 13060108HKG-001

## Equipment Photographs

Model: SBX5065KU / SBX5065KC

(Internal)




# INTERTEK TESTING SERVICE

Report No.: 13060108HKG-001

## Equipment Photographs

Model: SBX5065KU / SBX5065KC

(Internal)



# INTERTEK TESTING SERVICE



---

Report No.: 13060108HKG-001

## Equipment Photographs

Model: SBX5065KU / SBX5065KC

(Internal)





---

# INTERTEK TESTING SERVICE


---

Report No.: 13060108HKG-001

## Equipment Photographs

Model: SBX5065KU / SBX5065KC

(Internal)



# INTERTEK TESTING SERVICE

Report No.: 13060108HKG-001

## Equipment Photographs

Model: SBX5065KU / SBX5065KC

(Internal)



FCC ID: A2HSBX5065KU  
IC: 9903A-SBX5065KU


# INTERTEK TESTING SERVICE

Report No.: 13060108HKG-001

## Equipment Photographs

Model: SBX5065KU / SBX5065KC

(Internal)





# INTERTEK TESTING SERVICE

Report No.: 13060108HKG-001

## Equipment Photographs

Model: SBX5065KU / SBX5065KC

(Internal)





# INTERTEK TESTING SERVICE

Report No.: 13060108HKG-001

## Equipment Photographs

Model: SBX5065KU / SBX5065KC

(Internal)



FCC ID: A2HSBX5065KU  
IC: 9903A-SBX5065KU



# INTERTEK TESTING SERVICE

Report No.: 13060108HKG-001

## Equipment Photographs

Model: SBX5065KU / SBX5065KC

(Internal)




# INTERTEK TESTING SERVICE

Report No.: 13060108HKG-001

## Equipment Photographs

Model: SBX5065KU / SBX5065KC

(Internal)









# INTERTEK TESTING SERVICE

Report No.: 13060108HKG-001

## Equipment Photographs

Model: SBX5065KU / SBX5065KC

(Internal)





# INTERTEK TESTING SERVICE

Report No.: 13060108HKG-001

## Equipment Photographs

Model: SBX5065KU / SBX5065KC

(Internal)





# INTERTEK TESTING SERVICE

Report No.: 13060108HKG-001

## Equipment Photographs

Model: SBX5065KU / SBX5065KC

(Internal)



# INTERTEK TESTING SERVICE

Report No.: 13060108HKG-001

## Equipment Photographs

Model: SBX5065KU / SBX5065KC

(Internal)

