

CLX-3305FW Series Photo


Internal View Photo

CLX-3305FW Series Photo




Internal View Photo_Front

CLX-3305FW Series Photo



Internal View Photo_Right

CLX-3305FW Series Photo



Internal View Photo_Left

CLX-3305FW Series Photo




Internal View Photo_Rear

CLX-3305FW Series Photo



Internal View Photo_Top

CLX-3305FW Series Photo




Internal View Photo_Bottom

CLX-3305FW Series Photo


PBAs Photo

CLX-3305FW Series Photo




PBA Photo_Main PBA_Bottom

CLX-3305FW Series Photo




PBA Photo_SMPS PBA_Top

CLX-3305FW Series Photo




PBA Photo_SMPS PBA_Bottom

CLX-3305FW Series Photo




PBA Photo_HVPS PBA_Top

CLX-3305FW Series Photo




PBA Photo_HVPS PBA_Bottom

CLX-3305FW Series Photo




PBA Photo_Connection PBA_Top

CLX-3305FW Series Photo



PBA Photo_Connection PBA_Bottom

CLX-3305FW Series Photo




PBA Photo_CRUM PBA_Top

CLX-3305FW Series Photo




PBA Photo_CRUM PBA_Bottom

CLX-3305FW Series Photo




PBA Photo_Crumjoint PBA_Top

CLX-3305FW Series Photo




PBA Photo_Crumjoint PBA_Bottom

CLX-3305FW Series Photo




PBA Photo_USB Host PBA_Top

CLX-3305FW Series Photo




PBA Photo_USB Host PBA_Bottom

CLX-3305FW Series Photo




PBA Photo_OPE PBA_Top

CLX-3305FW Series Photo




PBA Photo_OPE PBA_Bottom

CLX-3305FW Series Photo




PBA Photo_Fax PBA_Top

CLX-3305FW Series Photo



PBA Photo_Fax PBA_Bottom

CLX-3305FW Series Photo



PBA Photo_ADF Connector PBA_Top

CLX-3305FW Series Photo



PBA Photo_ADF Connector PBA_Bottom

CLX-3305FW Series Photo



PBA Photo_WNPC PBA_Top

CLX-3305FW Series Photo



PBA Photo_WNPC PBA_Bottom