



Setup Photo

RADIATED RF MEASUREMENT SETUP (BELOW 30 MHz) X axis




RADIATED RF MEASUREMENT SETUP (BELOW 1 GHz) X axis






RADIATED RF MEASUREMENT SETUP (1 - 18 GHz) X axis




RADIATED RF MEASUREMENT SETUP (18 - 40 GHz) X axis




Test Set - Up Photos Page: 2 of 5 Report Format Version: BV-FRFTF-01-002



RADIATED RF MEASUREMENT SETUP (BELOW 30 MHz) Z axis




RADIATED RF MEASUREMENT SETUP (BELOW 1 GHz) Z axis




Test Set - Up Photos Page: 3 of 5 Report Format Version: BV-FRFTF-01-002



RADIATED RF MEASUREMENT SETUP (1 - 18 GHz) Z axis




RADIATED RF MEASUREMENT SETUP (18 - 40 GHz) Z axis





RADIATED RF MEASUREMENT SETUP FOR PORTABLE CONFIGURATION



- End of report -

Test Set - Up Photos Page: 5 of 5 Report Format Version: BV-FRFTF-01-002