



416, Maetan-3Dong, Yeongtong-Gu, Suwon-City, Gyeonggi-Do,
Korea 443-742

Date: February 22, 2010
Federal Communications Commission
7435 Oakland Mills Road
Columbia MD 21046

c.c.
Compliance Certification Services
Certification Division
47173 Benicia Street
Fremont, CA 94538, USA

Dear Sir/Madam

We, **SAMSUNG ELECTRONICS CO., LTD.**, located at 416, Maetan-3dong, Yeongtong-gu, Suwon-City, Gyeonggi-do, 443-742, Korea as manufacturer of the product **model: HMX-S16BN and HMX-S15BN**, declare that HMX-S15BN and HMX-16BN don't support HT-40.

FCC ID: A3LHMX-S16BN

In accordance with the marketing purpose, HT-40 for HMX-S15BN and HMX-S16BN is disabled by software although the module can support HT-40.

Sincerely,

A handwritten signature in black ink, appearing to be "S. Ra".

Sang Kyung (Peter) Ra / General Manager
Samsung Electronics Co., Ltd.