





**ANT 33**


**QPSK**

**16QAM**




**64QAM**

**256QAM**




**ANT 34**


**QPSK**




**16QAM**



**64QAM**



**256QAM**







**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2020-04662  
 Page (508) / (2355)  
 Pages

**ANT 35**



**QPSK**

**16QAM**



**64QAM**

**256QAM**







**ANT 36**



**QPSK**

**16QAM**



**64QAM**

**256QAM**







**ANT 37**



**QPSK**

**16QAM**



**64QAM**

**256QAM**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2020-04662  
 Page (511) / (2355)  
 Pages

**ANT 38**


**QPSK**




**16QAM**



**64QAM**



**256QAM**







**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2020-04662  
 Page (512) / (2355)  
 Pages

**ANT 39**



**QPSK**

**16QAM**



**64QAM**

**256QAM**






**ANT 40**

**QPSK**

**16QAM**








**ANT 41**



**QPSK**

**16QAM**



**64QAM**

**256QAM**







**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2020-04662  
 Page (515) / (2355)  
 Pages

**ANT 42**



**QPSK**

**16QAM**



**64QAM**

**256QAM**







**ANT 43**



**QPSK**

**16QAM**



**64QAM**

**256QAM**







**ANT 44**



**QPSK**

**16QAM**



**64QAM**

**256QAM**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2020-04662  
 Page (518) / (2355)  
 Pages

**ANT 45**

**QPSK**

**16QAM**






**CTK Co., Ltd.**  
(Ho-dong), 113, Yejik-ro, Cheoin-gu,  
Yongin-si, Gyeonggi-do, Korea  
Tel: +82-31-339-9970  
Fax: +82-31-624-9501

Report No.:  
CTK-2020-04662  
Page (519) / (2355)  
Pages

### ANT 46

#### QPSK

#### 16QAM







**ANT 47**



**QPSK**

**16QAM**



**64QAM**

**256QAM**







**ANT 48**



**QPSK**

**16QAM**



**64QAM**

**256QAM**









**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2020-04662  
 Page (522) / (2355)  
 Pages

**ANT 49**



**QPSK**

**16QAM**



**64QAM**

**256QAM**






**CTK Co., Ltd.**  
(Ho-dong), 113, Yejik-ro, Cheoin-gu,  
Yongin-si, Gyeonggi-do, Korea  
Tel: +82-31-339-9970  
Fax: +82-31-624-9501

Report No.:  
CTK-2020-04662  
Page (523) / (2355)  
Pages

### ANT 50


#### QPSK




#### 16QAM



#### 64QAM



#### 256QAM







**ANT 51**



**QPSK**

**16QAM**



**64QAM**

**256QAM**







**ANT 52**



**QPSK**

**16QAM**



**64QAM**

**256QAM**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2020-04662  
 Page (526) / (2355)  
 Pages

**ANT 53**

**QPSK**

**16QAM**







**ANT 54**



**QPSK**

**16QAM**



**64QAM**

**256QAM**







**ANT 55**



**QPSK**

**16QAM**



**64QAM**

**256QAM**







**ANT 56**



**QPSK**

**16QAM**



**64QAM**

**256QAM**









**ANT 57**



**QPSK**

**16QAM**



**64QAM**


**256QAM**






**ANT 58**


**QPSK**




**16QAM**



**64QAM**



**256QAM**







**ANT 59**



**QPSK**

**16QAM**



**64QAM**

**256QAM**







**ANT 60**



**QPSK**

**16QAM**



**64QAM**

**256QAM**







**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2020-04662  
 Page (534) / (2355)  
 Pages

**ANT 61**



**QPSK**

**16QAM**



**64QAM**

**256QAM**







**ANT 62**



**QPSK**

**16QAM**



**64QAM**

**256QAM**







**ANT 63**



**QPSK**

**16QAM**



**64QAM**

**256QAM**







**ANT 64**



**QPSK**

**16QAM**



**64QAM**

**256QAM**








**CTK Co., Ltd.**  
(Ho-dong), 113, Yejik-ro, Cheoin-gu,  
Yongin-si, Gyeonggi-do, Korea  
Tel: +82-31-339-9970  
Fax: +82-31-624-9501

Report No.:  
CTK-2020-04662  
Page (538) / (2355)  
Pages


### Test Plot at Peak-to-Average Ratio

BW 100MHz, Single carrier, Bottom  
ANT1


#### QPSK




#### 16QAM



#### 64QAM



#### 256QAM






**CTK Co., Ltd.**  
(Ho-dong), 113, Yejik-ro, Cheoin-gu,  
Yongin-si, Gyeonggi-do, Korea  
Tel: +82-31-339-9970  
Fax: +82-31-624-9501


Report No.:  
CTK-2020-04662  
Page (539) / (2355)  
Pages

### ANT2


#### QPSK




#### 16QAM



#### 64QAM



#### 256QAM







**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2020-04662  
 Page (540) / (2355)  
 Pages

**ANT3**



**QPSK**

**16QAM**



**64QAM**

**256QAM**







**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2020-04662  
 Page (541) / (2355)  
 Pages

**ANT4**



**QPSK**

**16QAM**



**64QAM**

**256QAM**







**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2020-04662  
 Page (542) / (2355)  
 Pages

**ANT5**



**QPSK**

**16QAM**



**64QAM**

**256QAM**







**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2020-04662  
 Page (543) / (2355)  
 Pages

**ANT6**



**QPSK**

**16QAM**



**64QAM**

**256QAM**







**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2020-04662  
 Page (544) / (2355)  
 Pages

**ANT7**



**QPSK**

**16QAM**



**64QAM**

**256QAM**







**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2020-04662  
 Page (545) / (2355)  
 Pages

**ANT8**



**QPSK**

**16QAM**



**64QAM**

**256QAM**









**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2020-04662  
 Page (546) / (2355)  
 Pages

**ANT9**



**QPSK**

**16QAM**



**64QAM**

**256QAM**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2020-04662  
 Page (547) / (2355)  
 Pages

**ANT10**


**QPSK**




**16QAM**



**64QAM**



**256QAM**







**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2020-04662  
 Page (548) / (2355)  
 Pages

**ANT11**



**QPSK**

**16QAM**



**64QAM**

**256QAM**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2020-04662  
 Page (549) / (2355)  
 Pages

**ANT12**


**QPSK**




**16QAM**



**64QAM**



**256QAM**







**CTK Co., Ltd.**  
(Ho-dong), 113, Yejik-ro, Cheoin-gu,  
Yongin-si, Gyeonggi-do, Korea  
Tel: +82-31-339-9970  
Fax: +82-31-624-9501

Report No.:  
CTK-2020-04662  
Page (550) / (2355)  
Pages

**ANT13**



**QPSK**

**16QAM**



**64QAM**

**256QAM**







**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2020-04662  
 Page (551) / (2355)  
 Pages

**ANT14**



**QPSK**

**16QAM**



**64QAM**

**256QAM**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2020-04662  
 Page (552) / (2355)  
 Pages

**ANT15**


**QPSK**




**16QAM**



**64QAM**



**256QAM**







**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2020-04662  
 Page (553) / (2355)  
 Pages

**ANT16**



**QPSK**

**16QAM**



**64QAM**

**256QAM**








**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2020-04662  
 Page (554) / (2355)  
 Pages

**ANT17**


**QPSK**




**16QAM**



**64QAM**



**256QAM**







**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2020-04662  
 Page (555) / (2355)  
 Pages

**ANT18**



**QPSK**

**16QAM**



**64QAM**

**256QAM**







**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2020-04662  
 Page (556) / (2355)  
 Pages

**ANT19**



**QPSK**

**16QAM**



**64QAM**

**256QAM**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2020-04662  
 Page (557) / (2355)  
 Pages

**ANT20**


**QPSK**




**16QAM**



**64QAM**



**256QAM**







**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2020-04662  
 Page (558) / (2355)  
 Pages

**ANT21**



**QPSK**

**16QAM**



**64QAM**

**256QAM**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2020-04662  
 Page (559) / (2355)  
 Pages

**ANT22**


**QPSK**



**16QAM**



**64QAM**



**256QAM**

