




ANT14


QPSK




16QAM



64QAM




256QAM





ANT15


QPSK



16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2020-04662
 Page (824) / (2355)
 Pages

ANT16

QPSK




16QAM



64QAM



256QAM






ANT17

QPSK



16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2020-04662
 Page (826) / (2355)
 Pages

ANT18


QPSK




16QAM



64QAM



256QAM






ANT19

QPSK

16QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2020-04662
 Page (828) / (2355)
 Pages

ANT20

QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2020-04662
 Page (829) / (2355)
 Pages

ANT21


QPSK



16QAM



64QAM




256QAM






ANT22

QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2020-04662
 Page (831) / (2355)
 Pages

ANT23


QPSK



16QAM



64QAM




256QAM




ANT24


QPSK




16QAM



64QAM



256QAM






ANT25

QPSK

16QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2020-04662
 Page (834) / (2355)
 Pages

ANT26


QPSK



16QAM



64QAM



256QAM






ANT27


QPSK

16QAM



ANT28


QPSK



16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2020-04662
 Page (837) / (2355)
 Pages

ANT29

QPSK




16QAM



64QAM




256QAM






ANT30

QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2020-04662
 Page (839) / (2355)
 Pages

ANT31

QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2020-04662
 Page (840) / (2355)
 Pages

ANT32


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2020-04662
 Page (841) / (2355)
 Pages

ANT33


QPSK

16QAM




ANT34


QPSK



16QAM



64QAM



256QAM





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2020-04662
 Page (843) / (2355)
 Pages

ANT35

QPSK




16QAM



64QAM



256QAM






ANT36


QPSK

16QAM




ANT37


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2020-04662
 Page (846) / (2355)
 Pages

ANT38

QPSK




16QAM



64QAM




256QAM



ANT39


QPSK




16QAM



64QAM




256QAM






ANT40


QPSK



16QAM



64QAM




256QAM



ANT41

QPSK



16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2020-04662
 Page (850) / (2355)
 Pages

ANT42

QPSK

16QAM





ANT43


QPSK



16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2020-04662
 Page (852) / (2355)
 Pages

ANT44


QPSK




16QAM



64QAM




256QAM




ANT45

QPSK




16QAM



64QAM




256QAM






ANT46

QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2020-04662
 Page (855) / (2355)
 Pages

ANT47

QPSK




16QAM



64QAM




256QAM




ANT48


QPSK



16QAM



64QAM




256QAM



ANT49


QPSK



16QAM



64QAM




256QAM





ANT50


QPSK



16QAM



64QAM




256QAM




ANT51

QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2020-04662
 Page (860) / (2355)
 Pages

ANT52

QPSK




16QAM



64QAM



256QAM






ANT53


QPSK

16QAM




ANT54

QPSK




16QAM



64QAM




256QAM




ANT55


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2020-04662
 Page (864) / (2355)
 Pages

ANT56


QPSK



16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2020-04662
 Page (865) / (2355)
 Pages

ANT57

QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2020-04662
 Page (866) / (2355)
 Pages

ANT58

QPSK


16QAM






ANT59


QPSK



16QAM



64QAM




256QAM






ANT60

QPSK




16QAM



64QAM




256QAM






ANT61

QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2020-04662
 Page (870) / (2355)
 Pages

ANT62


QPSK



16QAM



64QAM




256QAM



ANT63


QPSK



16QAM



64QAM



256QAM






ANT64

QPSK



16QAM



64QAM



256QAM





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2020-04662
 Page (873) / (2355)
 Pages

**BW 100MHz, Single carrier, Top
 ANT1**


QPSK



16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2020-04662
 Page (874) / (2355)
 Pages

ANT2

QPSK



16QAM



64QAM



256QAM

