





ANT41


QPSK




16QAM



64QAM




256QAM






ANT42


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2020-04662
 Page (1107) / (2355)
 Pages

ANT43


QPSK

16QAM



ANT44


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2020-04662
 Page (1109) / (2355)
 Pages

ANT45


QPSK

16QAM




ANT46


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2020-04662
 Page (1111) / (2355)
 Pages

ANT47


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2020-04662
 Page (1112) / (2355)
 Pages

ANT48


QPSK




16QAM



64QAM




256QAM




ANT49


QPSK




16QAM



64QAM




256QAM




ANT50


QPSK




16QAM



64QAM




256QAM




ANT51


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2020-04662
 Page (1116) / (2355)
 Pages

ANT52


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2020-04662
 Page (1117) / (2355)
 Pages

ANT53


QPSK




16QAM



64QAM




256QAM






ANT54


QPSK




16QAM



64QAM




256QAM






ANT55


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2020-04662
 Page (1120) / (2355)
 Pages

ANT56


QPSK




16QAM



64QAM




256QAM



ANT57


QPSK




16QAM



64QAM



256QAM





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2020-04662
 Page (1122) / (2355)
 Pages

ANT58


QPSK



16QAM



64QAM



256QAM





ANT59


QPSK




16QAM



64QAM



256QAM





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2020-04662
 Page (1124) / (2355)
 Pages

ANT60

QPSK




16QAM



64QAM




256QAM




ANT61


QPSK




16QAM



64QAM



256QAM





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2020-04662
 Page (1126) / (2355)
 Pages

ANT62


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2020-04662
 Page (1127) / (2355)
 Pages

ANT63


QPSK




16QAM



64QAM




256QAM




ANT64


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2020-04662
 Page (1129) / (2355)
 Pages

**BW 100MHz / 100MHz, Multi carrier(Non-contiguous), Bottom(1st FA CCO)
 ANT1**






ANT2

QPSK

16QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2020-04662
 Page (1131) / (2355)
 Pages

ANT3

QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2020-04662
 Page (1132) / (2355)
 Pages

ANT4

QPSK




16QAM



64QAM




256QAM




ANT5


QPSK




16QAM



64QAM




256QAM



ANT6


QPSK

16QAM



ANT7


QPSK




16QAM



64QAM




256QAM



ANT8

QPSK

16QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2020-04662
 Page (1137) / (2355)
 Pages

ANT9

QPSK




16QAM



64QAM




256QAM




ANT10


QPSK




16QAM



64QAM




256QAM




ANT11


QPSK




16QAM



64QAM




256QAM



ANT12


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2020-04662
 Page (1141) / (2355)
 Pages

ANT13


QPSK




16QAM



64QAM




256QAM




ANT14


QPSK




16QAM



64QAM




256QAM



ANT15


QPSK

16QAM




ANT16


QPSK




16QAM



64QAM




256QAM




ANT17


QPSK




16QAM



64QAM




256QAM






ANT18


QPSK




16QAM



64QAM




256QAM




ANT19


QPSK




16QAM



64QAM




256QAM




ANT20


QPSK




16QAM



64QAM




256QAM




ANT21


QPSK




16QAM



64QAM




256QAM




ANT22


QPSK




16QAM



64QAM




256QAM




ANT23


QPSK




16QAM



64QAM



256QAM




ANT24

QPSK




16QAM



64QAM



256QAM





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2020-04662
 Page (1153) / (2355)
 Pages

ANT25

QPSK



16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2020-04662
 Page (1154) / (2355)
 Pages

ANT26


QPSK

16QAM




ANT27


QPSK




16QAM



64QAM



256QAM






ANT28


QPSK

16QAM




ANT29


QPSK




16QAM



64QAM



256QAM



ANT30

QPSK



16QAM



64QAM



256QAM

