




CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2018-03329
Page (106) / (2957)
Pages

Band 66, BW 5MHz + BW 10MHz, Multi 2 carrier(Contiguous), 4TX, Top


QPSK



16QAM



64QAM



256QAM






ANT 4

Band 66, BW 5MHz + BW 10MHz, Multi 2 carrier(Contiguous), 4TX, Bottom


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2018-03329
 Page (108) / (2957)
 Pages

Band 66, BW 5MHz + BW 10MHz, Multi 2 carrier(Contiguous), 4TX, Top

QPSK




16QAM



64QAM



256QAM







ANT 1

Band 66, BW 5MHz + BW 15MHz, Multi 2 carrier(Contiguous), 4TX, Bottom



QPSK

16QAM



64QAM

256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2018-03329
 Page (110) / (2957)
 Pages

Band 66, BW 5MHz + BW 15MHz, Multi 2 carrier(Contiguous), 4TX, Top


QPSK




16QAM



64QAM




256QAM






ANT 2
Band 66, BW 5MHz + BW 15MHz, Multi 2 carrier(Contiguous), 4TX, Bottom


QPSK




16QAM



64QAM



256QAM





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501


Report No.:
CTK-2018-03329
Page (112) / (2957)
Pages

Band 66, BW 5MHz + BW 15MHz, Multi 2 carrier(Contiguous), 4TX, Top


QPSK




16QAM



64QAM



256QAM





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2018-03329
Page (113) / (2957)
Pages

ANT 3

Band 66, BW 5MHz + BW 15MHz, Multi 2 carrier(Contiguous), 4TX, Bottom



QPSK

16QAM



64QAM

256QAM





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2018-03329
 Page (114) / (2957)
 Pages

Band 66, BW 5MHz + BW 15MHz, Multi 2 carrier(Contiguous), 4TX, Top


QPSK




16QAM



64QAM



256QAM





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501



Report No.:
 CTK-2018-03329
 Page (115) / (2957)
 Pages

ANT 4

Band 66, BW 5MHz + BW 15MHz, Multi 2 carrier(Contiguous), 4TX, Bottom



QPSK

16QAM



64QAM


256QAM






Band 66, BW 5MHz + BW 15MHz, Multi 2 carrier(Contiguous), 4TX, Top


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2018-03329
 Page (117) / (2957)
 Pages


ANT 1

Band 66, BW 5MHz + BW 20MHz, Multi 2 carrier(Contiguous), 4TX, Bottom


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2018-03329
 Page (118) / (2957)
 Pages

Band 66, BW 5MHz + BW 20MHz, Multi 2 carrier(Contiguous), 4TX, Top


QPSK




16QAM



64QAM



256QAM





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2018-03329
 Page (119) / (2957)
 Pages

ANT 2
Band 66, BW 5MHz + BW 20MHz, Multi 2 carrier(Contiguous), 4TX, Bottom


QPSK




16QAM



64QAM




256QAM






Band 66, BW 5MHz + BW 20MHz, Multi 2 carrier(Contiguous), 4TX, Top


QPSK




16QAM



64QAM



256QAM






ANT 3

Band 66, BW 5MHz + BW 20MHz, Multi 2 carrier(Contiguous), 4TX, Bottom


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2018-03329
 Page (122) / (2957)
 Pages

Band 66, BW 5MHz + BW 20MHz, Multi 2 carrier(Contiguous), 4TX, Top


QPSK




16QAM



64QAM



256QAM





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501



Report No.:
 CTK-2018-03329
 Page (123) / (2957)
 Pages

ANT 4

Band 66, BW 5MHz + BW 20MHz, Multi 2 carrier(Contiguous), 4TX, Bottom



QPSK

16QAM



64QAM


256QAM






Band 66, BW 5MHz + BW 20MHz, Multi 2 carrier(Contiguous), 4TX, Top


QPSK




16QAM



64QAM



256QAM





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2018-03329
 Page (125) / (2957)
 Pages


ANT 1

Band 66, BW 10MHz + BW 10MHz, Multi 2 carrier(Contiguous), 4TX, Bottom


QPSK




16QAM



64QAM




256QAM





Band 66, BW 10MHz + BW 10MHz, Multi 2 carrier(Contiguous), 4TX, Top


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2018-03329
 Page (127) / (2957)
 Pages


ANT 2

Band 66, BW 10MHz + BW 10MHz, Multi 2 carrier(Contiguous), 4TX, Bottom


QPSK




16QAM



64QAM



256QAM





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501


Report No.:
CTK-2018-03329
Page (128) / (2957)
Pages

Band 66, BW 10MHz + BW 10MHz, Multi 2 carrier(Contiguous), 4TX, Top


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2018-03329
 Page (129) / (2957)
 Pages


ANT 3

Band 66, BW 10MHz + BW 10MHz, Multi 2 carrier(Contiguous), 4TX, Bottom


QPSK




16QAM



64QAM



256QAM





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501


Report No.:
CTK-2018-03329
Page (130) / (2957)
Pages

Band 66, BW 10MHz + BW 10MHz, Multi 2 carrier(Contiguous), 4TX, Top


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2018-03329
 Page (131) / (2957)
 Pages


ANT 4

Band 66, BW 10MHz + BW 10MHz, Multi 2 carrier(Contiguous), 4TX, Bottom


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2018-03329
 Page (132) / (2957)
 Pages

Band 66, BW 10MHz + BW 10MHz, Multi 2 carrier(Contiguous), 4TX, Top


QPSK




16QAM



64QAM



256QAM





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2018-03329
 Page (133) / (2957)
 Pages


ANT 1

Band 66, BW 10MHz + BW 15MHz, Multi 2 carrier(Contiguous), 4TX, Bottom


QPSK




16QAM



64QAM



256QAM







Band 66, BW 10MHz + BW 15MHz, Multi 2 carrier(Contiguous), 4TX, Top



QPSK

16QAM



64QAM

256QAM






ANT 2

Band 66, BW 10MHz + BW 15MHz, Multi 2 carrier(Contiguous), 4TX, Bottom



QPSK

16QAM



64QAM


256QAM






Band 66, BW 10MHz + BW 15MHz, Multi 2 carrier(Contiguous), 4TX, Top


QPSK




16QAM



64QAM



256QAM





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2018-03329
 Page (137) / (2957)
 Pages

ANT 3

Band 66, BW 10MHz + BW 15MHz, Multi 2 carrier(Contiguous), 4TX, Bottom



QPSK

16QAM



64QAM

256QAM







Band 66, BW 10MHz + BW 15MHz, Multi 2 carrier(Contiguous), 4TX, Top



QPSK

16QAM



64QAM

256QAM





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2018-03329
 Page (139) / (2957)
 Pages

ANT 4

Band 66, BW 10MHz + BW 15MHz, Multi 2 carrier(Contiguous), 4TX, Bottom


QPSK




16QAM



64QAM



256QAM







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2018-03329
Page (140) / (2957)
Pages

Band 66, BW 10MHz + BW 15MHz, Multi 2 carrier(Contiguous), 4TX, Top



QPSK

16QAM



64QAM

256QAM







ANT 1

Band 66, BW 10MHz + BW 20MHz, Multi 2 carrier(Contiguous), 4TX, Bottom


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2018-03329
 Page (142) / (2957)
 Pages

Band 66, BW 10MHz + BW 20MHz, Multi 2 carrier(Contiguous), 4TX, Top


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2018-03329
 Page (143) / (2957)
 Pages

ANT 2
Band 66, BW 10MHz + BW 20MHz, Multi 2 carrier(Contiguous), 4TX, Bottom


QPSK




16QAM



64QAM



256QAM






Band 66, BW 10MHz + BW 20MHz, Multi 2 carrier(Contiguous), 4TX, Top


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2018-03329
 Page (145) / (2957)
 Pages


ANT 3

Band 66, BW 10MHz + BW 20MHz, Multi 2 carrier(Contiguous), 4TX, Bottom


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2018-03329
 Page (146) / (2957)
 Pages

Band 66, BW 10MHz + BW 20MHz, Multi 2 carrier(Contiguous), 4TX, Top


QPSK




16QAM



64QAM



256QAM





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2018-03329
Page (147) / (2957)
Pages

ANT 4

Band 66, BW 10MHz + BW 20MHz, Multi 2 carrier(Contiguous), 4TX, Bottom



QPSK

16QAM



64QAM

256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2018-03329
 Page (148) / (2957)
 Pages

Band 66, BW 10MHz + BW 20MHz, Multi 2 carrier(Contiguous), 4TX, Top


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2018-03329
 Page (149) / (2957)
 Pages


ANT 1

Band 66, BW 5MHz + BW 15MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Bottom


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501


Report No.:
CTK-2018-03329
Page (150) / (2957)
Pages

Band 66, BW 5MHz + BW 15MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Middle


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2018-03329
 Page (151) / (2957)
 Pages

Band 66, BW 5MHz + BW 15MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Top


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2018-03329
 Page (152) / (2957)
 Pages


ANT 2

Band 66, BW 5MHz + BW 15MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Bottom


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2018-03329
 Page (153) / (2957)
 Pages

Band 66, BW 5MHz + BW 15MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Middle


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2018-03329
Page (154) / (2957)
Pages

Band 66, BW 5MHz + BW 15MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Top


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2018-03329
 Page (155) / (2957)
 Pages


ANT 3

Band 66, BW 5MHz + BW 15MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Bottom


QPSK




16QAM



64QAM



256QAM





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2018-03329
 Page (156) / (2957)
 Pages

Band 66, BW 5MHz + BW 15MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Middle


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2018-03329
 Page (157) / (2957)
 Pages

Band 66, BW 5MHz + BW 15MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Top


QPSK



16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2018-03329
 Page (158) / (2957)
 Pages


ANT 4

Band 66, BW 5MHz + BW 15MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Bottom


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2018-03329
 Page (159) / (2957)
 Pages

Band 66, BW 5MHz + BW 15MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Middle


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2018-03329
 Page (160) / (2957)
 Pages

Band 66, BW 5MHz + BW 15MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Top


QPSK




16QAM



64QAM



256QAM





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2018-03329
 Page (161) / (2957)
 Pages

ANT 1

Band 66, BW 10MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Bottom

QPSK	16QAM
<p>Center Freq 2.125000000 GHz</p> <p>Channel Power: 44.08 dBm / 30 MHz</p> <p>Power Spectral Density: -30.69 dBm / Hz</p>	<p>Center Freq 2.125000000 GHz</p> <p>Channel Power: 44.13 dBm / 30 MHz</p> <p>Power Spectral Density: -30.64 dBm / Hz</p>
64QAM	256QAM
<p>Center Freq 2.125000000 GHz</p> <p>Channel Power: 44.05 dBm / 30 MHz</p> <p>Power Spectral Density: -30.72 dBm / Hz</p>	<p>Center Freq 2.125000000 GHz</p> <p>Channel Power: 44.14 dBm / 30 MHz</p> <p>Power Spectral Density: -30.63 dBm / Hz</p>




CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2018-03329
 Page (162) / (2957)
 Pages

Band 66, BW 10MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Middle


QPSK



16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2018-03329
 Page (163) / (2957)
 Pages

Band 66, BW 10MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Top

QPSK



16QAM



64QAM



256QAM





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2018-03329
 Page (164) / (2957)
 Pages

ANT 2

Band 66, BW 10MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Bottom

QPSK	16QAM
<p>Channel Power: 44.35 dBm / 30 MHz</p> <p>Power Spectral Density: -30.42 dBm / Hz</p>	<p>Channel Power: 44.38 dBm / 30 MHz</p> <p>Power Spectral Density: -30.39 dBm / Hz</p>
64QAM	256QAM
<p>Channel Power: 44.21 dBm / 30 MHz</p> <p>Power Spectral Density: -30.56 dBm / Hz</p>	<p>Channel Power: 44.44 dBm / 30 MHz</p> <p>Power Spectral Density: -30.33 dBm / Hz</p>



CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2018-03329
 Page (165) / (2957)
 Pages

Band 66, BW 10MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Middle


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2018-03329
 Page (166) / (2957)
 Pages

Band 66, BW 10MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Top


QPSK




16QAM



64QAM



256QAM





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2018-03329
 Page (167) / (2957)
 Pages

ANT 3

Band 66, BW 10MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Bottom



QPSK

16QAM



64QAM

256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2018-03329
 Page (168) / (2957)
 Pages

Band 66, BW 10MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Middle


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2018-03329
 Page (169) / (2957)
 Pages

Band 66, BW 10MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Top


QPSK




16QAM



64QAM



256QAM





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2018-03329
 Page (170) / (2957)
 Pages

ANT 4

Band 66, BW 10MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Bottom

QPSK	16QAM
<p>Center Freq: 2.125000000 GHz Center Freq: 2.125000000 GHz Channel Power: 43.99 dBm / 30 MHz Power Spectral Density: -30.78 dBm / Hz</p>	<p>Center Freq: 2.125000000 GHz Center Freq: 2.125000000 GHz Channel Power: 44.09 dBm / 30 MHz Power Spectral Density: -30.68 dBm / Hz</p>
64QAM	256QAM
<p>Center Freq: 2.125000000 GHz Center Freq: 2.125000000 GHz Channel Power: 43.79 dBm / 30 MHz Power Spectral Density: -30.98 dBm / Hz</p>	<p>Center Freq: 2.125000000 GHz Center Freq: 2.125000000 GHz Channel Power: 44.05 dBm / 30 MHz Power Spectral Density: -30.72 dBm / Hz</p>




CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2018-03329
 Page (171) / (2957)
 Pages

Band 66, BW 10MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Middle


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2018-03329
 Page (172) / (2957)
 Pages

Band 66, BW 10MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Top


QPSK




16QAM



64QAM



256QAM





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2018-03329
Page (173) / (2957)
Pages

ANT 1

Band 66, BW 5MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Bottom



QPSK

16QAM



64QAM

256QAM






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501


Report No.:
CTK-2018-03329
Page (174) / (2957)
Pages

Band 66, BW 5MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Middle


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2018-03329
 Page (175) / (2957)
 Pages

Band 66, BW 5MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Top


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2018-03329
 Page (176) / (2957)
 Pages


ANT 2

Band 66, BW 5MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Bottom


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2018-03329
 Page (177) / (2957)
 Pages

Band 66, BW 5MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Middle


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2018-03329
 Page (178) / (2957)
 Pages

Band 66, BW 5MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Top


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2018-03329
 Page (179) / (2957)
 Pages


ANT 3

Band 66, BW 5MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Bottom


QPSK




16QAM



64QAM



256QAM





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2018-03329
 Page (180) / (2957)
 Pages

Band 66, BW 5MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Middle


QPSK




16QAM



64QAM




256QAM






Band 66, BW 5MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Top


QPSK




16QAM



64QAM



256QAM





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2018-03329
 Page (182) / (2957)
 Pages

ANT 4

Band 66, BW 5MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Bottom






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2018-03329
 Page (183) / (2957)
 Pages

Band 66, BW 5MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Middle


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2018-03329
 Page (184) / (2957)
 Pages

Band 66, BW 5MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Top


QPSK




16QAM



64QAM



256QAM





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2018-03329
 Page (185) / (2957)
 Pages


ANT 1

Band 66, BW 5MHz + BW 10MHz + BW 5MHz, Multi 3 carrier(Contiguous), 4TX, Bottom


QPSK




16QAM



64QAM



256QAM





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2018-03329
 Page (186) / (2957)
 Pages

Band 66, BW 5MHz + BW 10MHz + BW 5MHz, Multi 3 carrier(Contiguous), 4TX, Middle






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2018-03329
 Page (187) / (2957)
 Pages

Band 66, BW 5MHz + BW 10MHz + BW 5MHz, Multi 3 carrier(Contiguous), 4TX, Top


QPSK




16QAM



64QAM



256QAM





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2018-03329
 Page (188) / (2957)
 Pages


ANT 2

Band 66, BW 5MHz + BW 10MHz + BW 5MHz, Multi 3 carrier(Contiguous), 4TX, Bottom


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2018-03329
 Page (189) / (2957)
 Pages

Band 66, BW 5MHz + BW 10MHz + BW 5MHz, Multi 3 carrier(Contiguous), 4TX, Middle


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2018-03329
 Page (190) / (2957)
 Pages

Band 66, BW 5MHz + BW 10MHz + BW 5MHz, Multi 3 carrier(Contiguous), 4TX, Top


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2018-03329
 Page (191) / (2957)
 Pages


ANT 3

Band 66, BW 5MHz + BW 10MHz + BW 5MHz, Multi 3 carrier(Contiguous), 4TX, Bottom


QPSK




16QAM



64QAM



256QAM





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2018-03329
 Page (192) / (2957)
 Pages

Band 66, BW 5MHz + BW 10MHz + BW 5MHz, Multi 3 carrier(Contiguous), 4TX, Middle






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2018-03329
 Page (193) / (2957)
 Pages

Band 66, BW 5MHz + BW 10MHz + BW 5MHz, Multi 3 carrier(Contiguous), 4TX, Top


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2018-03329
Page (194) / (2957)
Pages


ANT 4

Band 66, BW 5MHz + BW 10MHz + BW 5MHz, Multi 3 carrier(Contiguous), 4TX, Bottom


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2018-03329
 Page (195) / (2957)
 Pages

Band 66, BW 5MHz + BW 10MHz + BW 5MHz, Multi 3 carrier(Contiguous), 4TX, Middle


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2018-03329
 Page (196) / (2957)
 Pages

Band 66, BW 5MHz + BW 10MHz + BW 5MHz, Multi 3 carrier(Contiguous), 4TX, Top


QPSK




16QAM



64QAM



256QAM





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2018-03329
 Page (197) / (2957)
 Pages

ANT 1

Band 66, BW 5MHz + BW 5MHz + BW 5MHz, Multi 3 carrier(Contiguous), 4TX, Bottom






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2018-03329
Page (198) / (2957)
Pages

Band 66, BW 5MHz + BW 5MHz + BW 5MHz, Multi 3 carrier(Contiguous), 4TX, Middle


QPSK



16QAM



64QAM



256QAM





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2018-03329
 Page (199) / (2957)
 Pages

Band 66, BW 5MHz + BW 5MHz + BW 5MHz, Multi 3 carrier(Contiguous), 4TX, Top


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2018-03329
 Page (200) / (2957)
 Pages


ANT 2

Band 66, BW 5MHz + BW 5MHz + BW 5MHz, Multi 3 carrier(Contiguous), 4TX, Bottom


QPSK




16QAM



64QAM



256QAM





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2018-03329
 Page (201) / (2957)
 Pages

Band 66, BW 5MHz + BW 5MHz + BW 5MHz, Multi 3 carrier(Contiguous), 4TX, Middle


QPSK




16QAM



64QAM



256QAM





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2018-03329
 Page (202) / (2957)
 Pages

Band 66, BW 5MHz + BW 5MHz + BW 5MHz, Multi 3 carrier(Contiguous), 4TX, Top

QPSK




16QAM



64QAM



256QAM





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501



Report No.:
 CTK-2018-03329
 Page (203) / (2957)
 Pages

ANT 3

Band 66, BW 5MHz + BW 5MHz + BW 5MHz, Multi 3 carrier(Contiguous), 4TX, Bottom



QPSK

16QAM



64QAM

256QAM





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501


Report No.:
CTK-2018-03329
Page (204) / (2957)
Pages

Band 66, BW 5MHz + BW 5MHz + BW 5MHz, Multi 3 carrier(Contiguous), 4TX, Middle


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2018-03329
 Page (205) / (2957)
 Pages

Band 66, BW 5MHz + BW 5MHz + BW 5MHz, Multi 3 carrier(Contiguous), 4TX, Top


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2018-03329
 Page (206) / (2957)
 Pages


ANT 4

Band 66, BW 5MHz + BW 5MHz + BW 5MHz, Multi 3 carrier(Contiguous), 4TX, Bottom


QPSK




16QAM



64QAM



256QAM





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501


Report No.:
CTK-2018-03329
Page (207) / (2957)
Pages

Band 66, BW 5MHz + BW 5MHz + BW 5MHz, Multi 3 carrier(Contiguous), 4TX, Middle


QPSK



16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2018-03329
 Page (208) / (2957)
 Pages

Band 66, BW 5MHz + BW 5MHz + BW 5MHz, Multi 3 carrier(Contiguous), 4TX, Top

QPSK




16QAM



64QAM



256QAM





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501



Report No.:
 CTK-2018-03329
 Page (209) / (2957)
 Pages

ANT 1

Band 66, BW 20MHz + BW 10MHz, Multi 2 carrier(Non-Contiguous), 4TX, Bottom



QPSK

16QAM



64QAM

256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2018-03329
 Page (210) / (2957)
 Pages

Band 66, BW 20MHz + BW 10MHz, Multi 2 carrier(Non-Contiguous), 4TX, Top


QPSK



16QAM



64QAM



256QAM

