





**ANT 2**  
**Band 66, BW 20MHz, Single 1 carrier, 4TX, Bottom**



QPSK

16QAM



64QAM


256QAM






**Band 66, BW 20MHz, Single 1 carrier, 4TX, Middle**


QPSK




16QAM



64QAM




256QAM





**Band 66, BW 20MHz, Single 1 carrier, 4TX, Top**


QPSK




16QAM



64QAM



256QAM







**ANT 3**  
**Band 66, BW 20MHz, Single 1 carrier, 4TX, Bottom**



QPSK

16QAM



64QAM

256QAM







**Band 66, BW 20MHz, Single 1 carrier, 4TX, Middle**



QPSK

16QAM



64QAM

256QAM







**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (426) / (2957)  
 Pages

**Band 66, BW 20MHz, Single 1 carrier, 4TX, Top**



QPSK

16QAM



64QAM

256QAM









**ANT 4**  
**Band 66, BW 20MHz, Single 1 carrier, 4TX, Bottom**



QPSK

16QAM



64QAM


256QAM






**Band 66, BW 20MHz, Single 1 carrier, 4TX, Middle**


QPSK




16QAM



64QAM



256QAM









**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (429) / (2957)  
 Pages

**Band 66, BW 20MHz, Single 1 carrier, 4TX, Top**



QPSK

16QAM



64QAM

256QAM







**ANT 1**

**Band 66, BW 5MHz + BW 5MHz, Multi 2 carrier(Contiguous), 4TX, Bottom**



QPSK

16QAM



64QAM

256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (431) / (2957)  
 Pages

**Band 66, BW 5MHz + BW 5MHz, Multi 2 carrier(Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03329  
 Page (432) / (2957)  
 Pages

**ANT 2**  
**Band 66, BW 5MHz + BW 5MHz, Multi 2 carrier(Contiguous), 4TX, Bottom**


QPSK




16QAM



64QAM



256QAM







**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (433) / (2957)  
 Pages

**Band 66, BW 5MHz + BW 5MHz, Multi 2 carrier(Contiguous), 4TX, Top**



QPSK

16QAM



64QAM

256QAM







**ANT 3**

**Band 66, BW 5MHz + BW 5MHz, Multi 2 carrier(Contiguous), 4TX, Bottom**


QPSK




16QAM



64QAM



256QAM








**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (435) / (2957)  
 Pages

**Band 66, BW 5MHz + BW 5MHz, Multi 2 carrier(Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (436) / (2957)  
 Pages


**ANT 4**

**Band 66, BW 5MHz + BW 5MHz, Multi 2 carrier(Contiguous), 4TX, Bottom**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (437) / (2957)  
 Pages

**Band 66, BW 5MHz + BW 5MHz, Multi 2 carrier(Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (438) / (2957)  
 Pages

**ANT 1**

**Band 66, BW 5MHz + BW 10MHz, Multi 2 carrier(Contiguous), 4TX, Bottom**



QPSK

16QAM



64QAM

256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (439) / (2957)  
 Pages

**Band 66, BW 5MHz + BW 10MHz, Multi 2 carrier(Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (440) / (2957)  
 Pages

**ANT 2**

**Band 66, BW 5MHz + BW 10MHz, Multi 2 carrier(Contiguous), 4TX, Bottom**



QPSK

16QAM



64QAM

256QAM









**Band 66, BW 5MHz + BW 10MHz, Multi 2 carrier(Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501



Report No.:  
 CTK-2018-03329  
 Page (442) / (2957)  
 Pages

**ANT 3**

**Band 66, BW 5MHz + BW 10MHz, Multi 2 carrier(Contiguous), 4TX, Bottom**



QPSK

16QAM



64QAM


256QAM






**Band 66, BW 5MHz + BW 10MHz, Multi 2 carrier(Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501



Report No.:  
 CTK-2018-03329  
 Page (444) / (2957)  
 Pages

**ANT 4**

**Band 66, BW 5MHz + BW 10MHz, Multi 2 carrier(Contiguous), 4TX, Bottom**



QPSK

16QAM



64QAM

256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03329  
 Page (445) / (2957)  
 Pages

**Band 66, BW 5MHz + BW 10MHz, Multi 2 carrier(Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM







**ANT 1**

**Band 66, BW 5MHz + BW 15MHz, Multi 2 carrier(Contiguous), 4TX, Bottom**



QPSK

16QAM



64QAM

256QAM








**Band 66, BW 5MHz + BW 15MHz, Multi 2 carrier(Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM







**ANT 2**

**Band 66, BW 5MHz + BW 15MHz, Multi 2 carrier(Contiguous), 4TX, Bottom**



QPSK

16QAM



64QAM

256QAM





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (449) / (2957)  
 Pages

**Band 66, BW 5MHz + BW 15MHz, Multi 2 carrier(Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM





**ANT 3**

**Band 66, BW 5MHz + BW 15MHz, Multi 2 carrier(Contiguous), 4TX, Bottom**



QPSK

16QAM



64QAM


256QAM





**Band 66, BW 5MHz + BW 15MHz, Multi 2 carrier(Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501



Report No.:  
 CTK-2018-03329  
 Page (452) / (2957)  
 Pages

**ANT 4**

**Band 66, BW 5MHz + BW 15MHz, Multi 2 carrier(Contiguous), 4TX, Bottom**



QPSK

16QAM



64QAM

256QAM








**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (453) / (2957)  
 Pages

**Band 66, BW 5MHz + BW 15MHz, Multi 2 carrier(Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501



Report No.:  
 CTK-2018-03329  
 Page (454) / (2957)  
 Pages

**ANT 1**

**Band 66, BW 5MHz + BW 20MHz, Multi 2 carrier(Contiguous), 4TX, Bottom**



QPSK

16QAM



64QAM

256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03329  
 Page (455) / (2957)  
 Pages

**Band 66, BW 5MHz + BW 20MHz, Multi 2 carrier(Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM







**ANT 2**

**Band 66, BW 5MHz + BW 20MHz, Multi 2 carrier(Contiguous), 4TX, Bottom**



QPSK

16QAM



64QAM


256QAM






**Band 66, BW 5MHz + BW 20MHz, Multi 2 carrier(Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM







**ANT 3**

**Band 66, BW 5MHz + BW 20MHz, Multi 2 carrier(Contiguous), 4TX, Bottom**


QPSK




16QAM



64QAM



256QAM








**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03329  
 Page (459) / (2957)  
 Pages

**Band 66, BW 5MHz + BW 20MHz, Multi 2 carrier(Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03329  
 Page (460) / (2957)  
 Pages

**ANT 4**

**Band 66, BW 5MHz + BW 20MHz, Multi 2 carrier(Contiguous), 4TX, Bottom**



QPSK

16QAM



64QAM


256QAM






**Band 66, BW 5MHz + BW 20MHz, Multi 2 carrier(Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM







**ANT 1**

**Band 66, BW 10MHz + BW 10MHz, Multi 2 carrier(Contiguous), 4TX, Bottom**


QPSK




16QAM



64QAM



256QAM





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (463) / (2957)  
 Pages

**Band 66, BW 10MHz + BW 10MHz, Multi 2 carrier(Contiguous), 4TX, Top**



QPSK

16QAM



64QAM

256QAM







**ANT 2**

**Band 66, BW 10MHz + BW 10MHz, Multi 2 carrier(Contiguous), 4TX, Bottom**



QPSK

16QAM



64QAM

256QAM









**Band 66, BW 10MHz + BW 10MHz, Multi 2 carrier(Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM







**ANT 3**

**Band 66, BW 10MHz + BW 10MHz, Multi 2 carrier(Contiguous), 4TX, Bottom**


QPSK




16QAM



64QAM




256QAM






**Band 66, BW 10MHz + BW 10MHz, Multi 2 carrier(Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (468) / (2957)  
 Pages


**ANT 4**

**Band 66, BW 10MHz + BW 10MHz, Multi 2 carrier(Contiguous), 4TX, Bottom**


QPSK




16QAM



64QAM




256QAM






**Band 66, BW 10MHz + BW 10MHz, Multi 2 carrier(Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (470) / (2957)  
 Pages


**ANT 1**

**Band 66, BW 10MHz + BW 15MHz, Multi 2 carrier(Contiguous), 4TX, Bottom**


QPSK




16QAM



64QAM



256QAM








**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03329  
 Page (471) / (2957)  
 Pages

**Band 66, BW 10MHz + BW 15MHz, Multi 2 carrier(Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501



Report No.:  
 CTK-2018-03329  
 Page (472) / (2957)  
 Pages

**ANT 2**

**Band 66, BW 10MHz + BW 15MHz, Multi 2 carrier(Contiguous), 4TX, Bottom**



QPSK

16QAM



64QAM


256QAM






**Band 66, BW 10MHz + BW 15MHz, Multi 2 carrier(Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (474) / (2957)  
 Pages


**ANT 3**

**Band 66, BW 10MHz + BW 15MHz, Multi 2 carrier(Contiguous), 4TX, Bottom**


QPSK




16QAM



64QAM




256QAM






**Band 66, BW 10MHz + BW 15MHz, Multi 2 carrier(Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501



Report No.:  
 CTK-2018-03329  
 Page (476) / (2957)  
 Pages

**ANT 4**

**Band 66, BW 10MHz + BW 15MHz, Multi 2 carrier(Contiguous), 4TX, Bottom**



QPSK

16QAM



64QAM

256QAM








**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03329  
 Page (477) / (2957)  
 Pages

**Band 66, BW 10MHz + BW 15MHz, Multi 2 carrier(Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM







**ANT 1**

**Band 66, BW 10MHz + BW 20MHz, Multi 2 carrier(Contiguous), 4TX, Bottom**



QPSK

16QAM



64QAM


256QAM






**Band 66, BW 10MHz + BW 20MHz, Multi 2 carrier(Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM







**ANT 2**

**Band 66, BW 10MHz + BW 20MHz, Multi 2 carrier(Contiguous), 4TX, Bottom**


QPSK




16QAM



64QAM



256QAM






**Band 66, BW 10MHz + BW 20MHz, Multi 2 carrier(Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM







**ANT 3**

**Band 66, BW 10MHz + BW 20MHz, Multi 2 carrier(Contiguous), 4TX, Bottom**


QPSK




16QAM



64QAM



256QAM









**Band 66, BW 10MHz + BW 20MHz, Multi 2 carrier(Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM







**ANT 4**

**Band 66, BW 10MHz + BW 20MHz, Multi 2 carrier(Contiguous), 4TX, Bottom**


QPSK




16QAM



64QAM




256QAM





**Band 66, BW 10MHz + BW 20MHz, Multi 2 carrier(Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (486) / (2957)  
 Pages


**ANT 1**

**Band 66, BW 5MHz + BW 15MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Bottom**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (487) / (2957)  
 Pages

**Band 66, BW 5MHz + BW 15MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Middle**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03329  
 Page (488) / (2957)  
 Pages

**Band 66, BW 5MHz + BW 15MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM








**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (489) / (2957)  
 Pages


**ANT 2**

**Band 66, BW 5MHz + BW 15MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Bottom**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03329  
 Page (490) / (2957)  
 Pages

**Band 66, BW 5MHz + BW 15MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Middle**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03329  
 Page (491) / (2957)  
 Pages

**Band 66, BW 5MHz + BW 15MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (492) / (2957)  
 Pages


**ANT 3**

**Band 66, BW 5MHz + BW 15MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Bottom**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03329  
 Page (493) / (2957)  
 Pages

**Band 66, BW 5MHz + BW 15MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Middle**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (494) / (2957)  
 Pages

**Band 66, BW 5MHz + BW 15MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM







**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03329  
 Page (495) / (2957)  
 Pages

**ANT 4**

**Band 66, BW 5MHz + BW 15MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Bottom**



QPSK

16QAM



64QAM

256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03329  
 Page (496) / (2957)  
 Pages

**Band 66, BW 5MHz + BW 15MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Middle**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03329  
 Page (497) / (2957)  
 Pages

**Band 66, BW 5MHz + BW 15MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM







**ANT 1**

**Band 66, BW 10MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Bottom**


**QPSK**




**16QAM**



**64QAM**



**256QAM**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03329  
 Page (499) / (2957)  
 Pages

**Band 66, BW 10MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Middle**


QPSK



16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03329  
 Page (500) / (2957)  
 Pages

**Band 66, BW 10MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Top**

QPSK



16QAM



64QAM



256QAM








**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (501) / (2957)  
 Pages


**ANT 2**

**Band 66, BW 10MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Bottom**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03329  
 Page (502) / (2957)  
 Pages

**Band 66, BW 10MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Middle**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03329  
 Page (503) / (2957)  
 Pages

**Band 66, BW 10MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM







**ANT 3**

**Band 66, BW 10MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Bottom**


**QPSK**




**16QAM**



**64QAM**



**256QAM**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03329  
 Page (505) / (2957)  
 Pages

**Band 66, BW 10MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Middle**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (506) / (2957)  
 Pages

**Band 66, BW 10MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM








**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (507) / (2957)  
 Pages


**ANT 4**

**Band 66, BW 10MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Bottom**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03329  
 Page (508) / (2957)  
 Pages

**Band 66, BW 10MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Middle**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03329  
 Page (509) / (2957)  
 Pages

**Band 66, BW 10MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (510) / (2957)  
 Pages


**ANT 1**

**Band 66, BW 5MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Bottom**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03329  
 Page (511) / (2957)  
 Pages

**Band 66, BW 5MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Middle**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03329  
 Page (512) / (2957)  
 Pages

**Band 66, BW 5MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM







**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501



Report No.:  
 CTK-2018-03329  
 Page (513) / (2957)  
 Pages

**ANT 2**

**Band 66, BW 5MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Bottom**



QPSK

16QAM



64QAM


256QAM






**Band 66, BW 5MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Middle**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03329  
 Page (515) / (2957)  
 Pages

**Band 66, BW 5MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501



Report No.:  
 CTK-2018-03329  
 Page (516) / (2957)  
 Pages

**ANT 3**

**Band 66, BW 5MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Bottom**



QPSK

16QAM



64QAM

256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03329  
 Page (517) / (2957)  
 Pages

**Band 66, BW 5MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Middle**


QPSK




16QAM



64QAM




256QAM






**Band 66, BW 5MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM








**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (519) / (2957)  
 Pages


**ANT 4**

**Band 66, BW 5MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Bottom**


QPSK




16QAM



64QAM




256QAM






**Band 66, BW 5MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Middle**


QPSK




16QAM



64QAM




256QAM






**Band 66, BW 5MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (522) / (2957)  
 Pages


**ANT 1**

**Band 66, BW 5MHz + BW 10MHz + BW 5MHz, Multi 3 carrier(Contiguous), 4TX, Bottom**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (523) / (2957)  
 Pages

**Band 66, BW 5MHz + BW 10MHz + BW 5MHz, Multi 3 carrier(Contiguous), 4TX, Middle**


QPSK




16QAM



64QAM




256QAM






**Band 66, BW 5MHz + BW 10MHz + BW 5MHz, Multi 3 carrier(Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM








**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (525) / (2957)  
 Pages


**ANT 2**

**Band 66, BW 5MHz + BW 10MHz + BW 5MHz, Multi 3 carrier(Contiguous), 4TX, Bottom**


QPSK



16QAM



64QAM



256QAM

