




**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03329  
 Page (526) / (2957)  
 Pages

**Band 66, BW 5MHz + BW 10MHz + BW 5MHz, Multi 3 carrier(Contiguous), 4TX, Middle**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03329  
 Page (527) / (2957)  
 Pages

**Band 66, BW 5MHz + BW 10MHz + BW 5MHz, Multi 3 carrier(Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (528) / (2957)  
 Pages


**ANT 3**

**Band 66, BW 5MHz + BW 10MHz + BW 5MHz, Multi 3 carrier(Contiguous), 4TX, Bottom**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03329  
 Page (529) / (2957)  
 Pages

**Band 66, BW 5MHz + BW 10MHz + BW 5MHz, Multi 3 carrier(Contiguous), 4TX, Middle**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03329  
 Page (530) / (2957)  
 Pages

**Band 66, BW 5MHz + BW 10MHz + BW 5MHz, Multi 3 carrier(Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (531) / (2957)  
 Pages


**ANT 4**

**Band 66, BW 5MHz + BW 10MHz + BW 5MHz, Multi 3 carrier(Contiguous), 4TX, Bottom**


QPSK




16QAM



64QAM



256QAM








**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03329  
 Page (532) / (2957)  
 Pages

**Band 66, BW 5MHz + BW 10MHz + BW 5MHz, Multi 3 carrier(Contiguous), 4TX, Middle**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03329  
 Page (533) / (2957)  
 Pages

**Band 66, BW 5MHz + BW 10MHz + BW 5MHz, Multi 3 carrier(Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM







**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501



Report No.:  
 CTK-2018-03329  
 Page (534) / (2957)  
 Pages

**ANT 1**

**Band 66, BW 5MHz + BW 5MHz + BW 5MHz, Multi 3 carrier(Contiguous), 4TX, Bottom**



QPSK

16QAM



64QAM

256QAM





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (535) / (2957)  
 Pages

**Band 66, BW 5MHz + BW 5MHz + BW 5MHz, Multi 3 carrier(Contiguous), 4TX, Middle**

QPSK



16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03329  
 Page (536) / (2957)  
 Pages

**Band 66, BW 5MHz + BW 5MHz + BW 5MHz, Multi 3 carrier(Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM






**ANT 2**

**Band 66, BW 5MHz + BW 5MHz + BW 5MHz, Multi 3 carrier(Contiguous), 4TX, Bottom**


**QPSK**




**16QAM**



**64QAM**



**256QAM**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (538) / (2957)  
 Pages

**Band 66, BW 5MHz + BW 5MHz + BW 5MHz, Multi 3 carrier(Contiguous), 4TX, Middle**



QPSK

16QAM



64QAM

256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03329  
 Page (539) / (2957)  
 Pages

**Band 66, BW 5MHz + BW 5MHz + BW 5MHz, Multi 3 carrier(Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM








**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (540) / (2957)  
 Pages

**ANT 3**

**Band 66, BW 5MHz + BW 5MHz + BW 5MHz, Multi 3 carrier(Contiguous), 4TX, Bottom**


QPSK




16QAM



64QAM



256QAM





**Band 66, BW 5MHz + BW 5MHz + BW 5MHz, Multi 3 carrier(Contiguous), 4TX, Middle**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (542) / (2957)  
 Pages

**Band 66, BW 5MHz + BW 5MHz + BW 5MHz, Multi 3 carrier(Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (543) / (2957)  
 Pages


**ANT 4**

**Band 66, BW 5MHz + BW 5MHz + BW 5MHz, Multi 3 carrier(Contiguous), 4TX, Bottom**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (544) / (2957)  
 Pages

**Band 66, BW 5MHz + BW 5MHz + BW 5MHz, Multi 3 carrier(Contiguous), 4TX, Middle**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (545) / (2957)  
 Pages

**Band 66, BW 5MHz + BW 5MHz + BW 5MHz, Multi 3 carrier(Contiguous), 4TX, Top**


QPSK



16QAM



64QAM



256QAM







**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501



Report No.:  
 CTK-2018-03329  
 Page (546) / (2957)  
 Pages

**ANT 1**

**Band 66, BW 20MHz + BW 10MHz, Multi 2 carrier(Non-Contiguous), 4TX, Bottom**



QPSK

16QAM



64QAM

256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03329  
 Page (547) / (2957)  
 Pages

**Band 66, BW 20MHz + BW 10MHz, Multi 2 carrier(Non-Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501



Report No.:  
 CTK-2018-03329  
 Page (548) / (2957)  
 Pages

**ANT 2**

**Band 66, BW 20MHz + BW 10MHz, Multi 2 carrier(Non-Contiguous), 4TX, Bottom**



QPSK

16QAM



64QAM

256QAM







**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (549) / (2957)  
 Pages

**Band 66, BW 20MHz + BW 10MHz, Multi 2 carrier(Non-Contiguous), 4TX, Top**



QPSK

16QAM



64QAM

256QAM





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501



Report No.:  
 CTK-2018-03329  
 Page (550) / (2957)  
 Pages

**ANT 3**

**Band 66, BW 20MHz + BW 10MHz, Multi 2 carrier(Non-Contiguous), 4TX, Bottom**



QPSK

16QAM



64QAM

256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03329  
 Page (551) / (2957)  
 Pages

**Band 66, BW 20MHz + BW 10MHz, Multi 2 carrier(Non-Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM







**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501



Report No.:  
 CTK-2018-03329  
 Page (552) / (2957)  
 Pages

**ANT 4**

**Band 66, BW 20MHz + BW 10MHz, Multi 2 carrier(Non-Contiguous), 4TX, Bottom**



QPSK

16QAM



64QAM


256QAM






**Band 66, BW 20MHz + BW 10MHz, Multi 2 carrier(Non-Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501



Report No.:  
 CTK-2018-03329  
 Page (554) / (2957)  
 Pages

**ANT 1**

**Band 66, BW 20MHz + BW 5MHz, Multi 2 carrier(Non-Contiguous), 4TX, Bottom**



QPSK

16QAM



64QAM

256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (555) / (2957)  
 Pages

**Band 66, BW 20MHz + BW 5MHz, Multi 2 carrier(Non-Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501



Report No.:  
 CTK-2018-03329  
 Page (556) / (2957)  
 Pages

**ANT 2**

**Band 66, BW 20MHz + BW 5MHz, Multi 2 carrier(Non-Contiguous), 4TX, Bottom**



QPSK

16QAM



64QAM

256QAM







**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (557) / (2957)  
 Pages

**Band 66, BW 20MHz + BW 5MHz, Multi 2 carrier(Non-Contiguous), 4TX, Top**



QPSK

16QAM



64QAM

256QAM









**ANT 3**

**Band 66, BW 20MHz + BW 5MHz, Multi 2 carrier(Non-Contiguous), 4TX, Bottom**


QPSK




16QAM



64QAM



256QAM







**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (559) / (2957)  
 Pages

**Band 66, BW 20MHz + BW 5MHz, Multi 2 carrier(Non-Contiguous), 4TX, Top**



QPSK

16QAM



64QAM

256QAM





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501



Report No.:  
 CTK-2018-03329  
 Page (560) / (2957)  
 Pages

**ANT 4**

**Band 66, BW 20MHz + BW 5MHz, Multi 2 carrier(Non-Contiguous), 4TX, Bottom**



QPSK

16QAM



64QAM


256QAM






**Band 66, BW 20MHz + BW 5MHz, Multi 2 carrier(Non-Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM







**ANT 1**

**Band 66, BW 15MHz + BW 10MHz, Multi 2 carrier(Non-Contiguous), 4TX, Bottom**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (563) / (2957)  
 Pages

**Band 66, BW 15MHz + BW 10MHz, Multi 2 carrier(Non-Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM








**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (564) / (2957)  
 Pages


**ANT 2**

**Band 66, BW 15MHz + BW 10MHz, Multi 2 carrier(Non-Contiguous), 4TX, Bottom**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03329  
 Page (565) / (2957)  
 Pages

**Band 66, BW 15MHz + BW 10MHz, Multi 2 carrier(Non-Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM







**ANT 3**

**Band 66, BW 15MHz + BW 10MHz, Multi 2 carrier(Non-Contiguous), 4TX, Bottom**


QPSK




16QAM



64QAM



256QAM





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (567) / (2957)  
 Pages

**Band 66, BW 15MHz + BW 10MHz, Multi 2 carrier(Non-Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM







**ANT 4**

**Band 66, BW 15MHz + BW 10MHz, Multi 2 carrier(Non-Contiguous), 4TX, Bottom**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (569) / (2957)  
 Pages

**Band 66, BW 15MHz + BW 10MHz, Multi 2 carrier(Non-Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM









**ANT 1**

**Band 66, BW 15MHz + BW 5MHz, Multi 2 carrier(Non-Contiguous), 4TX, Bottom**


QPSK




16QAM



64QAM



256QAM





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (571) / (2957)  
 Pages

**Band 66, BW 15MHz + BW 5MHz, Multi 2 carrier(Non-Contiguous), 4TX, Top**



QPSK

16QAM



64QAM

256QAM







**ANT 2**

**Band 66, BW 15MHz + BW 5MHz, Multi 2 carrier(Non-Contiguous), 4TX, Bottom**


**QPSK**




**16QAM**



**64QAM**



**256QAM**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (573) / (2957)  
 Pages

**Band 66, BW 15MHz + BW 5MHz, Multi 2 carrier(Non-Contiguous), 4TX, Top**



QPSK

16QAM



64QAM

256QAM







**ANT 3**

**Band 66, BW 15MHz + BW 5MHz, Multi 2 carrier(Non-Contiguous), 4TX, Bottom**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03329  
 Page (575) / (2957)  
 Pages

**Band 66, BW 15MHz + BW 5MHz, Multi 2 carrier(Non-Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM









**ANT 4**

**Band 66, BW 15MHz + BW 5MHz, Multi 2 carrier(Non-Contiguous), 4TX, Bottom**


QPSK




16QAM



64QAM



256QAM







**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (577) / (2957)  
 Pages

**Band 66, BW 15MHz + BW 5MHz, Multi 2 carrier(Non-Contiguous), 4TX, Top**



QPSK

16QAM



64QAM

256QAM





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501



Report No.:  
 CTK-2018-03329  
 Page (578) / (2957)  
 Pages

**ANT 1**

**Band 66, BW 10MHz + BW 10MHz, Multi 2 carrier(Non-Contiguous), 4TX, Bottom**



QPSK

16QAM



64QAM

256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (579) / (2957)  
 Pages

**Band 66, BW 10MHz + BW 10MHz, Multi 2 carrier(Non-Contiguous), 4TX, Top**



QPSK

16QAM



64QAM

256QAM





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03329  
 Page (580) / (2957)  
 Pages

**ANT 2**

**Band 66, BW 10MHz + BW 10MHz, Multi 2 carrier(Non-Contiguous), 4TX, Bottom**



QPSK

16QAM



64QAM

256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03329  
 Page (581) / (2957)  
 Pages

**Band 66, BW 10MHz + BW 10MHz, Multi 2 carrier(Non-Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM







**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501



Report No.:  
 CTK-2018-03329  
 Page (582) / (2957)  
 Pages

**ANT 3**

**Band 66, BW 10MHz + BW 10MHz, Multi 2 carrier(Non-Contiguous), 4TX, Bottom**



QPSK

16QAM



64QAM

256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03329  
 Page (583) / (2957)  
 Pages

**Band 66, BW 10MHz + BW 10MHz, Multi 2 carrier(Non-Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03329  
 Page (584) / (2957)  
 Pages

**ANT 4**

**Band 66, BW 10MHz + BW 10MHz, Multi 2 carrier(Non-Contiguous), 4TX, Bottom**



QPSK

16QAM



64QAM

256QAM







**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (585) / (2957)  
 Pages

**Band 66, BW 10MHz + BW 10MHz, Multi 2 carrier(Non-Contiguous), 4TX, Top**



QPSK

16QAM



64QAM

256QAM







**ANT 1**

**Band 66, BW 10MHz + BW 5MHz, Multi 2 carrier(Non-Contiguous), 4TX, Bottom**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03329  
 Page (587) / (2957)  
 Pages

**Band 66, BW 10MHz + BW 5MHz, Multi 2 carrier(Non-Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM









**ANT 2**

**Band 66, BW 10MHz + BW 5MHz, Multi 2 carrier(Non-Contiguous), 4TX, Bottom**



QPSK

16QAM



64QAM

256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03329  
 Page (589) / (2957)  
 Pages

**Band 66, BW 10MHz + BW 5MHz, Multi 2 carrier(Non-Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM






**ANT 3**

**Band 66, BW 10MHz + BW 5MHz, Multi 2 carrier(Non-Contiguous), 4TX, Bottom**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03329  
 Page (591) / (2957)  
 Pages

**Band 66, BW 10MHz + BW 5MHz, Multi 2 carrier(Non-Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM







**ANT 4**

**Band 66, BW 10MHz + BW 5MHz, Multi 2 carrier(Non-Contiguous), 4TX, Bottom**


QPSK




16QAM



64QAM



256QAM





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (593) / (2957)  
 Pages

**Band 66, BW 10MHz + BW 5MHz, Multi 2 carrier(Non-Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM







**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501



Report No.:  
 CTK-2018-03329  
 Page (594) / (2957)  
 Pages

**ANT 1**

**Band 66, BW 5MHz + BW 5MHz, Multi 2 carrier(Non-Contiguous), 4TX, Bottom**



QPSK

16QAM



64QAM

256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (595) / (2957)  
 Pages

**Band 66, BW 5MHz + BW 5MHz, Multi 2 carrier(Non-Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (596) / (2957)  
 Pages


**ANT 2**

**Band 66, BW 5MHz + BW 5MHz, Multi 2 carrier(Non-Contiguous), 4TX, Bottom**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03329  
 Page (597) / (2957)  
 Pages

**Band 66, BW 5MHz + BW 5MHz, Multi 2 carrier(Non-Contiguous), 4TX, Top**


QPSK



16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (598) / (2957)  
 Pages


**ANT 3**

**Band 66, BW 5MHz + BW 5MHz, Multi 2 carrier(Non-Contiguous), 4TX, Bottom**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03329  
 Page (599) / (2957)  
 Pages

**Band 66, BW 5MHz + BW 5MHz, Multi 2 carrier(Non-Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM








**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (600) / (2957)  
 Pages


**ANT 4**

**Band 66, BW 5MHz + BW 5MHz, Multi 2 carrier(Non-Contiguous), 4TX, Bottom**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03329  
 Page (601) / (2957)  
 Pages

**Band 66, BW 5MHz + BW 5MHz, Multi 2 carrier(Non-Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM







**ANT 1**

**Band 66, BW 10MHz + BW 15MHz + BW 5MHz, Multi 3 carrier(Non-Contiguous), 4TX, Bottom**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (603) / (2957)  
 Pages

**Band 66, BW 10MHz + BW 15MHz + BW 5MHz, Multi 3 carrier(Non-Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (604) / (2957)  
 Pages


**ANT 2**

**Band 66, BW 10MHz + BW 15MHz + BW 5MHz, Multi 3 carrier(Non-Contiguous), 4TX, Bottom**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (605) / (2957)  
 Pages

**Band 66, BW 10MHz + BW 15MHz + BW 5MHz, Multi 3 carrier(Non-Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM








**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (606) / (2957)  
 Pages


**ANT 3**

**Band 66, BW 10MHz + BW 15MHz + BW 5MHz, Multi 3 carrier(Non-Contiguous), 4TX, Bottom**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (607) / (2957)  
 Pages

**Band 66, BW 10MHz + BW 15MHz + BW 5MHz, Multi 3 carrier(Non-Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM







**ANT 4**

**Band 66, BW 10MHz + BW 15MHz + BW 5MHz, Multi 3 carrier(Non-Contiguous), 4TX, Bottom**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (609) / (2957)  
 Pages

**Band 66, BW 10MHz + BW 15MHz + BW 5MHz, Multi 3 carrier(Non-Contiguous), 4TX, Top**



QPSK

16QAM



64QAM

256QAM






**ANT 1**

**Band 66, BW 10MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Non-Contiguous), 4TX, Bottom**

QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03329  
 Page (611) / (2957)  
 Pages

**Band 66, BW 10MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Non-Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM









**ANT 2**

**Band 66, BW 10MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Non-Contiguous), 4TX, Bottom**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03329  
 Page (613) / (2957)  
 Pages

**Band 66, BW 10MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Non-Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM





**ANT 3**

**Band 66, BW 10MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Non-Contiguous), 4TX, Bottom**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03329  
 Page (615) / (2957)  
 Pages

**Band 66, BW 10MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Non-Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM





**ANT 4**

**Band 66, BW 10MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Non-Contiguous), 4TX, Bottom**

QPSK	16QAM
<p>Center Freq 2.12000000 GHz</p> <p>Center Freq 2.12000000 GHz</p> <p>Occupied Bandwidth <b>18.754 MHz</b></p> <p>Total Power 42.1 dBm</p> <p>Transmit Freq Error 19.701 kHz</p> <p>x dB Bandwidth 19.29 MHz</p>	<p>Center Freq 2.12000000 GHz</p> <p>Center Freq 2.12000000 GHz</p> <p>Occupied Bandwidth <b>18.763 MHz</b></p> <p>Total Power 41.7 dBm</p> <p>Transmit Freq Error 32.637 kHz</p> <p>x dB Bandwidth 19.31 MHz</p>
64QAM	256QAM
<p>Center Freq 2.12000000 GHz</p> <p>Center Freq 2.12000000 GHz</p> <p>Occupied Bandwidth <b>18.788 MHz</b></p> <p>Total Power 42.0 dBm</p> <p>Transmit Freq Error 25.789 kHz</p> <p>x dB Bandwidth 19.33 MHz</p>	<p>Center Freq 2.12000000 GHz</p> <p>Center Freq 2.12000000 GHz</p> <p>Occupied Bandwidth <b>18.800 MHz</b></p> <p>Total Power 42.0 dBm</p> <p>Transmit Freq Error 21.963 kHz</p> <p>x dB Bandwidth 19.34 MHz</p>




**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (617) / (2957)  
 Pages

**Band 66, BW 10MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Non-Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM







**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (618) / (2957)  
 Pages

**ANT 1**

**Band 66, BW 5MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Non-Contiguous), 4TX, Bottom**


QPSK




16QAM



64QAM



256QAM







**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (619) / (2957)  
 Pages

**Band 66, BW 5MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Non-Contiguous), 4TX, Top**



QPSK

16QAM



64QAM

256QAM







**ANT 2**

**Band 66, BW 5MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Non-Contiguous), 4TX, Bottom**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03329  
 Page (621) / (2957)  
 Pages

**Band 66, BW 5MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Non-Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (622) / (2957)  
 Pages


**ANT 3**

**Band 66, BW 5MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Non-Contiguous), 4TX, Bottom**


QPSK




16QAM



64QAM



256QAM







**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (623) / (2957)  
 Pages

**Band 66, BW 5MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Non-Contiguous), 4TX, Top**



QPSK

16QAM



64QAM

256QAM








**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (624) / (2957)  
 Pages


**ANT 4**

**Band 66, BW 5MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Non-Contiguous), 4TX, Bottom**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03329  
 Page (625) / (2957)  
 Pages

**Band 66, BW 5MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Non-Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (626) / (2957)  
 Pages


**ANT 1**

**Band 66, BW 5MHz + BW 10MHz + BW 5MHz, Multi 3 carrier(Non-Contiguous), 4TX, Bottom**


QPSK




16QAM



64QAM



256QAM







**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (627) / (2957)  
 Pages

**Band 66, BW 5MHz + BW 10MHz + BW 5MHz, Multi 3 carrier(Non-Contiguous), 4TX, Top**



QPSK

16QAM



64QAM

256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (628) / (2957)  
 Pages


**ANT 2**

**Band 66, BW 5MHz + BW 10MHz + BW 5MHz, Multi 3 carrier(Non-Contiguous), 4TX, Bottom**


QPSK




16QAM



64QAM



256QAM







**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (629) / (2957)  
 Pages

**Band 66, BW 5MHz + BW 10MHz + BW 5MHz, Multi 3 carrier(Non-Contiguous), 4TX, Top**



QPSK

16QAM



64QAM

256QAM








**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03329  
 Page (630) / (2957)  
 Pages


**ANT 3**

**Band 66, BW 5MHz + BW 10MHz + BW 5MHz, Multi 3 carrier(Non-Contiguous), 4TX, Bottom**


QPSK



16QAM



64QAM



256QAM

