




CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2731) / (2957)
Pages

64QAM



256QAM







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2732) / (2957)
Pages

ANT 1
Band 66, BW 10MHz, Single 1 carrier, 4TX

QPSK



16QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (2733) / (2957)
 Pages

64QAM





256QAM





ANT 2
Band 66, BW 10MHz, Single 1 carrier, 4TX

QPSK



16QAM








CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2735) / (2957)
Pages

64QAM




256QAM






ANT 3
Band 66, BW 10MHz, Single 1 carrier, 4TX

QPSK



16QAM






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2737) / (2957)
Pages

64QAM




256QAM





ANT 4
Band 66, BW 10MHz, Single 1 carrier, 4TX

QPSK



16QAM






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2739) / (2957)
Pages

64QAM



256QAM






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2017-01618-1
Page (2740) / (2957)
Pages

ANT 1
Band 66, BW 15MHz, Single 1 carrier, 4TX

QPSK



16QAM







CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (2741) / (2957)
 Pages

64QAM



256QAM







CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2017-01618-1
 Page (2742) / (2957)
 Pages

ANT 2
Band 66, BW 15MHz, Single 1 carrier, 4TX

QPSK



16QAM








CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2743) / (2957)
Pages

64QAM



256QAM







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2017-01618-1
Page (2744) / (2957)
Pages

ANT 3
Band 66, BW 15MHz, Single 1 carrier, 4TX

QPSK



16QAM







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2745) / (2957)
Pages

64QAM



256QAM







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501


Report No.:
CTK-2017-01618-1
Page (2746) / (2957)
Pages

ANT 4
Band 66, BW 15MHz, Single 1 carrier, 4TX

QPSK



16QAM








CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (2747) / (2957)
 Pages

64QAM



256QAM







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2017-01618-1
Page (2748) / (2957)
Pages

ANT 1
Band 66, BW 20MHz, Single 1 carrier, 4TX

QPSK



16QAM








CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2749) / (2957)
Pages

64QAM





256QAM







ANT 2
Band 66, BW 20MHz, Single 1 carrier, 4TX

QPSK



16QAM







CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (2751) / (2957)
 Pages

64QAM





256QAM






ANT 3
Band 66, BW 20MHz, Single 1 carrier, 4TX

QPSK



16QAM








CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2753) / (2957)
Pages

64QAM



256QAM






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2017-01618-1
Page (2754) / (2957)
Pages

ANT 4
Band 66, BW 20MHz, Single 1 carrier, 4TX

QPSK



16QAM








CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2755) / (2957)
Pages

64QAM



256QAM







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2756) / (2957)
Pages


ANT 1

Band 66, BW 5MHz + BW 5MHz, Multi 2 carrier(Contiguous), 4TX

QPSK



16QAM







CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (2757) / (2957)
 Pages

64QAM



256QAM





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2017-01618-1
Page (2758) / (2957)
Pages

ANT 2
Band 66, BW 5MHz + BW 5MHz, Multi 2 carrier(Contiguous), 4TX

QPSK



16QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (2759) / (2957)
 Pages

64QAM



256QAM





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2760) / (2957)
Pages



ANT 3

Band 66, BW 5MHz + BW 5MHz, Multi 2 carrier(Contiguous), 4TX

QPSK



16QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (2761) / (2957)
 Pages

64QAM





256QAM






ANT 4
Band 66, BW 5MHz + BW 5MHz, Multi 2 carrier(Contiguous), 4TX

QPSK



16QAM





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (2763) / (2957)
 Pages

64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501



Report No.:
 CTK-2017-01618-1
 Page (2764) / (2957)
 Pages

ANT 1
Band 66, BW 5MHz + BW 10MHz, Multi 2 carrier(Contiguous), 4TX

QPSK



16QAM








CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (2765) / (2957)
 Pages

64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (2766) / (2957)
 Pages

ANT 2
Band 66, BW 5MHz + BW 10MHz, Multi 2 carrier(Contiguous), 4TX

QPSK



16QAM





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (2767) / (2957)
 Pages

64QAM



256QAM





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2768) / (2957)
Pages

ANT 3
Band 66, BW 5MHz + BW 10MHz, Multi 2 carrier(Contiguous), 4TX

QPSK



16QAM







CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (2769) / (2957)
 Pages

64QAM




256QAM






ANT 4
Band 66, BW 5MHz + BW 10MHz, Multi 2 carrier(Contiguous), 4TX

QPSK




16QAM





64QAM



256QAM








ANT 1

Band 66, BW 5MHz + BW 15MHz, Multi 2 carrier(Contiguous), 4TX

QPSK



16QAM








CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2773) / (2957)
Pages

64QAM




256QAM






ANT 2
Band 66, BW 5MHz + BW 15MHz, Multi 2 carrier(Contiguous), 4TX

QPSK



16QAM








CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2775) / (2957)
Pages

64QAM



256QAM






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2776) / (2957)
Pages


ANT 3

Band 66, BW 5MHz + BW 15MHz, Multi 2 carrier(Contiguous), 4TX

QPSK



16QAM







CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (2777) / (2957)
 Pages

64QAM




256QAM




ANT 4
Band 66, BW 5MHz + BW 15MHz, Multi 2 carrier(Contiguous), 4TX

QPSK



16QAM








CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2779) / (2957)
Pages

64QAM



256QAM






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2780) / (2957)
Pages


ANT 1

Band 66, BW 5MHz + BW 20MHz, Multi 2 carrier(Contiguous), 4TX

QPSK



16QAM








CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (2781) / (2957)
 Pages

64QAM





256QAM






ANT 2
Band 66, BW 5MHz + BW 20MHz, Multi 2 carrier(Contiguous), 4TX

QPSK





16QAM







64QAM



256QAM






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2784) / (2957)
Pages


ANT 3

Band 66, BW 5MHz + BW 20MHz, Multi 2 carrier(Contiguous), 4TX

QPSK



16QAM







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2785) / (2957)
Pages

64QAM




256QAM






ANT 4
Band 66, BW 5MHz + BW 20MHz, Multi 2 carrier(Contiguous), 4TX

QPSK



16QAM







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2787) / (2957)
Pages

64QAM



256QAM






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2788) / (2957)
Pages


ANT 1

Band 66, BW 10MHz + BW 10MHz, Multi 2 carrier(Contiguous), 4TX

QPSK



16QAM







CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (2789) / (2957)
 Pages

64QAM



256QAM







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2790) / (2957)
Pages

ANT 2
Band 66, BW 10MHz + BW 10MHz, Multi 2 carrier(Contiguous), 4TX

QPSK



16QAM







CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (2791) / (2957)
 Pages

64QAM



256QAM






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2792) / (2957)
Pages



ANT 3

Band 66, BW 10MHz + BW 10MHz, Multi 2 carrier(Contiguous), 4TX

QPSK



16QAM







CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (2793) / (2957)
 Pages

64QAM





256QAM





ANT 4
Band 66, BW 10MHz + BW 10MHz, Multi 2 carrier(Contiguous), 4TX

QPSK



16QAM









CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2795) / (2957)
Pages

64QAM



256QAM







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2796) / (2957)
Pages


ANT 1

Band 66, BW 10MHz + BW 15MHz, Multi 2 carrier(Contiguous), 4TX

QPSK





16QAM






64QAM



256QAM







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501


Report No.:
CTK-2017-01618-1
Page (2798) / (2957)
Pages

ANT 2
Band 66, BW 10MHz + BW 15MHz, Multi 2 carrier(Contiguous), 4TX

QPSK



16QAM







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2799) / (2957)
Pages

64QAM



256QAM






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2800) / (2957)
Pages



ANT 3

Band 66, BW 10MHz + BW 15MHz, Multi 2 carrier(Contiguous), 4TX

QPSK



16QAM








CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (2801) / (2957)
 Pages

64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501



Report No.:
 CTK-2017-01618-1
 Page (2802) / (2957)
 Pages

ANT 4
Band 66, BW 10MHz + BW 15MHz, Multi 2 carrier(Contiguous), 4TX

QPSK



16QAM








CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (2803) / (2957)
 Pages

64QAM



256QAM







CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (2804) / (2957)
 Pages


ANT 1

Band 66, BW 10MHz + BW 20MHz, Multi 2 carrier(Contiguous), 4TX

QPSK



16QAM







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2805) / (2957)
Pages

64QAM



256QAM







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501


Report No.:
CTK-2017-01618-1
Page (2806) / (2957)
Pages

ANT 2
Band 66, BW 10MHz + BW 20MHz, Multi 2 carrier(Contiguous), 4TX

QPSK



16QAM








CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (2807) / (2957)
 Pages

64QAM



256QAM






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2808) / (2957)
Pages


ANT 3

Band 66, BW 10MHz + BW 20MHz, Multi 2 carrier(Contiguous), 4TX

QPSK



16QAM








CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2809) / (2957)
Pages

64QAM




256QAM






ANT 4
Band 66, BW 10MHz + BW 20MHz, Multi 2 carrier(Contiguous), 4TX

QPSK



16QAM









CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (2811) / (2957)
 Pages

64QAM



256QAM






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2812) / (2957)
Pages



ANT 1

Band 66, BW 5MHz + BW 15MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX

QPSK



16QAM








CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2813) / (2957)
Pages

64QAM



256QAM






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2814) / (2957)
Pages

ANT 2
Band 66, BW 5MHz + BW 15MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX

QPSK



16QAM






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2815) / (2957)
Pages

64QAM



256QAM






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2816) / (2957)
Pages


ANT 3

Band 66, BW 5MHz + BW 15MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX

QPSK



16QAM





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2817) / (2957)
Pages

64QAM




256QAM






ANT 4
Band 66, BW 5MHz + BW 15MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX

QPSK



16QAM







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2819) / (2957)
Pages

64QAM



256QAM






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2820) / (2957)
Pages



ANT 1

Band 66, BW 10MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX

QPSK



16QAM









CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2821) / (2957)
Pages

64QAM



256QAM







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501


Report No.:
CTK-2017-01618-1
Page (2822) / (2957)
Pages

ANT 2
Band 66, BW 10MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX

QPSK



16QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (2823) / (2957)
 Pages

64QAM



256QAM








ANT 3

Band 66, BW 10MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX

QPSK



16QAM







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2825) / (2957)
Pages

64QAM



256QAM







CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2017-01618-1
 Page (2826) / (2957)
 Pages

ANT 4
Band 66, BW 10MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX

QPSK



16QAM








CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2827) / (2957)
Pages

64QAM



256QAM







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2828) / (2957)
Pages


ANT 1

Band 66, BW 5MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX

QPSK



16QAM









CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2829) / (2957)
Pages

64QAM





256QAM







ANT 2
Band 66, BW 5MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX

QPSK



16QAM








CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (2831) / (2957)
 Pages

64QAM



256QAM






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2832) / (2957)
Pages

ANT 3

Band 66, BW 5MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX

QPSK



16QAM







CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (2833) / (2957)
 Pages

64QAM




256QAM






ANT 4
Band 66, BW 5MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Contiguous), 4TX

QPSK



16QAM







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2835) / (2957)
Pages

64QAM



256QAM

