




CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2836) / (2957)
Pages



ANT 1

Band 66, BW 5MHz + BW 10MHz + BW 5MHz, Multi 3 carrier(Contiguous), 4TX

QPSK



16QAM









CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (2837) / (2957)
 Pages

64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2017-01618-1
 Page (2838) / (2957)
 Pages

ANT 2
Band 66, BW 5MHz + BW 10MHz + BW 5MHz, Multi 3 carrier(Contiguous), 4TX

QPSK




16QAM







64QAM



256QAM







ANT 3

Band 66, BW 5MHz + BW 10MHz + BW 5MHz, Multi 3 carrier(Contiguous), 4TX

QPSK




16QAM





64QAM



256QAM







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2842) / (2957)
Pages

ANT 4

Band 66, BW 5MHz + BW 10MHz + BW 5MHz, Multi 3 carrier(Contiguous), 4TX

QPSK



16QAM








CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (2843) / (2957)
 Pages

64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (2844) / (2957)
 Pages


ANT 1

Band 66, BW 5MHz + BW 5MHz + BW 5MHz, Multi 3 carrier(Contiguous), 4TX

QPSK



16QAM







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2845) / (2957)
Pages

64QAM



256QAM







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2846) / (2957)
Pages

ANT 2

Band 66, BW 5MHz + BW 5MHz + BW 5MHz, Multi 3 carrier(Contiguous), 4TX

QPSK



16QAM







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2847) / (2957)
Pages

64QAM



256QAM






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2848) / (2957)
Pages


ANT 3

Band 66, BW 5MHz + BW 5MHz + BW 5MHz, Multi 3 carrier(Contiguous), 4TX

QPSK



16QAM







CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (2849) / (2957)
 Pages

64QAM



256QAM







ANT 4

Band 66, BW 5MHz + BW 5MHz + BW 5MHz, Multi 3 carrier(Contiguous), 4TX

QPSK





16QAM






64QAM



256QAM






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2852) / (2957)
Pages


ANT 1

Band 66, BW 20MHz + BW 10MHz, Multi 2 carrier(Non-contiguous), 4TX

QPSK



16QAM







CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (2853) / (2957)
 Pages

64QAM





256QAM






ANT 2
Band 66, BW 20MHz + BW 10MHz, Multi 2 carrier(Non-contiguous), 4TX

QPSK



16QAM







CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (2855) / (2957)
 Pages

64QAM



256QAM






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2856) / (2957)
Pages

ANT 3

Band 66, BW 20MHz + BW 10MHz, Multi 2 carrier(Non-contiguous), 4TX

QPSK



16QAM







CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (2857) / (2957)
 Pages

64QAM



256QAM








ANT 4

Band 66, BW 20MHz + BW 10MHz, Multi 2 carrier(Non-contiguous), 4TX

QPSK



16QAM








CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2859) / (2957)
Pages

64QAM



256QAM






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2860) / (2957)
Pages



ANT 1

Band 66, BW 20MHz + BW 5MHz, Multi 2 carrier(Non-contiguous), 4TX

QPSK



16QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (2861) / (2957)
 Pages

64QAM



256QAM







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501


Report No.:
CTK-2017-01618-1
Page (2862) / (2957)
Pages

ANT 2
Band 66, BW 20MHz + BW 5MHz, Multi 2 carrier(Non-contiguous), 4TX

QPSK



16QAM







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2863) / (2957)
Pages

64QAM



256QAM






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2864) / (2957)
Pages



ANT 3

Band 66, BW 20MHz + BW 5MHz, Multi 2 carrier(Non-contiguous), 4TX

QPSK



16QAM








CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2865) / (2957)
Pages

64QAM





256QAM






ANT 4
Band 66, BW 20MHz + BW 5MHz, Multi 2 carrier(Non-contiguous), 4TX

QPSK



16QAM







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2867) / (2957)
Pages

64QAM



256QAM





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2868) / (2957)
Pages


ANT 1

Band 66, BW 15MHz + BW 10MHz, Multi 2 carrier(Non-contiguous), 4TX

QPSK



16QAM







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2869) / (2957)
Pages

64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2017-01618-1
 Page (2870) / (2957)
 Pages

ANT 2
Band 66, BW 15MHz + BW 10MHz, Multi 2 carrier(Non-contiguous), 4TX

QPSK



16QAM







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2871) / (2957)
Pages

64QAM



256QAM







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2017-01618-1
Page (2872) / (2957)
Pages

ANT 3
Band 66, BW 15MHz + BW 10MHz, Multi 2 carrier(Non-contiguous), 4TX

QPSK



16QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (2873) / (2957)
 Pages

64QAM



256QAM






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501


Report No.:
CTK-2017-01618-1
Page (2874) / (2957)
Pages

ANT 4
Band 66, BW 15MHz + BW 10MHz, Multi 2 carrier(Non-contiguous), 4TX

QPSK



16QAM







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2875) / (2957)
Pages

64QAM



256QAM






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2876) / (2957)
Pages



ANT 1

Band 66, BW 15MHz + BW 5MHz, Multi 2 carrier(Non-contiguous), 4TX

QPSK



16QAM







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2877) / (2957)
Pages

64QAM





256QAM





ANT 2
Band 66, BW 15MHz + BW 5MHz, Multi 2 carrier(Non-contiguous), 4TX

QPSK



16QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (2879) / (2957)
 Pages

64QAM



256QAM






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2017-01618-1
Page (2880) / (2957)
Pages

ANT 3
Band 66, BW 15MHz + BW 5MHz, Multi 2 carrier(Non-contiguous), 4TX

QPSK



16QAM








CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2881) / (2957)
Pages

64QAM



256QAM







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2017-01618-1
Page (2882) / (2957)
Pages

ANT 4
Band 66, BW 15MHz + BW 5MHz, Multi 2 carrier(Non-contiguous), 4TX

QPSK



16QAM








CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2883) / (2957)
Pages

64QAM



256QAM







CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (2884) / (2957)
 Pages

ANT 1

Band 66, BW 10MHz + BW 10MHz, Multi 2 carrier(Non-contiguous), 4TX

QPSK



16QAM







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2885) / (2957)
Pages

64QAM





256QAM







ANT 2
Band 66, BW 10MHz + BW 10MHz, Multi 2 carrier(Non-contiguous), 4TX

QPSK



16QAM







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2887) / (2957)
Pages

64QAM



256QAM







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2888) / (2957)
Pages

ANT 3
Band 66, BW 10MHz + BW 10MHz, Multi 2 carrier(Non-contiguous), 4TX

QPSK



16QAM








CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (2889) / (2957)
 Pages

64QAM



256QAM






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501


Report No.:
CTK-2017-01618-1
Page (2890) / (2957)
Pages

ANT 4
Band 66, BW 10MHz + BW 10MHz, Multi 2 carrier(Non-contiguous), 4TX

QPSK



16QAM








CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2891) / (2957)
Pages

64QAM



256QAM






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2892) / (2957)
Pages



ANT 1

Band 66, BW 10MHz + BW 5MHz, Multi 2 carrier(Non-contiguous), 4TX

QPSK



16QAM







CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (2893) / (2957)
 Pages

64QAM





256QAM






ANT 2
Band 66, BW 10MHz + BW 5MHz, Multi 2 carrier(Non-contiguous), 4TX

QPSK



16QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (2895) / (2957)
 Pages

64QAM



256QAM





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501


Report No.:
CTK-2017-01618-1
Page (2896) / (2957)
Pages

ANT 3
Band 66, BW 10MHz + BW 5MHz, Multi 2 carrier(Non-contiguous), 4TX

QPSK



16QAM





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2897) / (2957)
Pages

64QAM



256QAM







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2898) / (2957)
Pages

ANT 4
Band 66, BW 10MHz + BW 5MHz, Multi 2 carrier(Non-contiguous), 4TX

QPSK



16QAM







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2899) / (2957)
Pages

64QAM



256QAM






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2900) / (2957)
Pages

ANT 1

Band 66, BW 5MHz + BW 5MHz, Multi 2 carrier(Non-contiguous), 4TX

QPSK



16QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (2901) / (2957)
 Pages

64QAM





256QAM






ANT 2
Band 66, BW 5MHz + BW 5MHz, Multi 2 carrier(Non-contiguous), 4TX

QPSK



16QAM







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2903) / (2957)
Pages

64QAM



256QAM







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2904) / (2957)
Pages

ANT 3

Band 66, BW 5MHz + BW 5MHz, Multi 2 carrier(Non-contiguous), 4TX

QPSK



16QAM






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2905) / (2957)
Pages

64QAM



256QAM





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2906) / (2957)
Pages

ANT 4

Band 66, BW 5MHz + BW 5MHz, Multi 2 carrier(Non-contiguous), 4TX

QPSK



16QAM







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2907) / (2957)
Pages

64QAM



256QAM






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2908) / (2957)
Pages


ANT 1

Band 66, BW 10MHz + BW 15MHz + BW 5MHz, Multi 3 carrier(Non-contiguous), 4TX

QPSK



16QAM







CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (2909) / (2957)
 Pages

64QAM



256QAM







CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2017-01618-1
 Page (2910) / (2957)
 Pages

ANT 2
Band 66, BW 10MHz + BW 15MHz + BW 5MHz, Multi 3 carrier(Non-contiguous), 4TX

QPSK



16QAM







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2911) / (2957)
Pages

64QAM



256QAM






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2912) / (2957)
Pages


ANT 3

Band 66, BW 10MHz + BW 15MHz + BW 5MHz, Multi 3 carrier(Non-contiguous), 4TX

QPSK



16QAM





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2913) / (2957)
Pages

64QAM



256QAM







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2914) / (2957)
Pages

ANT 4

Band 66, BW 10MHz + BW 15MHz + BW 5MHz, Multi 3 carrier(Non-contiguous), 4TX

QPSK



16QAM








CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (2915) / (2957)
 Pages

64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (2916) / (2957)
 Pages



ANT 1

Band 66, BW 10MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Non-contiguous), 4TX

QPSK



16QAM








CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2917) / (2957)
Pages

64QAM



256QAM







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2918) / (2957)
Pages

ANT 2

Band 66, BW 10MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Non-contiguous), 4TX

QPSK



16QAM








CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (2919) / (2957)
 Pages

64QAM



256QAM







CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (2920) / (2957)
 Pages


ANT 3

Band 66, BW 10MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Non-contiguous), 4TX

QPSK



16QAM







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2921) / (2957)
Pages

64QAM



256QAM








ANT 4

Band 66, BW 10MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Non-contiguous), 4TX

QPSK



16QAM








CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (2923) / (2957)
 Pages

64QAM



256QAM







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2924) / (2957)
Pages

ANT 1

Band 66, BW 5MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Non-contiguous), 4TX

QPSK



16QAM







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2925) / (2957)
Pages

64QAM



256QAM







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2926) / (2957)
Pages



ANT 2

Band 66, BW 5MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Non-contiguous), 4TX

QPSK



16QAM








CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2927) / (2957)
Pages

64QAM



256QAM





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2928) / (2957)
Pages

ANT 3

Band 66, BW 5MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Non-contiguous), 4TX

QPSK



16QAM







CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (2929) / (2957)
 Pages

64QAM



256QAM







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2930) / (2957)
Pages


ANT 4

Band 66, BW 5MHz + BW 10MHz + BW 10MHz, Multi 3 carrier(Non-contiguous), 4TX

QPSK



16QAM






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2931) / (2957)
Pages

64QAM



256QAM







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2932) / (2957)
Pages

ANT 1

Band 66, BW 5MHz + BW 10MHz + BW 5MHz, Multi 3 carrier(Non-contiguous), 4TX

QPSK



16QAM








CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2933) / (2957)
Pages

64QAM



256QAM







CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (2934) / (2957)
 Pages

ANT 2
Band 66, BW 5MHz + BW 10MHz + BW 5MHz, Multi 3 carrier(Non-contiguous), 4TX

QPSK



16QAM








CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (2935) / (2957)
 Pages

64QAM



256QAM






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2936) / (2957)
Pages


ANT 3

Band 66, BW 5MHz + BW 10MHz + BW 5MHz, Multi 3 carrier(Non-contiguous), 4TX

QPSK



16QAM







CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (2937) / (2957)
 Pages

64QAM



256QAM







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2938) / (2957)
Pages

ANT 4

Band 66, BW 5MHz + BW 10MHz + BW 5MHz, Multi 3 carrier(Non-contiguous), 4TX

QPSK



16QAM







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2939) / (2957)
Pages

64QAM



256QAM






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (2940) / (2957)
Pages

ANT 1

Band 66, BW 5MHz + BW 5MHz + BW 5MHz, Multi 3 carrier(Non-contiguous), 4TX

QPSK



16QAM

