




**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2017-01618-2  
 Page (171) / (282)  
 Pages

**Band 2, BW 20MHz, Single 1 carrier, 4TX, Middle**  
 [QPSK]


9 kHz - 150 kHz



150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 1919 MHz





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2017-01618-2  
 Page (172) / (282)  
 Pages


1919 MHz - 1929 MHz



1991 MHz - 2001 MHz



2001 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2017-01618-2  
 Page (173) / (282)  
 Pages

[16QAM]

9 kHz - 150 kHz




150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 1919 MHz





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2017-01618-2  
 Page (174) / (282)  
 Pages

1919 MHz - 1929 MHz



1991 MHz - 2001 MHz



2001 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2017-01618-2  
 Page (175) / (282)  
 Pages

[64QAM]


9 kHz - 150 kHz



150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 1919 MHz





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2017-01618-2  
 Page (176) / (282)  
 Pages

1919 MHz - 1929 MHz



1991 MHz - 2001 MHz



2001 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2017-01618-2  
 Page (177) / (282)  
 Pages

[256QAM]


9 kHz - 150 kHz




150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 1919 MHz





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2017-01618-2  
 Page (178) / (282)  
 Pages

1919 MHz - 1929 MHz



1991 MHz - 2001 MHz



2001 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz




**Band 2, BW 20MHz, Single 1 carrier, 4TX, Top**  
 [QPSK]


9 kHz - 150 kHz




150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 1919 MHz





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2017-01618-2  
 Page (180) / (282)  
 Pages

1919 MHz - 1929 MHz



1991 MHz - 2001 MHz



2001 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2017-01618-2  
 Page (181) / (282)  
 Pages

[16QAM]


9 kHz - 150 kHz



150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 1919 MHz





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2017-01618-2  
 Page (182) / (282)  
 Pages


1919 MHz - 1929 MHz



1991 MHz - 2001 MHz



2001 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2017-01618-2  
 Page (183) / (282)  
 Pages

[64QAM]


9 kHz - 150 kHz




150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 1919 MHz





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2017-01618-2  
 Page (184) / (282)  
 Pages

1919 MHz - 1929 MHz



1991 MHz - 2001 MHz



2001 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2017-01618-2  
 Page (185) / (282)  
 Pages

[256QAM]


9 kHz - 150 kHz



150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 1919 MHz






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2017-01618-2  
 Page (186) / (282)  
 Pages

1919 MHz - 1929 MHz



1991 MHz - 2001 MHz



2001 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2017-01618-2  
 Page (187) / (282)  
 Pages

**Band 2, BW 5MHz + BW 10MHz, Multi carrier(Contiguous), 2TX**  
 [QPSK]


9 kHz - 150 kHz




150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 1919 MHz





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2017-01618-2  
 Page (188) / (282)  
 Pages

1919 MHz - 1929 MHz



1991 MHz - 2001 MHz



2001 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz





**CTK Co., Ltd.**  
(Ho-dong), 113, Yejik-ro, Cheoin-gu,  
Yongin-si, Gyeonggi-do, Korea  
Tel: +82-31-339-9970  
Fax: +82-31-624-9501

Report No.:  
CTK-2017-01618-2  
Page (189) / (282)  
Pages

[16QAM]


9 kHz - 150 kHz



150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 1919 MHz





**CTK Co., Ltd.**  
(Ho-dong), 113, Yejik-ro, Cheoin-gu,  
Yongin-si, Gyeonggi-do, Korea  
Tel: +82-31-339-9970  
Fax: +82-31-624-9501

Report No.:  
CTK-2017-01618-2  
Page (190) / (282)  
Pages


1919 MHz - 1929 MHz



1991 MHz - 2001 MHz



2001 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2017-01618-2  
 Page (191) / (282)  
 Pages

[64QAM]


9 kHz - 150 kHz



150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 1919 MHz






**CTK Co., Ltd.**  
(Ho-dong), 113, Yejik-ro, Cheoin-gu,  
Yongin-si, Gyeonggi-do, Korea  
Tel: +82-31-339-9970  
Fax: +82-31-624-9501

Report No.:  
CTK-2017-01618-2  
Page (192) / (282)  
Pages


1919 MHz - 1929 MHz



1991 MHz - 2001 MHz



2001 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2017-01618-2  
 Page (193) / (282)  
 Pages

[256QAM]


9 kHz - 150 kHz




150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 1919 MHz





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2017-01618-2  
 Page (194) / (282)  
 Pages


1919 MHz - 1929 MHz



1991 MHz - 2001 MHz



2001 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2017-01618-2  
 Page (195) / (282)  
 Pages

**Band 2, BW 5MHz + BW 10MHz, Multi carrier(Contiguous), 4TX**  
 [QPSK]


9 kHz - 150 kHz



150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 1919 MHz






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2017-01618-2  
 Page (196) / (282)  
 Pages


1919 MHz - 1929 MHz



1991 MHz - 2001 MHz



2001 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2017-01618-2  
 Page (197) / (282)  
 Pages

[16QAM]


9 kHz - 150 kHz



150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 1919 MHz





**CTK Co., Ltd.**  
(Ho-dong), 113, Yejik-ro, Cheoin-gu,  
Yongin-si, Gyeonggi-do, Korea  
Tel: +82-31-339-9970  
Fax: +82-31-624-9501

Report No.:  
CTK-2017-01618-2  
Page (198) / (282)  
Pages


1919 MHz - 1929 MHz



1991 MHz - 2001 MHz



2001 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2017-01618-2  
 Page (199) / (282)  
 Pages

[64QAM]


9 kHz - 150 kHz



150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 1919 MHz






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2017-01618-2  
 Page (200) / (282)  
 Pages


1919 MHz - 1929 MHz



1991 MHz - 2001 MHz



2001 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2017-01618-2  
 Page (201) / (282)  
 Pages

[256QAM]


9 kHz - 150 kHz



150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 1919 MHz





**CTK Co., Ltd.**  
(Ho-dong), 113, Yejik-ro, Cheoin-gu,  
Yongin-si, Gyeonggi-do, Korea  
Tel: +82-31-339-9970  
Fax: +82-31-624-9501

Report No.:  
CTK-2017-01618-2  
Page (202) / (282)  
Pages


1919 MHz - 1929 MHz



1991 MHz - 2001 MHz



2001 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2017-01618-2  
 Page (203) / (282)  
 Pages

**Band 2, BW 10MHz + BW 10MHz, Multi carrier(Contiguous), 2TX**  
 [QPSK]


9 kHz - 150 kHz



150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 1919 MHz





**CTK Co., Ltd.**  
(Ho-dong), 113, Yejik-ro, Cheoin-gu,  
Yongin-si, Gyeonggi-do, Korea  
Tel: +82-31-339-9970  
Fax: +82-31-624-9501

Report No.:  
CTK-2017-01618-2  
Page (204) / (282)  
Pages


1919 MHz - 1929 MHz



1991 MHz - 2001 MHz



2001 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2017-01618-2  
 Page (205) / (282)  
 Pages

[16QAM]


9 kHz - 150 kHz



150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 1919 MHz





**CTK Co., Ltd.**  
(Ho-dong), 113, Yejik-ro, Cheoin-gu,  
Yongin-si, Gyeonggi-do, Korea  
Tel: +82-31-339-9970  
Fax: +82-31-624-9501

Report No.:  
CTK-2017-01618-2  
Page (206) / (282)  
Pages

1919 MHz - 1929 MHz



1991 MHz - 2001 MHz



2001 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2017-01618-2  
 Page (207) / (282)  
 Pages

[64QAM]


9 kHz - 150 kHz




150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 1919 MHz





**CTK Co., Ltd.**  
(Ho-dong), 113, Yejik-ro, Cheoin-gu,  
Yongin-si, Gyeonggi-do, Korea  
Tel: +82-31-339-9970  
Fax: +82-31-624-9501

Report No.:  
CTK-2017-01618-2  
Page (208) / (282)  
Pages


1919 MHz - 1929 MHz



1991 MHz - 2001 MHz



2001 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2017-01618-2  
 Page (209) / (282)  
 Pages

[256QAM]


9 kHz - 150 kHz



150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 1919 MHz






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2017-01618-2  
 Page (210) / (282)  
 Pages

1919 MHz - 1929 MHz



1991 MHz - 2001 MHz



2001 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz






**CTK Co., Ltd.**  
(Ho-dong), 113, Yejik-ro, Cheoin-gu,  
Yongin-si, Gyeonggi-do, Korea  
Tel: +82-31-339-9970  
Fax: +82-31-624-9501


Report No.:  
CTK-2017-01618-2  
Page (211) / (282)  
Pages

**Band 2, BW 10MHz + BW 10MHz, Multi carrier(Contiguous), 4TX**  
[QPSK]


9 kHz - 150 kHz



150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 1919 MHz







**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2017-01618-2  
 Page (212) / (282)  
 Pages

1919 MHz - 1929 MHz



1991 MHz - 2001 MHz



2001 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz





**CTK Co., Ltd.**  
(Ho-dong), 113, Yejik-ro, Cheoin-gu,  
Yongin-si, Gyeonggi-do, Korea  
Tel: +82-31-339-9970  
Fax: +82-31-624-9501

Report No.:  
CTK-2017-01618-2  
Page (213) / (282)  
Pages

[16QAM]


9 kHz - 150 kHz



150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 1919 MHz





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2017-01618-2  
 Page (214) / (282)  
 Pages


1919 MHz - 1929 MHz



1991 MHz - 2001 MHz



2001 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2017-01618-2  
 Page (215) / (282)  
 Pages

[64QAM]


9 kHz - 150 kHz



150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 1919 MHz






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2017-01618-2  
 Page (216) / (282)  
 Pages


1919 MHz - 1929 MHz




1991 MHz - 2001 MHz



2001 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2017-01618-2  
 Page (217) / (282)  
 Pages

[256QAM]


9 kHz - 150 kHz



150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 1919 MHz





**CTK Co., Ltd.**  
(Ho-dong), 113, Yejik-ro, Cheoin-gu,  
Yongin-si, Gyeonggi-do, Korea  
Tel: +82-31-339-9970  
Fax: +82-31-624-9501

Report No.:  
CTK-2017-01618-2  
Page (218) / (282)  
Pages


1919 MHz - 1929 MHz



1991 MHz - 2001 MHz



2001 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2017-01618-2  
 Page (219) / (282)  
 Pages

**Band 2, BW 10 MHz + BW 5MHz, Multi carrier(Non-Contiguous), 2TX**  
 [QPSK]


9 kHz - 150 kHz




150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 1919 MHz





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2017-01618-2  
 Page (220) / (282)  
 Pages

1919 MHz - 1929 MHz



1991 MHz - 2001 MHz



2001 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2017-01618-2  
 Page (221) / (282)  
 Pages

[16QAM]


9 kHz - 150 kHz



150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 1919 MHz





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2017-01618-2  
 Page (222) / (282)  
 Pages

1919 MHz - 1929 MHz



1991 MHz - 2001 MHz



2001 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz





**CTK Co., Ltd.**  
(Ho-dong), 113, Yejik-ro, Cheoin-gu,  
Yongin-si, Gyeonggi-do, Korea  
Tel: +82-31-339-9970  
Fax: +82-31-624-9501

Report No.:  
CTK-2017-01618-2  
Page (223) / (282)  
Pages

[64QAM]


9 kHz - 150 kHz




150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 1919 MHz





**CTK Co., Ltd.**  
(Ho-dong), 113, Yejik-ro, Cheoin-gu,  
Yongin-si, Gyeonggi-do, Korea  
Tel: +82-31-339-9970  
Fax: +82-31-624-9501

Report No.:  
CTK-2017-01618-2  
Page (224) / (282)  
Pages


1919 MHz - 1929 MHz



1991 MHz - 2001 MHz



2001 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2017-01618-2  
 Page (225) / (282)  
 Pages

[256QAM]


9 kHz - 150 kHz



150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 1919 MHz





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2017-01618-2  
 Page (226) / (282)  
 Pages


1919 MHz - 1929 MHz



1991 MHz - 2001 MHz



2001 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2017-01618-2  
 Page (227) / (282)  
 Pages

**Band 2, BW 10 MHz + BW 5 MHz, Multi carrier(Non-Contiguous), 4TX**  
 [QPSK]


9 kHz - 150 kHz




150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 1919 MHz





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2017-01618-2  
 Page (228) / (282)  
 Pages


1919 MHz - 1929 MHz



1991 MHz - 2001 MHz



2001 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2017-01618-2  
 Page (229) / (282)  
 Pages

[16QAM]


9 kHz - 150 kHz



150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 1919 MHz





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2017-01618-2  
 Page (230) / (282)  
 Pages


1919 MHz - 1929 MHz



1991 MHz - 2001 MHz



2001 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2017-01618-2  
 Page (231) / (282)  
 Pages

[64QAM]


9 kHz - 150 kHz



150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 1919 MHz





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2017-01618-2  
 Page (232) / (282)  
 Pages


1919 MHz - 1929 MHz



1991 MHz - 2001 MHz



2001 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2017-01618-2  
 Page (233) / (282)  
 Pages

[256QAM]


9 kHz - 150 kHz



150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 1919 MHz





**CTK Co., Ltd.**  
(Ho-dong), 113, Yejik-ro, Cheoin-gu,  
Yongin-si, Gyeonggi-do, Korea  
Tel: +82-31-339-9970  
Fax: +82-31-624-9501

Report No.:  
CTK-2017-01618-2  
Page (234) / (282)  
Pages


1919 MHz - 1929 MHz



1991 MHz - 2001 MHz



2001 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2017-01618-2  
 Page (235) / (282)  
 Pages

**Band 2, BW 10MHz + BW 10MHz, Multi carrier(Non-Contiguous), 2TX**  
 [QPSK]


9 kHz - 150 kHz



150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 1919 MHz





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2017-01618-2  
 Page (236) / (282)  
 Pages

1919 MHz - 1929 MHz



1991 MHz - 2001 MHz



2001 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2017-01618-2  
 Page (237) / (282)  
 Pages

[16QAM]


9 kHz - 150 kHz




150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 1919 MHz





**CTK Co., Ltd.**  
(Ho-dong), 113, Yejik-ro, Cheoin-gu,  
Yongin-si, Gyeonggi-do, Korea  
Tel: +82-31-339-9970  
Fax: +82-31-624-9501

Report No.:  
CTK-2017-01618-2  
Page (238) / (282)  
Pages


1919 MHz - 1929 MHz



1991 MHz - 2001 MHz



2001 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2017-01618-2  
 Page (239) / (282)  
 Pages

[64QAM]


9 kHz - 150 kHz



150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 1919 MHz





**CTK Co., Ltd.**  
(Ho-dong), 113, Yejik-ro, Cheoin-gu,  
Yongin-si, Gyeonggi-do, Korea  
Tel: +82-31-339-9970  
Fax: +82-31-624-9501

Report No.:  
CTK-2017-01618-2  
Page (240) / (282)  
Pages


1919 MHz - 1929 MHz



1991 MHz - 2001 MHz



2001 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2017-01618-2  
 Page (241) / (282)  
 Pages

[256QAM]


9 kHz - 150 kHz



150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 1919 MHz





**CTK Co., Ltd.**  
(Ho-dong), 113, Yejik-ro, Cheoin-gu,  
Yongin-si, Gyeonggi-do, Korea  
Tel: +82-31-339-9970  
Fax: +82-31-624-9501

Report No.:  
CTK-2017-01618-2  
Page (242) / (282)  
Pages


1919 MHz - 1929 MHz



1991 MHz - 2001 MHz



2001 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2017-01618-2  
 Page (243) / (282)  
 Pages

**Band 2, BW 10MHz + BW 10MHz, Multi carrier(Non-Contiguous), 4TX**  
 [QPSK]


9 kHz - 150 kHz




150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 1919 MHz





**CTK Co., Ltd.**  
(Ho-dong), 113, Yejik-ro, Cheoin-gu,  
Yongin-si, Gyeonggi-do, Korea  
Tel: +82-31-339-9970  
Fax: +82-31-624-9501

Report No.:  
CTK-2017-01618-2  
Page (244) / (282)  
Pages

1919 MHz - 1929 MHz



1991 MHz - 2001 MHz



2001 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2017-01618-2  
 Page (245) / (282)  
 Pages

[16QAM]


9 kHz - 150 kHz



150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 1919 MHz





**CTK Co., Ltd.**  
(Ho-dong), 113, Yejik-ro, Cheoin-gu,  
Yongin-si, Gyeonggi-do, Korea  
Tel: +82-31-339-9970  
Fax: +82-31-624-9501

Report No.:  
CTK-2017-01618-2  
Page (246) / (282)  
Pages


1919 MHz - 1929 MHz



1991 MHz - 2001 MHz



2001 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2017-01618-2  
 Page (247) / (282)  
 Pages

[64QAM]


9 kHz - 150 kHz



150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 1919 MHz






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2017-01618-2  
 Page (248) / (282)  
 Pages


1919 MHz - 1929 MHz



1991 MHz - 2001 MHz



2001 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2017-01618-2  
 Page (249) / (282)  
 Pages

[256QAM]


9 kHz - 150 kHz



150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 1919 MHz





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2017-01618-2  
 Page (250) / (282)  
 Pages


1919 MHz - 1929 MHz



1991 MHz - 2001 MHz



2001 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz

