




CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501


Report No.:
CTK-2017-01618-1
Page (302) / (893)
Pages

Band 66, BW 20MHz, Single 1 carrier, 2TX, Middle
[QPSK]


9 kHz - 150 kHz




150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 2099 MHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (303) / (893)
 Pages


2099 MHz - 2109 MHz



2181 MHz - 2191 MHz



2191 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (304) / (893)
Pages

[16QAM]


9 kHz - 150 kHz




150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 2099 MHz






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (305) / (893)
Pages


2099 MHz - 2109 MHz



2181 MHz - 2191 MHz



2191 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501


Report No.:
CTK-2017-01618-1
Page (306) / (893)
Pages

[64QAM]


9 kHz - 150 kHz



150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 2099 MHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (307) / (893)
 Pages

2099 MHz - 2109 MHz



2181 MHz - 2191 MHz



2191 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (308) / (893)
Pages

[256QAM]


9 kHz - 150 kHz



150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 2099 MHz







CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (309) / (893)
 Pages

2099 MHz - 2109 MHz



2181 MHz - 2191 MHz



2191 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2017-01618-1
 Page (310) / (893)
 Pages

Band 66, BW 20MHz, Single 1 carrier, 2TX, Top
 [QPSK]


9 kHz - 150 kHz




150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 2099 MHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (311) / (893)
 Pages

2099 MHz - 2109 MHz



2181 MHz - 2191 MHz



2191 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (312) / (893)
Pages

[16QAM]


9 kHz - 150 kHz



150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 2099 MHz







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (313) / (893)
Pages


2099 MHz - 2109 MHz




2181 MHz - 2191 MHz



2191 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (314) / (893)
Pages

[64QAM]


9 kHz - 150 kHz



150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 2099 MHz







CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (315) / (893)
 Pages

2099 MHz - 2109 MHz



2181 MHz - 2191 MHz



2191 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2017-01618-1
 Page (316) / (893)
 Pages

[256QAM]


9 kHz - 150 kHz



150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 2099 MHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (317) / (893)
 Pages

2099 MHz - 2109 MHz



2181 MHz - 2191 MHz



2191 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (318) / (893)
 Pages

Band 66, BW 20MHz, Single 1 carrier, 4TX, Bottom
 [QPSK]


9 kHz - 150 kHz




150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 2099 MHz






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (319) / (893)
Pages


2099 MHz - 2109 MHz



2181 MHz - 2191 MHz



2191 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501


Report No.:
CTK-2017-01618-1
Page (320) / (893)
Pages

[16QAM]


9 kHz - 150 kHz




150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 2099 MHz





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (321) / (893)
Pages


2099 MHz - 2109 MHz



2181 MHz - 2191 MHz



2191 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501


Report No.:
CTK-2017-01618-1
Page (322) / (893)
Pages

[64QAM]


9 kHz - 150 kHz



150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 2099 MHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (323) / (893)
 Pages


2099 MHz - 2109 MHz



2181 MHz - 2191 MHz



2191 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2017-01618-1
 Page (324) / (893)
 Pages

[256QAM]


9 kHz - 150 kHz



150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 2099 MHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (325) / (893)
 Pages


2099 MHz - 2109 MHz



2181 MHz - 2191 MHz



2191 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (326) / (893)
Pages

Band 66, BW 20MHz, Single 1 carrier, 4TX, Middle
[QPSK]


9 kHz - 150 kHz



150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 2099 MHz







CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (327) / (893)
 Pages

2099 MHz - 2109 MHz



2181 MHz - 2191 MHz



2191 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (328) / (893)
 Pages

[16QAM]


9 kHz - 150 kHz



150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 2099 MHz







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (329) / (893)
Pages


2099 MHz - 2109 MHz



2181 MHz - 2191 MHz



2191 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501


Report No.:
CTK-2017-01618-1
Page (330) / (893)
Pages

[64QAM]


9 kHz - 150 kHz




150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 2099 MHz







CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (331) / (893)
 Pages

2099 MHz - 2109 MHz



2181 MHz - 2191 MHz



2191 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2017-01618-1
 Page (332) / (893)
 Pages

[256QAM]


9 kHz - 150 kHz



150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 2099 MHz







CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (333) / (893)
 Pages

2099 MHz - 2109 MHz



2181 MHz - 2191 MHz



2191 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (334) / (893)
 Pages

Band 66, BW 20MHz, Single 1 carrier, 4TX, Top
 [QPSK]


9 kHz - 150 kHz



150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 2099 MHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (335) / (893)
 Pages

2099 MHz - 2109 MHz



2181 MHz - 2191 MHz



2191 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (336) / (893)
Pages

[16QAM]


9 kHz - 150 kHz




150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 2099 MHz







CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (337) / (893)
 Pages

2099 MHz - 2109 MHz



2181 MHz - 2191 MHz



2191 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501


Report No.:
CTK-2017-01618-1
Page (338) / (893)
Pages

[64QAM]

9 kHz - 150 kHz



150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 2099 MHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (339) / (893)
 Pages


2099 MHz - 2109 MHz



2181 MHz - 2191 MHz



2191 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2017-01618-1
 Page (340) / (893)
 Pages

[256QAM]


9 kHz - 150 kHz




150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 2099 MHz







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (341) / (893)
Pages


2099 MHz - 2109 MHz



2181 MHz - 2191 MHz



2191 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (342) / (893)
 Pages

Band 66, BW 5MHz + BW 10MHz, Multi 2 carrier(Contiguous), 2TX, Bottom
 [QPSK]


9 kHz - 150 kHz



150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 2099 MHz





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (343) / (893)
 Pages


2099 MHz - 2109 MHz



2181 MHz - 2191 MHz



2191 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (344) / (893)
Pages

[16QAM]


9 kHz - 150 kHz



150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 2099 MHz





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (345) / (893)
 Pages

2099 MHz - 2109 MHz



2181 MHz - 2191 MHz



2191 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (346) / (893)
 Pages

[64QAM]


9 kHz - 150 kHz



150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 2099 MHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (347) / (893)
 Pages

2099 MHz - 2109 MHz



2181 MHz - 2191 MHz



2191 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (348) / (893)
 Pages

[256QAM]


9 kHz - 150 kHz



150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 2099 MHz





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (349) / (893)
Pages

2099 MHz - 2109 MHz



2181 MHz - 2191 MHz



2191 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (350) / (893)
 Pages

Band 66, BW 5MHz + BW 10MHz, Multi 2 carrier(Contiguous), 2TX, Top
 [QPSK]


9 kHz - 150 kHz




150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 2099 MHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (351) / (893)
 Pages

2099 MHz - 2109 MHz



2181 MHz - 2191 MHz



2191 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (352) / (893)
Pages

[16QAM]


9 kHz - 150 kHz



150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 2099 MHz





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (353) / (893)
 Pages

2099 MHz - 2109 MHz



2181 MHz - 2191 MHz



2191 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2017-01618-1
 Page (354) / (893)
 Pages

[64QAM]


9 kHz - 150 kHz




150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 2099 MHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (355) / (893)
 Pages


2099 MHz - 2109 MHz



2181 MHz - 2191 MHz



2191 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (356) / (893)
 Pages

[256QAM]


9 kHz - 150 kHz



150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 2099 MHz





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (357) / (893)
 Pages

2099 MHz - 2109 MHz



2181 MHz - 2191 MHz



2191 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (358) / (893)
 Pages

Band 66, BW 5MHz + BW 10MHz, Multi 2 carrier(Contiguous), 4TX, Bottom
 [QPSK]


9 kHz - 150 kHz



150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 2099 MHz







CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (359) / (893)
 Pages

2099 MHz - 2109 MHz



2181 MHz - 2191 MHz



2191 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (360) / (893)
 Pages

[16QAM]


9 kHz - 150 kHz




150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 2099 MHz





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (361) / (893)
 Pages

2099 MHz - 2109 MHz



2181 MHz - 2191 MHz



2191 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (362) / (893)
 Pages

[64QAM]

9 kHz - 150 kHz



150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 2099 MHz







CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (363) / (893)
 Pages

2099 MHz - 2109 MHz



2181 MHz - 2191 MHz



2191 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2017-01618-1
 Page (364) / (893)
 Pages

[256QAM]


9 kHz - 150 kHz




150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 2099 MHz





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (365) / (893)
 Pages

2099 MHz - 2109 MHz



2181 MHz - 2191 MHz



2191 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (366) / (893)
 Pages

Band 66, BW 5MHz + BW 10MHz, Multi 2 carrier(Contiguous), 4TX, Top
 [QPSK]

9 kHz - 150 kHz




150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 2099 MHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (367) / (893)
 Pages


2099 MHz - 2109 MHz



2181 MHz - 2191 MHz



2191 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (368) / (893)
 Pages

[16QAM]

9 kHz - 150 kHz



150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 2099 MHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (369) / (893)
 Pages

2099 MHz - 2109 MHz



2181 MHz - 2191 MHz



2191 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (370) / (893)
 Pages

[64QAM]

9 kHz - 150 kHz




150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 2099 MHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (371) / (893)
 Pages

2099 MHz - 2109 MHz



2181 MHz - 2191 MHz



2191 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2017-01618-1
 Page (372) / (893)
 Pages

[256QAM]


9 kHz - 150 kHz



150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 2099 MHz





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (373) / (893)
Pages

2099 MHz - 2109 MHz



2181 MHz - 2191 MHz



2191 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (374) / (893)
 Pages

Band 66, BW 5MHz + BW 20MHz, Multi 2 carrier(Contiguous), 2TX, Bottom
 [QPSK]


9 kHz - 150 kHz



150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 2099 MHz





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (375) / (893)
 Pages

2099 MHz - 2109 MHz



2181 MHz - 2191 MHz



2191 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2017-01618-1
 Page (376) / (893)
 Pages

[16QAM]

9 kHz - 150 kHz



150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 2099 MHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (377) / (893)
 Pages

2099 MHz - 2109 MHz



2181 MHz - 2191 MHz



2191 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (378) / (893)
 Pages

[64QAM]


9 kHz - 150 kHz



150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 2099 MHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (379) / (893)
 Pages


2099 MHz - 2109 MHz



2181 MHz - 2191 MHz



2191 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2017-01618-1
 Page (380) / (893)
 Pages

[256QAM]


9 kHz - 150 kHz



150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 2099 MHz





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (381) / (893)
 Pages

2099 MHz - 2109 MHz



2181 MHz - 2191 MHz



2191 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2017-01618-1
 Page (382) / (893)
 Pages

Band 66, BW 5MHz + BW 20MHz, Multi 2 carrier(Contiguous), 2TX, Top
 [QPSK]


9 kHz - 150 kHz



150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 2099 MHz






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2017-01618-1
Page (383) / (893)
Pages

2099 MHz - 2109 MHz



2181 MHz - 2191 MHz



2191 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2017-01618-1
 Page (384) / (893)
 Pages

[16QAM]


9 kHz - 150 kHz




150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 2099 MHz





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (385) / (893)
 Pages

2099 MHz - 2109 MHz



2181 MHz - 2191 MHz



2191 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (386) / (893)
 Pages

[64QAM]


9 kHz - 150 kHz



150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 2099 MHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (387) / (893)
 Pages

2099 MHz - 2109 MHz



2181 MHz - 2191 MHz



2191 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (388) / (893)
 Pages

[256QAM]


9 kHz - 150 kHz



150 kHz - 30 MHz



30 MHz - 1000 MHz



1000 MHz - 2099 MHz





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2017-01618-1
 Page (389) / (893)
 Pages

2099 MHz - 2109 MHz



2181 MHz - 2191 MHz



2191 MHz - 12.75 GHz



12.75 GHz - 26.5 GHz

