




CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-00289
 Page (109) / (192)
 Pages

[64QAM]

9 kHz - 150 kHz



150 kHz - 30 MHz




30 MHz - 860 MHz




860 MHz - 868 MHz




895 MHz - 905 MHz



905 MHz - 1 GHz



1 GHz - 12.75 GHz





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-00289
 Page (110) / (192)
 Pages

[256QAM]

9 kHz - 150 kHz



150 kHz - 30 MHz




30 MHz - 860 MHz




860 MHz - 868 MHz




895 MHz - 905 MHz



905 MHz - 1 GHz



1 GHz - 12.75 GHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-00289
 Page (111) / (192)
 Pages

**BW 10MHz+5MHz, Multi 2 carrier(Contiguous), 4Tx, Bottom
 ANT 1
 [QPSK]**






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-00289
 Page (112) / (192)
 Pages

[16QAM]


9 kHz - 150 kHz




150 kHz - 30 MHz



30 MHz - 860 MHz



860 MHz - 868 MHz



894 MHz - 1 GHz



1 GHz - 12.75 GHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-00289
 Page (113) / (192)
 Pages

[64QAM]

9 kHz - 150 kHz




150 kHz - 30 MHz




30 MHz - 860 MHz




860 MHz - 868 MHz



894 MHz - 1 GHz



1 GHz - 12.75 GHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-00289
 Page (114) / (192)
 Pages

[256QAM]

9 kHz - 150 kHz




150 kHz - 30 MHz



30 MHz - 860 MHz




860 MHz - 868 MHz



894 MHz - 1 GHz



1 GHz - 12.75 GHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-00289
 Page (115) / (192)
 Pages

ANT 2
[QPSK]

9 kHz - 150 kHz




150 kHz - 30 MHz




30 MHz - 860 MHz




860 MHz - 868 MHz



894 MHz - 1 GHz



1 GHz - 12.75 GHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-00289
 Page (116) / (192)
 Pages

[16QAM]

9 kHz - 150 kHz



150 kHz - 30 MHz




30 MHz - 860 MHz




860 MHz - 868 MHz



894 MHz - 1 GHz



1 GHz - 12.75 GHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-00289
 Page (117) / (192)
 Pages

[64QAM]


9 kHz - 150 kHz



150 kHz - 30 MHz




30 MHz - 860 MHz




860 MHz - 868 MHz



894 MHz - 1 GHz



1 GHz - 12.75 GHz





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-00289
 Page (118) / (192)
 Pages

[256QAM]

9 kHz - 150 kHz




150 kHz - 30 MHz



30 MHz - 860 MHz




860 MHz - 868 MHz



894 MHz - 1 GHz



1 GHz - 12.75 GHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-00289
 Page (119) / (192)
 Pages

ANT 3
[QPSK]

9 kHz - 150 kHz



150 kHz - 30 MHz




30 MHz - 860 MHz



860 MHz - 868 MHz



894 MHz - 1 GHz



1 GHz - 12.75 GHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-00289
 Page (120) / (192)
 Pages

[16QAM]

9 kHz - 150 kHz



150 kHz - 30 MHz




30 MHz - 860 MHz




860 MHz - 868 MHz



894 MHz - 1 GHz



1 GHz - 12.75 GHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-00289
 Page (121) / (192)
 Pages

[64QAM]


9 kHz - 150 kHz




150 kHz - 30 MHz




30 MHz - 860 MHz




860 MHz - 868 MHz



894 MHz - 1 GHz



1 GHz - 12.75 GHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-00289
 Page (122) / (192)
 Pages

[256QAM]


9 kHz - 150 kHz



150 kHz - 30 MHz




30 MHz - 860 MHz



860 MHz - 868 MHz



894 MHz - 1 GHz



1 GHz - 12.75 GHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-00289
 Page (123) / (192)
 Pages

ANT 4
[QPSK]

9 kHz - 150 kHz




150 kHz - 30 MHz




30 MHz - 860 MHz



860 MHz - 868 MHz



894 MHz - 1 GHz



1 GHz - 12.75 GHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-00289
 Page (124) / (192)
 Pages

[16QAM]


9 kHz - 150 kHz




150 kHz - 30 MHz



30 MHz - 860 MHz



860 MHz - 868 MHz



894 MHz - 1 GHz



1 GHz - 12.75 GHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-00289
 Page (125) / (192)
 Pages

[64QAM]


9 kHz - 150 kHz




150 kHz - 30 MHz



30 MHz - 860 MHz



860 MHz - 868 MHz



894 MHz - 1 GHz



1 GHz - 12.75 GHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-00289
 Page (126) / (192)
 Pages

[256QAM]

9 kHz - 150 kHz



150 kHz - 30 MHz



30 MHz - 860 MHz




860 MHz - 868 MHz



894 MHz - 1 GHz



1 GHz - 12.75 GHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-00289
 Page (127) / (192)
 Pages

**BW 10MHz+5MHz, Multi 2 carrier(Contiguous), 4Tx, Middle
 ANT 1
 [QPSK]**






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-00289
 Page (128) / (192)
 Pages

[16QAM]

9 kHz - 150 kHz



150 kHz - 30 MHz



30 MHz - 869 MHz



894 MHz - 1 GHz



1 GHz - 12.75 GHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-00289
 Page (129) / (192)
 Pages

[64QAM]

9 kHz - 150 kHz




150 kHz - 30 MHz



30 MHz - 869 MHz



894 MHz - 1 GHz



1 GHz - 12.75 GHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-00289
 Page (130) / (192)
 Pages

[256QAM]

9 kHz - 150 kHz




150 kHz - 30 MHz



30 MHz - 869 MHz



894 MHz - 1 GHz



1 GHz - 12.75 GHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-00289
 Page (131) / (192)
 Pages

ANT 2
[QPSK]

9 kHz - 150 kHz




150 kHz - 30 MHz



30 MHz - 869 MHz



894 MHz - 1 GHz



1 GHz - 12.75 GHz



[16QAM]

9 kHz - 150 kHz




150 kHz - 30 MHz



30 MHz - 869 MHz



894 MHz - 1 GHz



1 GHz - 12.75 GHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-00289
 Page (133) / (192)
 Pages

[64QAM]

9 kHz - 150 kHz




150 kHz - 30 MHz




30 MHz - 869 MHz



894 MHz - 1 GHz



1 GHz - 12.75 GHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-00289
 Page (134) / (192)
 Pages

[256QAM]

9 kHz - 150 kHz




150 kHz - 30 MHz




30 MHz - 869 MHz



894 MHz - 1 GHz



1 GHz - 12.75 GHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-00289
 Page (135) / (192)
 Pages

ANT 3
[QPSK]

9 kHz - 150 kHz




150 kHz - 30 MHz



30 MHz - 869 MHz



894 MHz - 1 GHz



1 GHz - 12.75 GHz

