



ELECTRONICS

SAMSUNG ELECTRONICS AMERICA, INC.

American QA Lab

3351 Michelson Drive, Suite 290

Irvine, CA 92612

May 3, 2005

Federal Communications Commission
Equipment Approval Services
7435 Oakland Mills Road
Columbia, MD 21046
Attn: Stan Lyles

SUBJECT: FCC ID: A3LSCHI730

731 Confirmation No.: EA562274

Correspondence Reference No.: 28742

Request for Tech. Info.: 04/05/05

Dear Mr. Lyles:

Submitted herewith is an amendment provided in response to the request for technical information dated April 5, 2005.

1. A new FCC ID is required only if the RF power increase is due to a design change. There has been no design change in this Bluetooth transmitter. The FCC normally allows manufacturing tolerance for RF power output of +/- 2dB on Part 15C transmitters.

We trust this information is sufficient to resolve the FCC questions regarding this application. If you have any further questions, please do not hesitate to contact us.

Sincerely,

A handwritten signature in black ink that reads "S. J. Kim".

Steve Kim
General Manager
SAMSUNG Electronics America Inc.