



1. AC POWERLINE CONDUCTED EMISSION MEASUREMENT



2. RADIATED EMISSION MEASUREMENT



3. OUTPUT SIGNAL LEVEL & OUTPUT TERMINAL CONDUCTED SPURIOUS EMISSION MEASUREMENT



4. ANTENNA TRANSFER SWITCH MEASUREMENT

