



Date: September 11, 2015

Federal Communications Commission  
Authorization and Evaluation Division  
1435 Oakland Mills Road  
Columbia, MD 21046

SUBJECT: Class II Permissive Change for FCC ID: A3LSLS-BU103

The device identified as FCC ID: A3LSLS-BU103 was granted by the FCC on 06/10/2015. We would like to modify the authorized equipment for below changes:

- Remove Resistor at CPU heat sink for GPS degradation
- Add CAP and SCHOTTKY DIODES for GPIO issue
- Add resistor at GPS bias choke for inductor damage
- Move CAP forward for TSSI accuracy issue
- PAM change
- Add inductor to GND
- Add EMI plate on antenna casing

For details, please refer to the Change Detail exhibit.

Sincerely yours,

A handwritten signature in black ink, appearing to be "Chan Ho Youn", written over a horizontal line.

Chan Ho Youn  
General Manger  
Samsung Electronics Co. LTD  
TEL: +1-973-808-6362  
jjano.youn@samsung.com