



## Appendix D. #Antenna Location & Distance


\* Diagonal dimension of Display and device



\* Distance between antennas and edge



\* Distance between BT/WLAN Antenna and Edge



**Appendix E. EUT Photo**

**Front**



**Rear**



**KCTL Inc.**

65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)

Report No.:  
KR21-SPF0015  
Page (169) of (180)



**Left**



**Right**



**KCTL Inc.**

65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)

Report No.:  
KR21-SPF0015  
Page (170) of (180)



**Top**



**Bottom**



**KCTL Inc.**

65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)

Report No.:  
KR21-SPF0015  
Page (171) of (180)



**Appendix F. Test Setup Photo**  
**Appendix F.1 Test Setup Photo (Head)**

**Right Cheek**



**Right Tilt**





**KCTL Inc.**

65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)

Report No.:  
KR21-SPF0015  
Page (172) of (180)



**Left Cheek**



**Left Tilt**



**KCTL Inc.**

65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)

Report No.:  
KR21-SPF0015  
Page (173) of (180)



**Appendix F.2 Test Setup Photo (Body-Worn)**

**Front (15 mm)**




**Rear (15 mm)**






**Rear without Holder (15 mm)**



**Rear Earphone (15 mm)**



**KCTL Inc.**

65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)

Report No.:  
KR21-SPF0015  
Page (175) of (180)



**Appendix F.3 Test Setup Photo (Hotspot)**

**Front (10 mm)**



**Rear (10 mm)**



**KCTL Inc.**

65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)


Report No.:  
KR21-SPF0015  
Page (176) of (180)



**Left (10 mm)**




**Right (10 mm)**



**Top (10 mm)**



**Bottom (10 mm)**



**KCTL Inc.**

65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)

Report No.:  
KR21-SPF0015  
Page (178) of (180)



**Appendix F.4 Test Setup Photo (Phablet)**

**Front (0 mm)**



**Rear (0 mm)**





**KCTL Inc.**

65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)

Report No.:  
KR21-SPF0015  
Page (179) of (180)



**Rear (14 mm)**



**Left (0 mm)**





**KCTL Inc.**

65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)

Report No.:  
KR21-SPF0015  
Page (180) of (180)



**Left (14 mm)**



**Top (0 mm)**



**End of test report**