



**HCT Co., Ltd.**

74, Seoicheon-ro 578beon-gil, Majang-myeon, Icheon-si, Gyeonggi-do, 17383 KOREA  
Tel. +82 31 634 6300 Fax. +82 31 645 6401


|   |   |
|---|---|
| <h1>Appendix A:<br/>Test Setup<br/>Photo</h1> | <b>FCC ID</b><br>A3LSMA217M   |
|   | <b>File No.</b><br>HCT-RF-2004-FC011-P      HCT-RF-2004-FC016-P<br>HCT-RF-2004-FC012-P<br>HCT-RF-2004-FC013-P<br>HCT-RF-2004-FC014-P<br>HCT-RF-2004-FC015-P |


**REVISION HISTORY**


The revision history for this document is shown in table.


| Revision No. | Date of Issue  | Description     |
|--------------|----------------|-----------------|
| 0            | April 10, 2020 | Initial Release |


### 1. Radiated Test Setup Photo

































## 2. Conducted Test Setup Photo

