



Appendix C. Test Photo**Right Cheek****Right Tilt**


KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr


Report No.:
KR19-SPF0006
Page (131) of (139)



KCTL



Left Cheek






Left Tilt



Front (15 mm)**Front (10 mm)**

Rear (15 mm)**Rear (10 mm)**

Left (10 mm)**Right (10 mm)**

Top (10 mm)**Bottom (10 mm)**


KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr


Report No.:
KR19-SPF0006
Page (136) of (139)



System Check 900 MHz




System Check 2 450 MHz



KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr



Report No.:
KR19-SPF0006
Page (137) of (139)

KCTL**System Check 2 600 MHz****KCTL**

KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr



Report No.:
KR19-SPF0006
Page (138) of (139)

KCTL**Liquid Depth HSL 900****Liquid Depth HSL 2450**

KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR19-SPF0006
Page (139) of (139)

KCTL**Liquid Depth MSL 900****Liquid Depth MSL 2450****End of test report**