

KCTL Inc.


65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR20-SRF0115-A


Page (77) of (103)




10M BW QPSK Lower extended 1RB




10M BW QPSK Upper extended 1RB




10M BW QPSK Lower extended FRB




10M BW QPSK Upper extended FRB




10M BW 16QAM Lower extended 1RB




10M BW 16QAM Upper extended 1RB



10M BW 16QAM Lower extended FRB




10M BW 16QAM Upper extended FRB




Test mode: LTE Band 41


5M BW QPSK Low ch. 1RB




5M BW QPSK High ch. 1RB




5M BW QPSK Low ch. FRB




5M BW QPSK High ch. FRB




5M BW 16QAM Low ch. 1RB




5M BW 16QAM High ch. 1RB




5M BW 16QAM Low ch. FRB




5M BW 16QAM High ch. FRB




10M BW QPSK Low ch. 1RB




10M BW QPSK High ch. 1RB




10M BW QPSK Low ch. FRB




10M BW QPSK High ch. FRB




10M BW 16QAM Low ch. 1RB




10M BW 16QAM High ch. 1RB



10M BW 16QAM Low ch. FRB



10M BW 16QAM High ch. FRB



KCTL Inc.


65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR20-SRF0115-A


Page (80) of (103)




15M BW QPSK Low ch. 1RB




15M BW QPSK High ch. 1RB




15M BW QPSK Low ch. FRB




15M BW QPSK High ch. FRB




15M BW 16QAM Low ch. 1RB




15M BW 16QAM High ch. 1RB



15M BW 16QAM Low ch. FRB



15M BW 16QAM High ch. FRB



This test report shall not be reproduced, except in full, without the written approval