

# KCTL Inc.


65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)

Report No.:  
KR20-SRF0016-A


Page (23) of (219)




## UNII-2C / 802.11n HT20 / Low ch.




## UNII-2C / 802.11n HT20 / Mid ch.



## UNII-2C / 802.11n HT20 / High ch.



## UNII-2C / 802.11n HT20 / Straddle ch.



# KCTL Inc.


65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)

Report No.:  
KR20-SRF0016-A


Page (24) of (219)




## UNII-3 / 802.11n HT20 / Low ch.



## UNII-3 / 802.11n HT20 / Mid ch.



## UNII-3 / 802.11n HT20 / High ch.



blank

# KCTL Inc.


65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)

Report No.:  
KR20-SRF0016-A


Page (25) of (219)




## UNII-1 / 802.11n HT40 / Low ch.




## UNII-2A / 802.11n HT40 / Low ch.



## UNII-1 / 802.11n HT40 / High ch.



## UNII-2A / 802.11n HT40 / High ch.



# KCTL Inc.


65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)

Report No.:  
KR20-SRF0016-A


Page (26) of (219)




## UNII-2C / 802.11n HT40 / Low ch.




## UNII-2C / 802.11n HT40 / Straddle ch.



## UNII-2C / 802.11n HT40 / Mid ch.




## UNII-3 / 802.11n HT40 / Low ch.



## UNII-2C / 802.11n HT40 / High ch.




## UNII-3 / 802.11n HT40 / High ch.




This test report shall not be reproduced, except in full, without the written approval


**UNII-1 / 802.11ac VHT20 / Low ch.**




**UNII-2A / 802.11ac VHT20 / Low ch.**




**UNII-1 / 802.11ac VHT20 / Mid ch.**




**UNII-2A / 802.11ac VHT20 / Mid ch.**



**UNII-1 / 802.11ac VHT20 / High ch.**



**UNII-2A / 802.11ac VHT20 / High ch.**



# KCTL Inc.


65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)

Report No.:  
KR20-SRF0016-A


Page (28) of (219)




## UNII-2C / 802. 11ac VHT20 / Low ch.



## UNII-2C / 802. 11ac VHT20 / Mid ch.



## UNII-2C / 802. 11ac VHT20 / High ch.



## UNII-2C 802. 11ac VHT20 / Straddle ch.



# KCTL Inc.


65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)

Report No.:  
KR20-SRF0016-A


Page (29) of (219)




## UNII-3 / 802.11ac VHT20 / Low ch.



## UNII-3 / 802.11ac VHT20 / Mid ch.



## UNII-3 802.11ac VHT20 / High ch.



blank

# KCTL Inc.


65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)

Report No.:  
KR20-SRF0016-A


Page (30) of (219)




## UNII-1 / 802.11ac VHT40 / Low ch.



## UNII-2A / 802.11ac VHT40 / Low ch.



## UNII-1 / 802.11ac VHT40 / High ch.



## UNII-2A / 802.11ac VHT40 / High ch.

