

KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr


Report No.:
KR20-SRF0023

Page (17) of (57)



26dB Bandwidth

Test mode: LTE Band 26 (Part 90)



KCTL Inc.


65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR20-SRF0023


Page (18) of (57)




3M BW / QPSK / Low ch.




3M BW / 16QAM / Low ch.



3M BW / QPSK / High ch.



3M BW / 16QAM / High ch.



KCTL Inc.


65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR20-SRF0023


Page (19) of (57)




5M BW / QPSK / Low ch.




5M BW / 16QAM / Low ch.



5M BW / QPSK / High ch.



5M BW / 16QAM / High ch.



KCTL Inc.


65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR20-SRF0023


Page (20) of (57)




10M BW / QPSK / Mid ch.




10M BW / 16QAM / Mid ch.



15M BW / QPSK / Mid ch.




15M BW / 16QAM / Mid ch.




Straddle channel


1.4M BW / QPSK




1.4M BW / 16QAM




3M BW / QPSK




3M BW / 16QAM



5M BW / QPSK



5M BW / 16QAM



KCTL Inc.


65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR20-SRF0023


Page (22) of (57)




10M BW / QPSK




10M BW / 16QAM



15M BW / QPSK




15M BW / 16QAM



99% Occupied Bandwidth

Test mode: LTE Band 26 (Part 90)



KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR20-SRF0023


Page (24) of (57)



3M BW / QPSK / Low ch.



3M BW / 16QAM / Low ch.



3M BW / QPSK / High ch.



3M BW / 16QAM / High ch.



KCTL Inc.


65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR20-SRF0023


Page (25) of (57)




5M BW / QPSK / Low ch.



5M BW / 16QAM / Low ch.



5M BW / QPSK / High ch.



5M BW / 16QAM / High ch.



KCTL Inc.


65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR20-SRF0023


Page (26) of (57)



10M BW / QPSK / Mid ch.



10M BW / 16QAM / Mid ch.



15M BW / QPSK / Mid ch.



15M BW / 16QAM / Mid ch.



KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr


Report No.:
KR20-SRF0023

Page (27) of (57)




Straddle channel


1.4M BW / QPSK




1.4M BW / 16QAM




3M BW / QPSK




3M BW / 16QAM



5M BW / QPSK



5M BW / 16QAM



KCTL Inc.


65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR20-SRF0023


Page (28) of (57)




10M BW / QPSK



10M BW / 16QAM



15M BW / QPSK



15M BW / 16QAM

