



Appendix D. #Antenna Location & Distance

* Placement of each antenna



* Distance between WLAN antenna and edge



KCTL Inc.


65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR20-SPF0038
Page (108) of (117)



* Distance between BT/WLAN antenna antenna and edge

Rear View



Appendix E. EUT Photo

Front



Rear



KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR20-SPF0038
Page (110) of (117)



Left



Right



KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR20-SPF0038
Page (111) of (117)

KCTL

Top



Bottom



Appendix F. Test Setup Photo

Rear (0mm)



Rear (12mm)



Rear With Protective Cover (0 mm)



Rear With Protective Cover (12 mm)



KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR20-SPF0038
Page (114) of (117)

KCTL

Left (0 mm)



Left (5 mm)



Left With Protective Cover (5 mm)



Right (0 mm)




KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR20-SPF0038
Page (116) of (117)



Top (0 mm)



Top (7 mm)



KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR20-SPF0038
Page (117) of (117)



Top With Protective Cover (7 mm)



End of test report