


13. SETUP PHOTOS

ANTENNA PORT CONDUCTED RF MEASUREMENT SETUP





RADIATED RF MEASUREMENT SETUP (BELOW 1 GHz)







RADIATED RF MEASUREMENT SETUP (BELOW 1 GHz with Keyboard)







RADIATED RF MEASUREMENT SETUP (ABOVE 1 GHz)







RADIATED RF MEASUREMENT SETUP (ABOVE 1 GHz with Keyboard)






RADIATED RF MEASUREMENT SETUP FOR PORTABLE CONFIGURATION











POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP





END OF REPORT

Page 53 of 53