Serial# 13070234-FCC-H Issue Date July 17th, 2013 Page 97 of 104 www.siemic.com

# Annex B SAR System PHOTOGRAPHS




Liquid depth ≥ 15cm



# Annex C SETUP PHOTOGRAPHS

### **Right Head Touch View**



**Right Head Tilt View** 




### **Left Head Touch View**




**Left Head Tilt View** 



## **Body Setup Photo (LCD UP)**



## **Body Setup Photo (LCD DOWN)**



Serial# 13070234-FCC-H Issue Date July 17th, 2013 Page 101 of 104 www.siemic.com

### Annex D EUT PHOTOGRAPHS

#### **EUT-Front Side View**



#### **EUT-Back Side View**



### **EU-Uncover View (A4.5)**



### **EU-Uncover View (AC4.5)**



### **EU-Top View**



Serial# 13070234-FCC-Hssue Date July 17th, 2013
Page 104 of 104
www.siemic.com

### **Annex E Declaration Letter**





To: 775 Montague Expressway Milpitas, CA 95035, USA

# **Declaration Letter**

For our business issue and marketing requirement, we would like to list 2 model numbers on The FCC reports, as following:

Model No.: A4.5,AC4.5

We declare that , A4.5, AC4.5 the difference of these is listed as below:

Main Model No	Serial Model No	Difference
A4.5	AC4.5	PCB ,Antenna and Appearance
		shape are the same .
		Different: A4.5 has two Sim card
		slots ,AC4.5 has one Sim card slot .

Thank you!

Sincerely,

Client's signature :

Client's name / title: Luis Sosa/CEO

Contact information / address: 1612 NW, 84TH Ave. Miami, Florida, U.S.A 33126