






Plot on Channel 6475 MHz




Plot on Channel 6515 MHz



Plot on Channel 6535 MHz




Plot on Channel 6695 MHz







Plot on Channel 6855 MHz




Plot on Channel 6875 MHz




Plot on Channel 6895 MHz



Plot on Channel 6995 MHz



Plot on Channel 7095 MHz






EUT Mode


802.11be EHT20 26RU0

Plot on Channel 5955 MHz




02:33:29 PM 02/01/2024

Plot on Channel 6435 MHz




03:16:18 PM 02/01/2024

Plot on Channel 6535 MHz



03:57:16 PM 02/01/2024

Plot on Channel 6895 MHz




04:44:55 PM 02/01/2024



EUT Mode


802.11be EHT20 26RU4

Plot on Channel 6195 MHz




02:42:30 PM 02/01/2024

Plot on Channel 6475 MHz




03:33:50 PM 02/01/2024

Plot on Channel 6695 MHz



04:04:49 PM 02/01/2024

Plot on Channel 6995 MHz




04:53:11 PM 02/01/2024



EUT Mode


802.11be EHT20 26RU8

Plot on Channel 6415 MHz




03:07:42 PM 02/01/2024

Plot on Channel 6515 MHz




03:49:22 PM 02/01/2024

Plot on Channel 6855 MHz




04:15:29 PM 02/01/2024

Plot on Channel 6875 MHz



04:31:01 PM 02/01/2024

Plot on Channel 7095 MHz




05:01:12 PM 02/01/2024



EUT Mode


802.11be EHT20 52RU37

Plot on Channel 5955 MHz




02:38:03 PM 02/01/2024

Plot on Channel 6435 MHz




03:17:34 PM 02/01/2024

Plot on Channel 6535 MHz



03:58:33 PM 02/01/2024

Plot on Channel 6895 MHz




04:46:13 PM 02/01/2024




EUT Mode

802.11be EHT20 52RU38


Plot on Channel 6195 MHz




Plot on Channel 6475 MHz



Plot on Channel 6695 MHz



Plot on Channel 6995 MHz







EUT Mode

802.11be EHT20 52RU40


Plot on Channel 6415 MHz




Plot on Channel 6515 MHz



Plot on Channel 6855 MHz




Plot on Channel 6875 MHz





Plot on Channel 7095 MHz






EUT Mode


802.11be EHT20 106RU53

Plot on Channel 5955 MHz




02:39:59 PM 02/01/2024

Plot on Channel 6195 MHz




03:03:37 PM 02/01/2024

Plot on Channel 6435 MHz



03:20:27 PM 02/01/2024


Plot on Channel 6475 MHz




03:44:16 PM 02/01/2024




Plot on Channel 6535 MHz




Plot on Channel 6695 MHz



Plot on Channel 6895 MHz



Plot on Channel 6995 MHz







EUT Mode

802.11be EHT20 106RU54


Plot on Channel 6415 MHz




Plot on Channel 6515 MHz



Plot on Channel 6855 MHz




Plot on Channel 6875 MHz





Plot on Channel 7095 MHz






EUT Mode


802.11be EHT20 MRU 106T+26T82

Plot on Channel 5955 MHz




05:35:55 PM 02/02/2024

Plot on Channel 6435 MHz




10:25:32 AM 02/02/2024

Plot on Channel 6535 MHz



11:35:32 AM 02/02/2024

Plot on Channel 6895 MHz




02:24:49 PM 02/02/2024



EUT Mode


802.11be EHT20 MRU 106T+26T83

Plot on Channel 6195 MHz




05:51:07 PM 02/02/2024

Plot on Channel 6415 MHz




10:04:44 AM 02/02/2024

Plot on Channel 6475 MHz



10:57:23 AM 02/02/2024


Plot on Channel 6515 MHz



11:13:01 AM 02/02/2024




Plot on Channel 6695 MHz




11:57:33 AM 02/02/2024

Plot on Channel 6855 MHz




03:26:46 PM 02/02/2024

Plot on Channel 6875 MHz




02:10:20 PM 02/02/2024



02:38:51 PM 02/02/2024

Plot on Channel 7095 MHz



03:03:45 PM 02/02/2024