

Declaration of Dedicated RF card requirement

Date: May 16, 2003

American Telecommunications Certification Body, Inc.
6731 Whittier Avenue
Suite C110
McLean, VA 22101

FCC ID: A6RMCX1000A

To Whom It May Concern:

We, Yamaha declare here that this system requires the dedicated Radio Frequency card for its functional working.


If the card is not equipped or the card other than its dedicated card is equipped with the system,
the following message is appeared on the display, and the system is not operated until the power is off and restarted.

MCX-1000 WIRELESS LAN CARD NOT FOUND
DISCONNECT THE MCX-1000 FROM THE AC OUTLET
AND INSERT THE MCX-1000 WIRELESS LAN CARD

MCX-1000 decides whether or not the card is its dedicated one when it is turned on
by accessing to Attribute area in the card that has its manufacture's code and ID.

Thank you for your attention to this matter.

Sincerely



Kenichi Suetsugu
Manager
Safety Standard Section

YAMAHA CORPORATION
10-1 Nakazawa-cho, Hamamatsu 430-8650, Japan
Tel. 81-53-460-2376 Fax. 81-53-460-2379