



# Intertek Testing Services

## ETL SEMKO

Report No.: 0005083  
Transmit Mode

Tested By: Hong, Report No.: 0005083

Scan Settings (1 Range)

| Frequencies |      |      |       | Receiver Settings |        |       |        |
|-------------|------|------|-------|-------------------|--------|-------|--------|
| Start       | Stop | Step | IF BW | Detector          | M-Time | Atten | Preamp |
| 450k        | 30M  | 5k   | 10k   | PK                | 20ms   | AUTO  | LN OFF |


Final Measurement: x QP

Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB

| Transducer No. | Start | Stop | Name   |
|----------------|-------|------|--------|
| 21             | 9k    | 30M  | EW0698 |



Ctrl No.: N/A



# Intertek Testing Services

## ETL SEMKO

Report No.: 0005083  
Transmit Mode

Tested By: Hong, Report No.:0005083

Scan Settings (1 Range)

|----- Frequencies -----||----- Receiver Settings -----|

| Start | Stop | Step | IF BW | Detector | M-Time | Atten | Preamp | OpRge |
|-------|------|------|-------|----------|--------|-------|--------|-------|
|-------|------|------|-------|----------|--------|-------|--------|-------|

|      |     |    |     |    |      |      |        |      |
|------|-----|----|-----|----|------|------|--------|------|
| 450k | 30M | 5k | 10k | PK | 20ms | AUTO | LN OFF | 60dB |
|------|-----|----|-----|----|------|------|--------|------|

Final Measurement Results:

no Results