

June 14, 2005

RE: FCC ID: AB6NT1030VBTS\_ATCB002500 Attention: Thomas Wong

I have a few comments on this Application. Please note that further comments may arise in response to answers provided to the questions below.

1. Please note that the label and the 731 form do not agree as to the FCC ID number. The label shows AB6NT1030BTS While the 731 shows AB6NT800RM-CBTS. Please explain and please provide an accurate 731 form.

Dennis Ward

Dennis Ward mailto:dward@AmericanTCB.com

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.