

Attn: Reviewing Agency or TCB

RE: FCC ID: AB6NTE310AG Model AP7215

I certify that the submitted data accurately represents the current state of the device or system for which equipment certification update is sought. The product will not be utilizing the DFS channels and therefore Nortel formally requests that the DFS bands be removed from the current FCC Listing . The only bands of operation are the 5725 – 5850 MHz and the 2412-2462 MHz band as per the original approval. The access to the DFS channels has been eliminated via a factory software change and the user does not have the capability of accessing these channels any more.

Dated this 27th day of September 2007 by

ha (Signature)

Marin Sampaleanu, P. Eng.

Title:Regulatory PrimeEmail:marsam@nortel.comOn behalf of:NortelTelephone:(403) 769 4781