APPLICANT: MOTOROLA SOLUTIONS EQUIPMENT TYPE: ABZ89FT5901

109AB-T5901


## **Photographs of the Device**

Photographs – Index

<u>EXHIBIT</u>	DESCRIPTION
A1	ID Label Location
A2	FCC / IC Identification Label

## **Photographs of the Device**

ID Label Location



**EQUIPMENT TYPE: ABZ89FT5901** 109AB-T5901

## **Photographs of the Device**

FCC / IC Identification Label



## DBR M12

Serial No: XXXXXXXXXX F.O. XXXXXXXXX XXXXX Page No: XX Item No: XX

Model No: T8899A FCC ID: ABZ89FT5901 IC:109AB-T5901 HVIN:T8899-800

Super Model:SQM01SUM0338A Serial No: XXXXXXXXXXX

This device complies with Part 15 of the FCC rules. Operation is subject to the following two conditions: (1) This device may not be harmful interference and (2) this device must accept any interference received including interference that may cause undersired operation.







Made in Mexico

42.0 - 60.0 V === 130A Max