

APPLICANT: MOTOROLA SOLUTIONS

EQUIPMENT TYPE: ABZ99FT3094B
109AB-99FT3094B

Photographs of the Device

FCC / IC Identification Label

SN: 

 **MOTOROLA** SLR 5700

Serial No: 4781QY0148
Model No: AAR10QCGANQ1AN
S/Tanapa: PMUE43092AANAA
FCC ID: ABZ99FT3094B
IC: 109AB-99FT3094B
IC Model No: SLR 5700-VHFB

This device complies with Part 15 of the FCC rules, operation is subject to the condition that this device does not cause harmful interference

MAC 1:  87E40FD2582
MAC 2:  87E40FD2583




 Prof. Transceiver
31 NH

100-240V ~ Max 4A 50/60 Hz
11.0-14.4V === 17A Max

Made in Mexico