

Photographs of the Device

Photographs – Index

<u>EXHIBIT</u>	<u>DESCRIPTION</u>
A1	ID Label Location
A2	FCC / IC Identification Label


Photographs of the Device


ID Label Location



Photographs of the Device

FCC / IC Identification Label



SN: 






MOTOROLA SLR 8000


This device complies with Part 15 of the FCC rules. operation is subject to the condition that this device does not cause harmful interference

Serial No: 433IYY0565
 Model No: T8319A
 S/Tanapa: PMUD3360A
 FCC ID: ABZ99FT3095B
 IC: 109AB-99FT3095B
 HVIN: SLR 8000 - VHFB
 US: ABZNINANPMLN6730
 IC: 109AB-PMLN6730

MAC 1:  685E1CA4A5A8
 MAC 2:  685E1CA4A5A9

LISTED
I.T.E.
E300595



100-240V ~ Max 10A 50/60 Hz
 11.0-15.5V == 27A Max OR 32.0V == 23A Max

Mfr. Date: 02/07/2023
 Made in Mexico