

Photographs of the Device

Photographs – Index

<u>EXHIBIT</u>	<u>DESCRIPTION</u>
C1-1	External Front View of Base Radio
C1-2	External Front View of Base Radio, Top Cover and Front Panel Removed
C1-3	External Back View of Base Radio
C1-4	FCC / IC Identification Label

Photographs of the Device

External Front View of Base Radio



Photographs of the Device

External Front View of Base Radio, Top Cover and Front Panel Removed




Photographs of the Device


External Back View of Base Radio



Photographs of the Device

FCC / IC Identification Label



SN: 



MOTOROLA SLR 8000

This device complies with Part 15 of the FCC rules. operation is subject to the condition that this device does not cause harmful interference

Serial No: 433IYY0565
 Model No: T8319A
 S/Tanapa: PMUD3360A
 FCC ID: ABZ99FT3095B
 IC: 109AB-99FT3095B
 HVIN: SLR 8000 - VHFB
 US: ABZNINANPMLN6730
 IC: 109AB-PMLN6730

MAC 1:  685E1CA4A5A8
 MAC 2:  685E1CA4A5A9

100-240V ~ Max 10A 50/60 Hz
 11.0-15.5V == 27A Max OR 32.0V == 23A Max

Mfr. Date: 02/07/2023
 Made in Mexico

